



16-2655.00

Photo 17: Level 2 Underside – View of precast filigree floor panel with significant loss of section and exposed and corroded prestress strands and triangulated trusses



Photo 18: Level 2 Underside – View showing severe corrosion damage and sectional loss of precast filigree panel. Also note severe corrosion & complete loss of floor drain





16-2655.00

Photo 27: Level 3 – View of typical cracking and delamination at the column base



Photo 28: View of supplemental added floor drains and lines non-functional and in disrepair

