





# FACILITY CONDITION ASSESSMENT AND ENERGY AUDIT

#### STATE OF VERMONT

2 Governor Aiken Avenue Montpelier, Vermont 05633-5801



FACILITY CONDITION ASSESSMENT OF

#### VERMONT VETERANS' HOME

325 North Street Bennington, Vermont 05201

#### **PREPARED BY:**

#### **EMG**

222 Schilling Circle, Suite 275 Hunt Valley, Maryland 21031 800.733.0660 410.785.6220 (fax) www.emgcorp.com

#### **EMG CONTACT:**

Marge Mitnick Program Manager 800.733.0660 x6230 mmitnick@emgcorp.com

**EMG Project #:** 106686.13R-001.305 **Date of Report:** November 18, 2013 **On-Site Date:** October 14-16, 2013



# TABLE OF CONTENTS

1.	Execu	tive Summary	1
	1.1	Purpose and Scope	1
	1.1.1	Probable Capital Needs - Immediate Repairs	2
	1.1.2	Probable Capital Needs - Capital Reserves	2
	1.1.3	Remaining Useful Life Estimate	3
	1.1.4	Opinions Of Probable Cost	3
	1.1.5	Priority Ranking	3
	1.1.6	Energy Audit	
	1.2	Summary of Findings	
	1.3	Facility Condition Index	
	1.4	Immediate and Capital Needs Sorted By Priority	
	1.5	Immediate and Capital Needs Sorted By Category	
	1.6	Distribution of Immediate Needs by Building System	
	1.7	Distribution of Capital Needs by Building System	
	1.8	Energy Results	
	1.9	Project Narrative	
В	Shell	Systems	13
	B20	EXTERIOR ENCLOSURE	14
	B30	Roofing	22
C	Interi	iors Systems	29
	C10	INTERIOR CONSTRUCTION	29
	C30	INTERIOR FINISHES	31
D	Servi	ces Systems	33
	D10	CONVEYING SYSTEMS	33
	D20	PLUMBING	34
	D30	HVAC	
	D40	FIRE PROTECTION Systems	39
	D50	ELECTRICAL SYSTEMS	
E	Equip	ment & Furnishing Systems	47
	E10	EQUIPMENT	47
G	Build	ling Sitework Systems	61
	G20	SITE IMPROVEMENTS	
	G30	SITE CIVIL/Mechanical Utilities	68
	G40	SITE ELECTRICAL Utilities	
2.	Acces	sibility Issues	71
3.		y Audit	
-	1.1.	Energy Conservation Measures	
	1.2.	Recommended Operations and Maintenance Plan	
4.		ral Assessment Information	
5.		ication	
		ndices	

## 1. EXECUTIVE SUMMARY

#### 1.1 PURPOSE AND SCOPE

The evaluation team visited Vermont Veterans' Home to evaluate the general condition of the building(s) and site improvements, reviewed available construction documents in order to familiarize themselves with the physical conditions, setting and be able to comment on the in-place construction systems, life safety, mechanical, electrical and plumbing systems, and the general built environment. The evaluation team conducted a walk-through survey of the building(s) in order to observe building systems and components, identify physical deficiencies and formulate recommendations to remedy the physical deficiencies.

- As a part of the walk-through survey, the evaluation team surveyed 100% of the facility's interior. In addition, EMG surveyed the exterior of the properties including the building exterior, roofs, and sidewalk/pavement.
- The evaluation team interviewed the building maintenance staff to inquire about the subject property's historical repairs and replacements and their costs, level of preventive maintenance exercised, pending repairs and improvements, and frequency of repairs and replacements.
- The evaluation team developed opinions based on their site evaluation, interviews with relevant maintenance contractors, municipal authorities, and experience gained on similar properties previously evaluated. The evaluation team questioned others who are knowledgeable of the subject property's physical condition and operation or knowledgeable of similar systems to gain comparative information to use in evaluation of the subject property.
- The evaluation team reviewed documents and information provided by BGS staff that could also aid the knowledge of the subject property's physical improvements, extent and type of use, and/or assist in identifying material discrepancies between reported information and observed conditions.

The Client contracted with EMG to conduct a Facility Condition Assessment (FCA) and Level 1 Energy Audit consisting of field observations, document review and related due diligence tasks of the subject property.

#### **Project Description**

Item	Description
Project Name	Vermont Veterans' Home
Building ID	VVH
Property Type	Skilled Nursing Facility
Year Built	1887
Phase 2 Year of Construction	1967
Phase 3 Year of Construction	1985
Number of Stories	2
Occupied	Yes
Land Area (acres)	83

106686.13R-001.305

Item	Description
Gross Building Area (SF)	140,000

The goal of the FCA is to gather the data necessary to understand the existing facilities condition, identify strategies to meet the facilities life cycle needs and create the foundation for an overall capital plan. The facilities condition analysis includes the following:

- Current conditions analyses existing facility requirements including deferred maintenance, recommended discretionary improvements, and code noncompliance issues.
- Anticipated facility reserve analyses projections of ongoing degradation of facilities' components and costs associated with the reserve or replacement of these components as they reach the end of their useful lives
- Funding needs analysis summary report of deferred maintenance and systems reserves funding needs.

The physical condition of building systems and related components are typically defined as being in one of three conditions: Good, Fair, or Poor, or a combination thereof. For the purposes of this report, the following definitions are used:

- Good = Satisfactory as-is. Requires only routine maintenance over the evaluation period. Repair or replacement may be required due to a system's estimated useful life.
- Fair = Satisfactory as-is. Repair or replacement is required due to current physical condition and/or estimated remaining useful life.
- Poor = Immediate repair, replacement, or significant maintenance is required.

EMG's calculation of probable capital needs methodology involves identification and quantification of those systems or components requiring immediate actions or capital funding reserves over the lifecycle horizon of the facility key components. The component is segregated into two categories "Immediate Repairs" and "Capital Reserve" defined as follows:

#### 1.1.1 Probable Capital Needs - Immediate Repairs

Immediate repairs are opinions of probable costs that require immediate action as a result of: (1) material existing or potential unsafe conditions, (2) material building or fire code violations, or (3) conditions that, if left un-remedied, have the potential to result in or contribute to critical element or system failure within one year or will most probably result in a significant escalation of its remedial cost. Immediate repair costs are items which require action in year one of the capital expenditure horizons.

#### 1.1.2 Probable Capital Needs - Capital Reserves

Capital Reserves are for recurring probable expenditures that are not classified as operation or maintenance expenses. The modified capital reserves should be budgeted for in advance on an annual basis. Capital reserves are reasonably predictable both in terms of frequency and cost. However, capital reserves may also include components or systems that have an indeterminable life but nonetheless have a potential liability for failure within an estimated time period.

106686.13R-001.305

#### 1.1.3 Remaining Useful Life Estimate

Based upon site observations, research, and judgment, along with referencing Expected Useful Life (EUL) tables from various industry sources, EMG opines as to when a system or component will most probably necessitate replacement. Exposure to the elements, initial quality and installation, extent of use, the quality and amount of preventive maintenance exercised, etc., are all factors that impact the effective age of a system or component. As a result, a system or component may have an effective age that is greater or less than its actual chronological age. The Remaining Useful Life (RUL) of a component or system equals the EUL less its effective age.

#### 1.1.4 Opinions Of Probable Cost

Estimates for individual repair and replacements are a key part of this engagement. These estimates are based on invoice or bid documents provided by the Owner/facility or construction cost estimates developed by construction resources such as R.S. Means, EMG's experience with past costs for similar properties, city cost indexes, and assumptions regarding future economic conditions. Where quantities could not be derived from an actual take-off, lump sum costs or allowances are utilized.

Opinions of probable costs should only be construed as preliminary, order of magnitude budgets. Actual costs most probably will vary from the consultant's opinions of probable costs depending on such matters as type and design of suggested remedy, quality of materials and installation, manufacturer and type of equipment or system selected, field conditions, whether a physical deficiency is repaired or replaced in whole, phasing of the work (if applicable), quality of contractor, market conditions, and whether competitive pricing is solicited, etc. ASTM E2018-08 recognizes that certain opinions of probable costs cannot be developed within the scope of this guide without further study. Opinions of probable cost for further study should be included in the PCR.

#### 1.1.5 Priority Ranking

EMG recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities of recommended repairs and/or replacements. During the assessment the collected data is entered directly into the EMG assessment and capital planning database using tablet computers. Based on the analysis of the collected data a Priority Ranking is calculated for each item observed. The Priority Ranking calculation is a function of four key facility variables to include:

- 1. <u>Building Mission Ranking</u> if the building is one of multiple building at the facility, each building is ranked on a scale of 1-10 based on conversations with the client. This rank helps defines the importance of each building to the overall mission of the facility. For example the building containing the administrative and executive offices for the subject property may carry a higher ranked importance than the building that the landscaping and lawn equipment is stored in at the facility. Both are required for the operation of the facility but the office / admin building has a higher importance to the mission than the landscaping / lawn equipment building. However, if the facility is a golf course that relies heavily of landscaping and lawn equipment this importance ranking may change significantly.
- 2. <u>Remaining Useful Life Ranking</u> the estimated useful life (EUL) projection of the component is calibrated against the remaining useful life (RUL) as estimated by EMG field assessor. This ratio is then utilized as a factor in the priority ranking.
- 3. <u>Asset Component Category</u> each asset or component evaluated is assigned a unique Uniformat code. The Uniformat designation is then associated with a ranking based on the overall importance to the



operation of the facility. A asset that is a related to building envelope e.g. roof, window, exterior siding, is assigned a higher ranking than a component such a flooring, carpeting or other athletic type feature.

4. <u>Functional Asset Categories</u> – the cost associated with each asset or component evaluated is assigned to a category to include; Code Compliance, Facility Operations, Environmental Factors, Facility Functionality and Integrity of the Facility.

Based on the results of the ranking calculation derived from the analysis of the variables described above, the assets and component is assigned to one of the following Priority Ranking categories. The scale is 1-5 with 1=highest and 5=lowest priority. EMG will use seasoned judgment and the following guidance when determining priority:

- <u>Priority One</u> = Critical Requires immediate attention to correct a cited safety and/or code hazard, stop accelerated deterioration, or return equipment or systems to operation. Priority One items are to be addressed on an immediate or short term time horizon.
- <u>Priority Two</u> = Indirect Impact on Facility Mission conditions that, if not corrected expeditiously, will become critical within one year items are to be addressed for replacement, maintenance or repair on a near term horizon.
- Priority Three = Necessary conditions that require appropriate action to prevent deterioration if deferred further. Items are to be addressed by a planned routine maintenance or be part of a documented preventive maintenance program in an effort to meet or extend the expected useful estimate. Items in this category, if not maintained, will reach end of useful life on an accelerated basis. Replace items that will reach or exceed their useful service life.
- <u>Priority Four</u> = Recommended conditions that include items that represent a sensible improvement. Items in this category include conditions requiring appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further.
- Priority Five = Enhancements The items are aesthetic in nature. Typical enhancement items include repainting, improved signage, re-carpeting or other items that provide enhanced facility environs. These items could also include condition that meets current industry standards or do not conform to existing standards, but do not require action until substantial work is undertaken, which would then require corrective action. Priority Five items that represent code violations as a result of revised and changing codes.

#### 1.1.6 Energy Audit

The purpose of this Energy Audit is to provide a baseline of energy usage, the relative energy efficiency of the facility, and specific recommendations for Energy Conservation Measures. Information obtained from these analyses may be used to support a future application to an Energy Conservation Program, Federal and Utility grants towards energy conservation, as well as support performance contracting, justify a municipal bond-funded improvement program, or as a basis for replacement of equipment or systems

The energy audit consisted of an onsite visual assessment to determine current conditions, itemize the energy consuming equipment (i.e. boilers, make-up air units, DHW equipment); review lighting systems both exterior and interior; and review efficiency of all such equipment. The study also included interviews and consultation with operational and maintenance personnel. The following is a summary of the tasks and reporting that make up the Energy Audit portion of the report.

The following is a summary of the tasks and reporting that make up the Energy Audit portion of the report.

#### **ENERGY AND WATER USING EQUIPMENT**

• EMG has surveyed the common areas, tenant areas, maintenance facilities and mechanical rooms to document utility-related equipment, including heating systems, cooling systems, air handling systems and lighting systems.



#### **BUILDING ENVELOPE**

• EMG has reviewed the characteristics and conditions of the building envelope, checking insulation values and conditions. This review also includes an inspection of the condition of walls, windows, doors, roof areas, insulation and special use areas.

#### **RECOMMENDATIONS FOR ENERGY SAVINGS OPPORTUNITIES**

 Based on the information gathered during the onsite assessment, the utility rates, as well as recent consumption data and engineering analysis, EMG has identified opportunities to save energy and provide probable construction costs, projected energy/utility savings and provide a simple payback analysis.

#### **ANALYSIS OF ENERGY CONSUMPTION**

- Based on the information gathered during the onsite assessment and a minimum of one year of utility billing history, EMG has conducted an analysis of the energy usage of all equipment, and identified which equipment is using the most energy and what equipment upgrades may be necessary. As a result, equipment upgrades or replacements are identified that may provide a reasonable return on the investment and improve maintenance reliability.
- Energy Audit Process
- Interviewing staff and review plans and past upgrades
- Performing an energy audit for each use type
- Performing a preliminary evaluation of the utility system
- Analyzing findings, utilizing ECM cost-benefit worksheets
- Making preliminary recommendations for system energy improvements and measures
- Estimating initial cost and changes in operating and maintenance costs based on implementation of energy efficiency measures
- Ranking recommended cost measures, based on the criticality of the project and the largest payback.

All the Energy Conservation Measures (ECMs) are broken into two major categories:

- 1. **No/Low Cost Recommendations**: No/Low cost is defined as any project with initial investment of less than \$1000.
- 2. **Capital Cost Recommendations**: Capital cost defined as any project with initial investment greater than or equal to \$1000.

EMG screens ECMs based on the payback criteria.

<u>Simple Payback Period</u> –The number of years required for the cumulative value of energy or water cost savings less future non-fuel or non-water costs to equal the investment costs of the building energy or water system, without consideration of discount rates. ECMs with a payback period greater than the Expected Useful Life (EUL) of the project are not typically recommended, as the cost of the project will not be recovered during the lifespan of the equipment. These ECMs are recommended for implementation during future system replacement. At that time, replacement may be evaluated based on the premium cost of installing energy efficient equipment.

 $Simple\ Payback = \frac{Initial\ Cost}{Annual\ Savings}$ 

#### 1.2 SUMMARY OF FINDINGS

This report represents summary-level findings for the Facility Condition Assessment. The deficiencies identified in this assessment can be combined with potential new construction requirements to develop an overall Long Term Capital Needs Plan that can be the basis for a facility wide capital improvement funding strategy. Key findings from the assessment include:

Key Finding	Metric
Facility Condition Index	0.92 %
Current Replacement Value	\$56,000,000
Immediate Capital Needs	\$515,185
1-5 Year Capital Needs	\$659,389
6-10 Year Capital Needs	\$599,391

#### 1.3 FACILITY CONDITION INDEX

The Facility Condition Index (FCI) gives an indication of a building's or portfolio's overall state of condition. The values are based on a 0-100% + scale and are derived by dividing the repair costs for a facility by a theoretical replacement value. This replacement value is calculated by multiplying the existing building square footage of a given facility by the Cost per Square Foot to construct a new, similar facility. Typically, the FCI is calculated using only the current condition values, not taking into account the future need identified in the life cycle evaluation. Accounting principles indicate that a value of 65%, or the "rule of two-thirds", be utilized for the FCI threshold for identifying potential replacement candidates. Once the current repair costs reach 65%, or roughly two-thirds of the full replacement value of the estimated cost to replace a facility, it may not be prudent to continue to fund repairs. In cases where aggressive facilities planning is expected to be necessary, this threshold may be adjusted to address more pressing need.




Vermont Veterans' Home, FCI: 0.92%

#### 1.4 IMMEDIATE AND CAPITAL NEEDS SORTED BY PRIORITY

Just because a building system or component has an immediate or capital requirement does not necessarily mean that item is a high priority when compared to the needs of another component. The needs have been prioritized according to five priority levels, with Priority 1 items being the most critical to address:

#### Immediate and Capital Needs by System and Priority






	Priority					
Building System	1	2	3	4	5	Total
B Shell	\$	\$	\$333,387	\$561,101	\$	\$894,488
C Interiors	\$	\$	\$	\$251,950	\$	\$251,950
D Services	\$	\$	\$713,144	\$314,329	\$	\$1,027,474
E Equipment & Furnishing	\$	\$	\$85,939	\$274,333	\$	\$360,272
G Building Sitework	\$	\$	\$144,472	\$301,016	\$	\$445,488
Totals	\$	\$	\$1,276,942	\$1,702,729	\$	\$2,979,671

Priority

#### 1.5 IMMEDIATE AND CAPITAL NEEDS SORTED BY CATEGORY

The deficiencies are sorted by categories which define briefly the reason the need exists. A requirement may have more than one applicable category. The category is selected based on the need priority, the most heavily impacted building system and the category with the greatest life safety significance.

#### Immediate and Capital Needs by Category



Building System	Total Cost
OP - Maintenance	\$526,543
IN - Beyond Rated Life	\$1,895,656
OP - Security	\$41,640
FN - Modernization	\$140,300
IN - Appearance	\$121,950
IN - Reliability	\$253,583
Total	\$2,979,671

The following is a list of the categories with a brief description:

#### **Code Compliance**

- Accessibility: Conditions that violate the American Disabilities Act guidelines
- Building Code: Conditions that violate Building codes
- Life Safety: Conditions that violate NFPA 101 Life Safety Code

#### **Operations**

- Energy: Conditions that adversely affect energy use
- Maintenance: Components or systems that require routine maintenance
- Security: Conditions that compromise the protection of the asset or its occupants

#### **Environmental**

- Air/ Water Quality: Conditions that affect air or water quality
- Asbestos: Visible observance of suspected asbestos-containing material(ACM)
- Lead Visible Observance of suspected lead based paint
- PCB: Observance of suspected PCB containing equipment

#### **Functionality**


- Mission: Components which do not meet the mission of the organization
- Modernization: Conditions that need to made modern in appearance or function
- Plant Adaptation: Components or systems that must change to fit a new or adapted use
- Obsolescence: Components or systems that are or are becoming obsolete
- Capacity: Components or system which cannot meet demand load

#### Integrity

- Appearance: Problems with the asset's appearance that are not functional in nature
- Reliability: Components or systems which cannot be depended on
- Beyond Rated Life: A component or system that has exceeded its rated life

#### 1.6 DISTRIBUTION OF IMMEDIATE NEEDS BY BUILDING SYSTEM


## Distribution of Immediate Needs by Building System



Building System	<b>Estimated Cost</b>	Percentage of Total Cost
Erosion Control Measures	\$34,475	6.7%
Exterior Wall Construction	\$952	0.2%
Fixtures & Transformers	\$39,250	7.6%
Food Service Equipment	\$12,500	2.4%
Local Area Networks	\$217,600	42.2%
Medical Equipment	\$5,000	1.0%
Other Controls & Instrumentation	\$1,500	0.3%
Roof Finishes	\$178,523	34.7%
Site Furnishings	\$2,400	0.5%
Windows	\$22,986	4.5%
Total	<b>\$515,185</b>	100%

#### 1.7 DISTRIBUTION OF CAPITAL NEEDS BY BUILDING SYSTEM

#### Distribution of Capital Needs by Building System



Building System	<b>Estimated Cost</b>	Percentage of Total Cost
B Shell	\$692,028	28.1%
C Interiors	\$251,950	10.2%
D Services	\$808,374	32.8%
E Equipment & Furnishing	\$342,772	13.9%
G Building Sitework	\$369,363	15.0%
Total	\$2,464,486	100%

#### 1.8 **ENERGY RESULTS**

EMG has conducted an Energy Audit on the Vermont Veterans' Home. The study included a review of the building's construction features, historical energy and water consumption and costs, review of the building envelope, HVAC equipment, heat distribution systems, lighting, and the building's operational and maintenance practices.



EMG has identified five Energy Conservation Measures (ECMs) for this property. The savings for each measure are calculated using standard engineering methods followed in the industry, and detailed calculations for ECM are provided in Appendix F for reference. A 10% discount in energy savings was applied to account for the interactive effects amongst the ECMs. In addition to the consideration of the interactive effects, EMG has applied a 15% contingency to the implementation costs to account for potential cost overruns during the implementation of the ECMs.

#### Summary of Financial Information for Recommended Energy Conservation Measures

Item	Estimate
Total Projected Initial ECM Investment	\$ 320,274 (In Current Dollars)
Estimated Annual Cost Savings Related to ECMs	\$91,121 (In Current Dollars)
Net Effective ECM Payback	3.51 years
Estimated Annual Energy Savings	7.66%
Estimated Annual Cost Savings (excluding water)	8.13%

#### 1.9 **PROJECT NARRATIVE**

Significant capital construction began in the 1960's including renovation of the administration building, six residential wings, kitchen and dining room, new nursing care units, a chapel, social hall. The facility resides in low lying land with creeks and natural springs adjacent to a river. Land is ideal for farming, but has been challenging for the expansion basements and crawlspaces which have been generally damp and subject to flooding.

Reportedly, by 2004 the facility was showing effects of aging and deferred maintenance. Beginning in 2005, with significant capital funding, several phases of remediation and renovations occurred.

- Most basements and crawlspaces have been remediated for mold and asbestos, and water sealed.
- The central mechanical system is in the process of transitioning from a steam-fired hot water system to a facility-wide geothermal system for heating and cooling. The upgrade is approximately 80% complete; two of the existing boilers will remain for domestic hot water.
- Four residential wings have been renovated.
- Lighting systems, electronic controls, information systems, and sprinkler system have been updated.

Most residential wings have been fully renovated or extensively repaired in recent years with the exception of E Wing which is scheduled for renovation in the final phase of mold remediation and geothermal updates. The remaining geothermal upgrades are included in the current capital improvement plan. The commercial kitchen has had partial updates in the service line. Additional kitchen updates are required. Some lighting efficiency upgrades are required.

Landscape grades along many building perimeters have settled causing surface drainage towards foundation walls and basements. Soil replenishment and grading is required.

# A SUBSTRUCTURE SYSTEMS

## A10 FOUNDATIONS

Item	Description
A1011 Wall Foundations	Reinforced Concrete, Wall and Footings - 4FT Crawl Spaces
Condition	Good
Qty / UOM	31000 / SF
RUL (years)	33
Location	Crawl Spaces below Resident Wings

Item	Description	
A1011 Wall Foundations	Reinforced Concrete, Walls and Footings, Full Basement	
Condition	Good	
Qty / UOM	30000 / SF	
RUL (years)	33	
Location	Common Area Basements below Main Lobby, A, B, & C Wings	

Item	Description	
A1031 Standard Slab on Grade	Reinforced Concrete, Slab on Grade	
Condition	Good	
Qty / UOM	44000 / SF	
RUL (years)	22	
Location	Resident Wings	

## B SHELL SYSTEMS

## **B10** SUPERSTRUCTURE

Item	Description
B1012 Upper Floors Construction	Concrete over Crawls and Upper Floor Construction
Condition	Good
Qty / UOM	14000 / SF
RUL (years)	33
Location	Second Floor Center

Item	Description
B1021 Flat Roof Construction	Open-Web Steel Joists Supporting Corrugated Metal Roof Deck with Lightweight Concrete Topping
Condition	Good
Qty / UOM	94000 / SF
RUL (years)	25
Location	Resident Wings

Item	Description
B1022 Pitched Roof Construction	Traditional Wood Beams and Rafters
Condition	Fair - Good
Qty / UOM	2500 / SF
RUL (years)	35
Location	Original Home

#### **B20** EXTERIOR ENCLOSURE

Item	Description
<b>B2011 Exterior Wall Construction</b>	Brick Chimney

106686.13R-001.305

Item	Description
Condition	Poor
Qty / UOM	1 / LS
RUL (years)	20
Location	Boiler Building
Exterior Wall Construction	Brick Masonry Veneer

#### **Observations/Comments:**

The brick chimney is no longer required for the current oil combustion equipment. Significant brick repair pointing is required, particularly near the top.

#### **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
B2011	Repair Brick Chimney	1.0 - EA	25000.0	OP - Maintenance	Priority 4	2014	25,000
B2011	Repair Brick Chimney	1.0 - EA	25000.0	OP - Maintenance	Priority 4	2024	25,000

Item	Description
B2011 Exterior Wall Construction	Caulk sealant at joints and openings
Condition	Fair - Good
Qty / UOM	3000 / LF
RUL (years)	6
Location	All exterior walls

#### **Observations/Comments:**

Caulking is reasonably well maintained. Seasonal inspection and routine caulk repair is required.



106686.13R-001.305

#### **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
B2011	Replace Caulk sealant at joints and openings	3,000.0 - LF	3.8	OP - Maintenance	Priority 4	2019	11,520

Item	Description
B2011 Exterior Wall Construction	Vertical wood siding
Condition	Poor - Fair
Qty / UOM	675 / SF
RUL (years)	11
Location	In-Service & Social Hall

#### **Observations/Comments:**

The original finish on the natural wood siding is weathered. Thorough surface preparation and application of durable stain and sealer is recommended.

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	General Painting Cost Per SF,	675.0		OD	D : ''		
B2011	Minor Prep Work, Up to 4- Story Bldg.	675.0 - SF	1.4	OP - Maintenance	Priority 4	2013	952
	, ,						
	General Painting Cost Per SF,						
	Minor Prep Work, Up to 4-	675.0 -		OP -	Priority		
B2011	Story Bldg.	SF	1.4	Maintenance	4	2023	952

106686.13R-001.305

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
B2011	Replace Vertical Wood Siding	675.0 - SF	12.7	IN - Beyond Rated Life	Priority 4	2024	8,559

Item	Description
B2011 Exterior Wall Construction	EIFS with Stucco Over Cement Board
Condition	Good
Qty / UOM	44 / CSF
RUL (years)	27
Location	North Village Wing

#### **Observations/Comments:**

EIFS is on good condition. Maintenance is anticipated.

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Repair 10% of Asset: EIFS with	5.0 -		OP -	Priority		
B2011	Stucco Over Cement Board	CSF	476.0	Maintenance	4	2016	2,380
	Repair 10% of Asset: EIFS with	5.0 -		OP -	Priority		
B2011	Stucco Over Cement Board	CSF	476.0	Maintenance	4	2024	2,380
	Repair 10% of Asset: EIFS with	5.0 -		OP -	Priority		
B2011	Stucco Over Cement Board	CSF	476.0	Maintenance	4	2032	2,380

106686.13R-001.305

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
B2011	Color Coat 100% of Asset: EIFS	44.0 - CSF	218.0	OP - Maintenance	Priority 4	2032	9,592

Item	Description
B2011 Exterior Wall Construction	Wood Lap Siding and Trim
Condition	Fair - Good
Qty / UOM	5200 / SF
RUL (years)	23
Location	Origional Bldg and Maintenance Garage
Exterior Wall Construction	Solid Wood Lap Siding

## **Observations/Comments:**

Historic wood structures will require painting.

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Paint Existing Wood Siding and trim, One Coat, Spray with	5,200.0		OP -	Priority		
B2011	Medium Prep and Clean Up	- SF	1.2	Maintenance	4	2015	6,396
	Paint Existing Wood Siding and						
	trim, One Coat, Spray with	5,200.0		OP -	Priority		
B2011	Medium Prep and Clean Up	- SF	1.2	Maintenance	4	2025	6,396

Item	Description
<b>B2011 Exterior Wall Construction</b>	Brick Exteriors

Item	Description
Condition	Fair - Good
Qty / UOM	9800 / CSF
RUL (years)	24
Location	Most exterior walls
Exterior Wall Construction	Brick Masonry Veneer

## **Observations/Comments:**

Pointing will be required throughout the assessment period.

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Daint Brial Francis NA/alla	20.0		OD	Dui - uit		
B2011	Point Brick Exterior Walls where required	20.0 - CSF	948.0	OP - Maintenance	Priority 4	2018	18,960
	Point Brick Exterior Walls	20.0 -		OP -	Priority		
B2011	where required	CSF	948.0	Maintenance	4	2028	18,960

Item	Description
B2021 Windows	Corridor Windows
Condition	Poor - Fair
Qty / UOM	18 / EA
RUL (years)	0
Location	Corridor at Dining and Chapel
Window Type	Fixed
Windows Material	Aluminum
Windows Glazing	Single Glazed
Window Operation	Fixed

106686.13R-001.305

#### **Observations/Comments:**

Windows along the EW corridors at Chapel and Dining are single glazed and represent a significant heating and cooling load.

#### **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
B2021	Replace Corridor Windows	18.0 - EA	1277.0	IN - Beyond Rated Life	Priority 3	2013	22,986

Item	Description
B2021 Windows	Casement Windows
Condition	Poor - Fair
Qty / UOM	64 / EA
RUL (years)	2
Location	Administration and D wing
Window Type	Casement
Windows Material	Aluminum
Windows Glazing	Double Glazed
Window Operation	Manual

#### **Observations/Comments:**

Operable casement windows are aging and have failed hardware and leaking insulated glass seals.

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Casement	64.0 -		IN - Beyond Rated	Priority		
B2021	Windows	EA	911.0	Life	3	2015	58,304



Item	Description
B2032 Solid Exterior Doors	Exterior Steel Doors
Condition	Fair - Good
Qty / UOM	32 / EA
RUL (years)	32
Location	All entrances
Door Hardware	Knob
Door Operation	Manual
Core Type	Solid Core
Door Frame	Metal Framed

#### **Observations/Comments:**

Exterior doors in some areas receive high usage and wear. Ongoing replacements are required.

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Repair 8% of Asset: Steel,	4.0 -		IN -	Priority		
B2032	Insulated Core, Ptd. Door	EA	1098.0	Reliability	3	2014	4,392
B2032	Repair 8% of Asset: Steel, Insulated Core, Ptd. Door	4.0 - EA	1098.0	IN - Reliability	Priority 3	2018	4,392
	Repair 8% of Asset: Steel,	4.0 -		IN -	Priority		
B2032	Insulated Core, Ptd. Door	EA	1098.0	Reliability	3	2022	4,392

# FACILITY CONDITION ASSESSMENT

AND ENERGY AUDIT

106686.13R-001.305

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Repair 8% of Asset: Steel,	4.0 -		IN -	Priority		
B2032	Insulated Core, Ptd. Door	EA	1098.0	Reliability	3	2026	4,392
	Repair 8% of Asset: Steel,	4.0 -		IN -	Priority		
B2032	Insulated Core, Ptd. Door	EA	1098.0	Reliability	3	2030	4,392

#### **Cost Summary:**

Year	Total Expenditures
2013	\$23,938
2014	\$29,392
2015	\$64,700
2016	\$2,380
2018	\$23,352
2019	\$11,520
2022	\$4,392
2023	\$952
2024	\$35,939
2025	\$6,396
2026	\$4,392
Year	Total Expenditures
2028	\$18,960
2030	\$4,392
2032	\$11,972

## B30 Roofing

Item	Description
B3011 Roof Finishes	Asphalt Shingles Original House

106686.13R-001.305

Item	Description
Condition	Poor - Fair
Qty / UOM	120 / SQ
RUL (years)	3
Location	House, Boiler and Maintenance Buildings

#### **Observations/Comments:**

Shingle roofs are nearing replacement in the oldest buildings. Roofs were reported to have been replaced in 1989.

#### **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
B3011	Replace Asphalt Shingles Original House	120.0 - SQ	430.0	IN - Reliability	Priority 3	2016	51,600

Item	Description
B3011 Roof Finishes	Wood Roof Shingles
Condition	Fair - Good
Qty / UOM	25 / SQ
RUL (years)	15
Location	In-Service Social Building
Traffic Toppings and Paving	Wood shingles
Flashings and Trim	Metal
Roof Warranty	Unknown

#### **Observations/Comments:**

The existing wood shingle roof will require repair over time. When replaced, premimum architectural shingles are recommended.



106686.13R-001.305

#### **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Wood Roof	25.0 -		IN - Beyond Rated	Priority		
B3011	Shingles	SQ	817.0	Life	4	2028	20,425

Item	Description
B3011 Roof Finishes	TPO Roofs on B. C and D Wings
Condition	Good
Qty / UOM	250 / SQ
RUL (years)	19
Location	B, C, & D Wings

#### **Observations/Comments:**

From 2008 to 2012, many roof finishes have been replaced with adheared TPO over tapered insulation. Roofs were replaced in Wings A, B, C and D.

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace TPO Roofs on B. C	250.0 -		IN - Beyond	Priority		
B3011	and D Wings	SQ	714.1	Rated Life	4	2032	178,523

Item	Description
B3011 Roof Finishes	TPO Roof North Wings
Condition	Good
Qty / UOM	300 / SQ
RUL (years)	18

106686.13R-001.305

Item	Description
Location	

#### **Observations/Comments:**

From 2008 to 2012, many roof finishes have been replaced with adheared TPO over upgraded tapered insulation. Roof were replaced in Wings A, B, C and D. Replacements are anticipated at the end of the assessment period.

#### **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
B3011	Replace TPO Roof North Wings	300.0 - SQ	714.1	IN - Beyond Rated Life	Priority 4	2031	214,227

Item	Description
B3011 Roof Finishes	TPO Roof on Entrance, Dining and East Wing
Condition	Poor
Qty / UOM	250 / SQ
RUL (years)	0
Location	Entrance, Dining and East Wing

#### **Observations/Comments:**

Remaininging flat roofs require insulation upgrades and replacement with TPO roofing.

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace TPO Roof on Entrance,	250.0 -		IN -	Priority		
B3011	Dining and East Wing	SQ	714.1	Reliability	3	2013	1 <i>7</i> 8,523

Item	Description
B3011 Roof Finishes	TPO Roof on A Wing and D Dayroom



106686.13R-001.305

Item	Description
Condition	Good
Qty / UOM	300 / SQ
RUL (years)	18
Location	

#### **Observations/Comments:**

From 2008 to 2012, many roof finishes have been replaced with adheared TPO over upgraded tapered insulation. Roofs were replaced in Wings A, B, C and D.

#### **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
B3011	Replace TPO Roof on A Wing and D Dayroom	300.0 - SQ	1.0	IN - Beyond Rated Life	Priority 4	2031	300

Item	Description
B3021 Glazed Roof Openings	Plexi-Glass Skylights
Condition	Poor - Fair
Qty / UOM	15 / EA
RUL (years)	3
Location	Flat Roofs

#### **Observations/Comments:**

Remaining skylights have significant cracks and discoloration. Replacement before significant leaks develop is recommended.



106686.13R-001.305

#### **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
B3021	Replace Plexi-Glass Skylights	15.0 - EA	1.0	IN - Beyond Rated Life	Priority 3	2016	15

Item	Description
B3021 Glazed Roof Openings	Plexi-Glass Skylights
Condition	Good
Qty / UOM	25 / EA
RUL (years)	17
Location	Flat Roofs

## **Observations/Comments:**

Skylights should be replaced in conjunction with roof replacements.

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Plexi-Glass	25.0 -		IN - Beyond Rated	Priority		
B3021	Skylights	EA	328.0	Life	4	2030	8,200

# FACILITY CONDITION ASSESSMENT

AND ENERGY AUDIT

106686.13R-001.305

#### **Cost Summary:**

Year	Total Expenditures
2013	\$178,523
2016	\$51,615
2028	\$20,425
2030	\$8,200
2031	\$214,527
2032	\$178,523

# **INTERIORS SYSTEMS**

#### C10 INTERIOR CONSTRUCTION

Item	Description
C1021 Interior Doors	Automatic Accessible Door, Wood
Condition	Fair - Good
Qty / UOM	40 / EA
RUL (years)	27
Location	

#### **Observations/Comments:**

Interior doors in high traffic areas require ongoing repairs and replacements.

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Danain 201 of Accet Automotic						
	Repair 2% of Asset: Automatic Accessible Door, Wood with	2.0 -		OP -	Priority		
C1021	Glass Panels	EA	6500.0	Maintenance	4	2014	13,000
	Repair 2% of Asset: Automatic						
	Accessible Door, Wood with	2.0 -		OP -	Priority		
C1021	Glass Panels	EA	6500.0	Maintenance	4	2016	13,000
	Repair 2% of Asset: Automatic	2.0		0.0	D : :		
C1021	Accessible Door, Wood with	2.0 - E A	6500.0	OP -	Priority	2018	13 000
C1021	Glass Panels	EA	6500.0	Maintenance	4	2018	13,00

# FACILITY CONDITION ASSESSMENT

AND ENERGY AUDIT

#### 106686.13R-001.305

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
C1021	Repair 2% of Asset: Automatic Accessible Door, Wood with Glass Panels	2.0 - EA	6500.0	OP - Maintenance	Priority 4	2020	13,000
C1021	Repair 2% of Asset: Automatic Accessible Door, Wood with Glass Panels	2.0 - EA	6500.0	OP - Maintenance	Priority 4	2022	13,000
C1021	Repair 2% of Asset: Automatic Accessible Door, Wood with Glass Panels	2.0 - EA	6500.0	OP - Maintenance	Priority 4	2024	13,000
C1021	Repair 2% of Asset: Automatic Accessible Door, Wood with Glass Panels	2.0 - EA	6500.0	OP - Maintenance	Priority 4	2026	13,000
C1021	Repair 2% of Asset: Automatic Accessible Door, Wood with Glass Panels	2.0 - EA	6500.0	OP - Maintenance	Priority 4	2028	13,000
C1021	Repair 2% of Asset: Automatic Accessible Door, Wood with Glass Panels	2.0 - EA	6500.0	OP - Maintenance	Priority 4	2030	13,000

106686.13R-001.305

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Repair 2% of Asset: Automatic	2.0		O.D.	D : :		
	Accessible Door, Wood with	2.0 -		OP -	Priority		
C1021	Glass Panels	EA	6500.0	Maintenance	4	2032	13,000

#### **Cost Summary:**

Year	Total Expenditures
2014	\$13,000
2016	\$13,000
2018	\$13,000
2020	\$13,000
2022	\$13,000
2024	\$13,000
2026	\$13,000
2028	\$13,000
2030	\$13,000
2032	\$13,000

#### C30 **INTERIOR FINISHES**

Item	Description
C3024 Flooring	Vinyl Composition Floor Tiles
Condition	Fair - Good
Qty / UOM	9000 / SY
RUL (years)	5
Location	Throughout interiors

## **Observations/Comments:**

Floor tile receives high traffic and requires ongoing replacements.



106686.13R-001.305

## **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
C3024	Repair 5% of Asset: Floor tile replacements	450.0 - SY	67.8	IN - Appearance	Priority 4	2014	30,488
C3024	Repair 5% of Asset: Floor tile replacements	450.0 - SY	67.8	IN - Appearance	Priority 4	2019	30,488
23021	геріасеннена	3.	07.0	/ ippediance		2013	30,100
	Repair 5% of Asset: Floor tile	450.0 -		IN -	Priority		
C3024	replacements	SY	67.8	Appearance	4	2024	30,488
	Donois 50/ of Accet. Flantill	450.0		IN -	Dui ouite		
C3024	Repair 5% of Asset: Floor tile replacements	450.0 - SY	67.8	Appearance	Priority 4	2029	30,488

#### **Cost Summary:**

Year	Total Expenditures
2014	\$30,488
2019	\$30,488
2024	\$30,488
2029	\$30,488

#### SERVICES SYSTEMS D

#### D10 CONVEYING SYSTEMS

Item	Description
D1011 Passenger Elevators	Hydraulic Elevator, Large Cab
Condition	Good
Qty / UOM	1/EA
RUL (years)	28
Location	Central Lobby

Item	Description
D1011 Passenger Elevators	Hydraulic Elevator, Small Cab
Condition	Fair
Qty / UOM	1 / EA
RUL (years)	1
Location	B/C Wing

#### **Observations/Comments:**

Based on estimated remaining useful life (RUL® and condition, the elevator cab requires early replacement during the assessment period.

#### **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Hydraulic	1.0 -		IN - Beyond	Priority		
D1011	Elevator, Small Cab	EA	24940.2	Rated Life	3	2014	24,940

#### **Cost Summary:**

Year	Total Expenditures
2014	\$24,940



#### D20 PLUMBING

Item	Description
D2022 Hot Water Service	Laundry Hot Water Boiler, Steam-Fed
Condition	Good
Qty / UOM	200 / GALS
RUL (years)	24
Location	Basement Mechanical Room

#### **Observations/Comments:**

Steam supplied hot-water boiler supplying laundry room washers.

#### **Cost Summary:**

#### D30 HVAC

Energy Supply	
Item	Description
Fuel Oil Type	#2 Fuel Oil
Fuel Gas Type	LP Gas
Solid Fuel Type	N/A
District Heat Type	N/A
District Cooling Type	N/A
Solar Thermal	N/A
Fuel Tank Type	UST
Fuel Tank Size (gallons)	N/A
Fuel Tank Location	Several tanks (Jeff)
Gas Meter Location	N/A
Electrical Meter Location	Reported 5 meters on the site
Water Meter Location	N/A

Item	Description
D3021 Boilers	Oil-Fired Steam Boiler
Condition	Good



Item	Description
Qty / UOM	1 / EA
RUL (years)	26
Location	Boiler Room Addition

#### **Observations/Comments:**

The facility has three oil-fired steam boilers. The larger of the three, installed in 2004, is proposed to be removed once the geothermal project is complete and the heating load has been re-evaluated.

Item	Description
D3021 Boilers	Oil-Fired Steam Boiler, Domestic Water
Condition	Good
Qty / UOM	2/EA
RUL (years)	22
Location	Basement Mechanical Room

#### **Observations/Comments:**

The two oil-fired steam boilers installed in 2005 appear to be in good condition. After the completion of the geothermal system, these boilers are planned to remain in service for heating of domestic water.

Item	Description
D3022.1 Circulating Pumps	Geothermal System Circulation Pumps
Condition	Good
Qty / UOM	35 / EA
RUL (years)	9
Location	Basement/Crawl Spaces

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
D3022	Replace Geothermal System Circulation Pumps	35.0 - EA	6941.0	IN - Beyond Rated Life	Priority 4	2022	242,935

Item	Description
D3041.1 Air Handling Units	AHU #1
Condition	Good
Qty / UOM	1 / EA
RUL (years)	13
Location	North Wing

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
D3041	Replace AHU #1	1.0 - EA	6233.0	IN - Beyond Rated Life	Priority 4	2026	6,233

Item	Description
D3041.1 Air Handling Units	AHU #3
Condition	Good
Qty / UOM	1 / EA
RUL (years)	18
Location	A Wing

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
				IN - Beyond Rated	Priority		
D3041	Replace AHU #3	1.0 - EA	4780.0	Life	4	2031	4,780

Item	Description
D3041.1 Air Handling Units	AHU #2
Condition	Good
Qty / UOM	1 / EA
RUL (years)	13
Location	North Wing

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
D3041	Replace AHU #2	1.0 - EA	3204.0	IN - Beyond Rated Life	Priority 4	2026	3,204

Item	Description
D3051.1 Terminal Heat Pumps	Water/Air Heat Pump
Condition	Good
Qty / UOM	6/EA
RUL (years)	22
Location	B, C, & D Wings

Item	Description
D3051.1 Terminal Heat Pumps	Water/Water Heat Pump
Condition	Good
Qty / UOM	10 / EA
RUL (years)	23
Location	A and North Wings

Item	Description
D3051.1 Terminal Heat Pumps	Water/Air Heat Pump

Item	Description
Condition	Good
Qty / UOM	80 / EA
RUL (years)	23
Location	A and North Wings

Item	Description
D3051.1 Terminal Heat Pumps	Water/Water Heat Pump
Condition	Good
Qty / UOM	35 / EA
RUL (years)	22
Location	B, C, & D Wings

Item	Description
D3051.1 Terminal Heat Pumps	Heat Pump System
Condition	Good
Qty / UOM	5 / LS
RUL (years)	26
Location	East Wing

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Expand heat pump system						
	into East Wing to complete	1.0 -		FN -	Priority		
D3051	geothermal project	LS	140300.0	Modernization	3	2014	140,300

Item	Description
D3069 Other Controls & Instrumentation	Well Pump Controller
Condition	Fair - Good

106686.13R-001.305

Item	Description
Qty / UOM	1 / EA
RUL (years)	20
Location	Geothermal Wells

# **Observations/Comments:**

The well pump controller is in good condition. Issues have arisen, primarily during electrical storms, taking the controller out of service. Precautions are necessary to ensure continued operation.

#### **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Provide system grounding as required to eliminate electrical	1.0 -		IN -	Priority		
D3069	disruption.	EA	1500.0	Reliability	3	2013	1,500

#### **Cost Summary:**

Year	Total Expenditures
2013	\$1,500
2014	\$140,300
2022	\$242,935
2026	\$9,437
2031	\$4,780

# **D40** FIRE PROTECTION Systems

Fire and Life Safety System		
Item Description		
Fire Alarm System Components Present		
Smoke detectors	Yes	
Pull stations	Yes	
Audible alarms	Yes	
Strobe lights	Yes	



Fire and Life Safety System		
Item	Description	
Central fire alarm panel	Yes	
Annunciator panel	Yes	
Smoke Detectors Power Supply	Hardwired Electric	
Carbon Monoxide Detectors	Yes	
Heat Detector	N/A	
Central Fire Alarm Panel Location	Electrical Room	
Annunciator Panel Location	N/A	
Fire Extinguishers	Yes	
Fire Extinguisher Inspection Date	September 2, 2013	
Distance to Nearest Fire Hydrant (ft)	50	
Illuminated Exit Signs	Yes	
Kitchen Suppression Systems	Yes	
Halon Gas Systems	No	
Smoke Evacuation Systems	Yes	
Fire-rated Stairwells	No	
Fire-rated Stairwell Finish	N/A	
Stairwell Discharge	Exterior of the building at Grade	
Stairwell Pressurized	N/A	
Fire-Rated Doors Observed	Yes	
Location of Fire-Rated Doors	N/A	
Fire Alarm Service Company	N/A	
Date of Last Fire Alarm Service	December 14, 2012	
Are the individual office unit fire alarm systems monitored?	Yes	
Are the common area fire alarm systems monitored?	Yes	
Types of Common Areas Monitored	N/A	
Fire Alarm Monitoring Company	Alarm 7 Suppression, Inc. Glenville, NY	

Item	Description
D4011 Sprinkler Water Supply	Wet Pipe Sprinkler System
Condition	Good

106686.13R-001.305

Item	Description
Qty / UOM	140000 / SF
RUL (years)	32
Location	Throughout interiors

Item	Description
D4011 Sprinkler Water Supply	Air Compressor, Dry Pipe Sprinkler System
Condition	Fair
Qty / UOM	1 / EA
RUL (years)	18
Location	Basement/Crawl Spaces

# **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
D4011	Replace Air Compressor, Dry Pipe Sprinkler System	1.0 - EA	1679.1	IN - Beyond Rated Life	Priority 4	2031	1,679

# **Cost Summary:**

Year	Total Expenditures
2031	\$1,679

# D50 ELECTRICAL SYSTEMS

Item	Description		
D5012 Low Tension Service & Dist.	Switchgear, Mainframe, 3000 Amps		
Condition	Good		
Qty / UOM	1 / EA		
RUL (years)	27		



Item	Description
Location	

#### **Observations/Comments:**

New switchgear with 3000 Amp capacity was installed in 2010, backfeeding the 1600 Amp service equipment installed in 1975.

Item	Description
D5012 Low Tension Service & Dist.	Transformer, 1,080 kVA
Condition	Good
Qty / UOM	1 / EA
RUL (years)	37
Location	

# **Observations/Comments:**

New electric service installed approximately three years ago.

Item	Description
D5012 Low Tension Service & Dist.	Electrical Distribution
Condition	Good
Qty / UOM	1/EA
RUL (years)	37
Location	Each Wing

#### **Observations/Comments:**

Multiple circuit breaker panels installed in a common room in each resident wing for standard commercial power, emergency power, heat pumps, etc.

Item	Description
D5034 Call Systems	Call for Aid Posts in Staff Parking
Condition	Poor
Qty / UOM	5 / EA
RUL (years)	2
Location	Staff Parking

# **Observations/Comments:**

The open campus with staff entering and leaving around the clock has created circumstances where staff feels unsafe. Five locations along staff parking areas have been designated for installation of Security Call Stations. Cost includes trenching and connection to existing security monitoing system.

#### **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Call for Aid Posts	5.0 -		IN - Beyond	Priority		
D5034	in Staff Parking	EA	5500.0	Rated Life	3	2015	27,500
	Replace Call for Aid Posts	5.0 -		IN - Beyond	Priority		
D5034	in Staff Parking	EA	5500.0	Rated Life	3	2030	27,500

Item	Description
D5037 Fire Alarm Systems	Central Fire Alarm Control Panel
Condition	Good
Qty / UOM	1 / EA
RUL (years)	9
Location	Basement Mechanical Room

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Central Fire Alarm	1.0 -		IN - Beyond	Priority		
D5037	Control Panel	EA	12114.9	Rated Life	4	2022	12,115

Item	Description
D5039 Local Area Networks	Network distribution and control systems
Condition	Poor
Qty / UOM	170000 / SF
RUL (years)	0
Location	Patient Mgt Stations & Central Records

#### **Observations/Comments:**

Federal requirements for medical records integrated with caregiver decision making has made the IT systems in the building obsolete. The base network distribution system requires optical fiber upgrades to permit medical record management upgrades.

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Network						
	distribution and control	170,000.0 -		IN - Beyond	Priority		
D5039	systems	SF	1.3	Rated Life	3	2013	217,600
	Replace Network						
	distribution and control	170,000.0 -		IN - Beyond	Priority		
D5039	systems	SF	1.3	Rated Life	3	2028	217,600

Item	Description
D5092 Emergency Light & Power Systems	Diesel Generator, 40kW
Condition	Poor - Fair
Qty / UOM	1 / EA
RUL (years)	1
Location	Boiler House

# **Observations/Comments:**

The existing 40kW generator currently in service is reported to be more than 70 years old. This generator is planned to be removed and an existing 75kW generator available on site to be installed. The 75kW generator is approximately 25 years old and reported to be in good working condition.

#### **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Diesel	1.0 -		IN - Beyond	Priority		
D5092	Generator, 40kW	EA	56204.0	Rated Life	3	2014	56,204

Item	Description
D5092 Emergency Light & Power Systems	Diesel Generator Module, 250kW
Condition	Good
Qty / UOM	2/EA
RUL (years)	27
Location	Exterior Module

Item	Description
D5092 Emergency Light & Power Systems	Propane Generator Module, 100kW
Condition	Good
Qty / UOM	1/EA
RUL (years)	12
Location	Outside B Wing

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Propane Generator	1.0 -		IN - Beyond	Priority		
D5092	Module, 100kW	EA	43380.0	Rated Life	4	2025	43,380

Item	Description
D5092 Emergency Light & Power Systems	Diesel Generator, 75kW
Condition	Fair
Qty / UOM	1 / EA
RUL (years)	20
Location	A Wing

# **Observations/Comments:**

Diesel Generator, 75kW, currently spare and stored in the basement.

# **Cost Summary:**

Year	Total Expenditures
2013	\$217,600
2014	\$56,204
2015	\$27,500
2022	\$12,115
2025	\$43,380
2028	\$217,600
2030	\$27,500

#### **EQUIPMENT & FURNISHING SYSTEMS** Ε

#### E10 **EQUIPMENT**

Item	Description
E1016 Laundry & Dry Cleaning Equipment	Commercial Washers
Condition	Fair - Good
Qty / UOM	2/EA
RUL (years)	10
Location	Laundry Room

# **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Commercial			IN - Beyond Rated	Priority		
E1016	Washers	2.0 - EA	13312.0	, Life	4	2023	26,624

Item	Description
E1016 Laundry & Dry Cleaning Equipment	Commercial Washers
Condition	Good
Qty / UOM	2/EA
RUL (years)	14
Location	Laundry Room

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
					D: '		
	Replace Commercial			IN - Beyond Rated	Priority		
E1016	Washers	2.0 - EA	25295.0	Life	4	2027	50,590

Item	Description
E1028 Medical Equipment	Compressed oxygen control and manifold
Condition	Poor - Fair
Qty / UOM	1/EA
RUL (years)	0
Location	Rear of B Wing

#### **Observations/Comments:**

There are two oxygen storage and distribution rooms. One serving A wing and North Village uses current technology for economical liquid oxygen distribution. The oxygen room serving B Wing on the east rear end has older gas distribution with an aging control system. Conversion to liquid requires new controls and manifold as well as terminal fittings.

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Compressed oxygen	1.0 -		IN - Beyond	Priority		
E1028	control and manifold	EA	5000.0	Rated Life	3	2013	5,000
	Replace Compressed oxygen	1.0 -		IN - Beyond	Priority		
E1028	control and manifold	EA	5000.0	Rated Life	3	2023	5,000

Item	Description
E1093 Food Service Equipment	Vegatable Peeler
Condition	Fair - Good
Qty / UOM	1 / EA
RUL (years)	4
Location	Central Kitchen

106686.13R-001.305

# **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Vegetable			IN - Beyond Rated	Priority		
E1093	Peeler	1.0 - EA	6500.0	Life	4	2017	6,500
	Replace Vegetable			IN - Beyond Rated	Priority		
E1093	Peeler	1.0 - EA	6500.0	Life	4	2032	6,500

Item	Description
E1093 Food Service Equipment	Four Drawer Warmer
Condition	Fair - Good
Qty / UOM	1/EA
RUL (years)	6
Location	Central Kitchen

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Four Drawer			IN - Beyond Rated	Priority		
E1093	Warmer	1.0 - EA	2800.0	Life	4	2019	2,800

Item	Description
E1093 Food Service Equipment	Convection Steamer
Condition	Good

106686.13R-001.305

Item	Description
Qty / UOM	1 / EA
RUL (years)	2
Location	Central Kitchen

# **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Convection			IN - Beyond Rated	Priority		
E1093	Steamer	1.0 - EA	12800.0	Life	3	2015	12,800
	Replace Convection			IN - Beyond Rated	Priority		
E1093	Steamer	1.0 - EA	12800.0	Life	3	2030	12,800

Item	Description
E1093 Food Service Equipment	Tilting Skillet
Condition	Good
Qty / UOM	1/EA
RUL (years)	6
Location	Central Kitchen

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
E1093	Replace Tilting Skillet	1.0 - EA	9800.0	IN - Beyond Rated Life	Priority 4	2019	9,800

Item	Description
E1093 Food Service Equipment	3 Compartment Sink with Drain boards
Condition	Fair
Qty / UOM	3/EA
RUL (years)	3
Location	Central Kitchen

# **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
F	Replace 3 Compartment Sink	3.0 -		IN - Beyond	Priority		
E1093	with Drain Boards	EA	1475.0	Rated Life	3	2016	4,425

Item	Description
E1093 Food Service Equipment	Exhaust Hood 4 ft X 4 ft
Condition	Poor
Qty / UOM	1/EA
RUL (years)	1
Location	Central Kitchen

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Exhaust			IN - Beyond Rated	Priority		
E1093	Hood	1.0 - EA	1.0	Life	3	2014	1

106686.13R-001.305

Item	Description
E1093 Food Service Equipment	Conveyor Dishwasher
Condition	Good
Qty / UOM	1 / EA
RUL (years)	1
Location	

# **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Conveyor			IN - Beyond	Priority		
E1093	Dishwasher	1.0 - EA	16500.0	Rated Life	3	2014	16,500

Item	Description
E1093 Food Service Equipment	Thermal Food Delivery Carts
Condition	Good
Qty / UOM	12 / EA
RUL (years)	7
Location	Central Kitchen

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
E1093	Replace Thermal Food Delivery Carts	12.0 - EA	4500.0	IN - Beyond Rated Life	Priority 4	2020	54,000

Item	Description
E1093 Food Service Equipment	Cook hood with Fire Suppression
Condition	Fair - Good
Qty / UOM	4/EA
RUL (years)	8
Location	Central Kitchen

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
E1093	Replace Cook hood with Fire Suppression	4.0 - EA	5685.0	IN - Beyond Rated Life	Priority 4	2021	22,740

Item	Description
E1093 Food Service Equipment	Stove Broiler Oven Combo
Condition	Good
Qty / UOM	1 / EA
RUL (years)	11
Location	Central Kitchen

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
E1093	Replace Stove Broiler Oven Combo	1.0 - EA	8600.0	IN - Beyond Rated Life	Priority 4	2024	8,600

Item	Description
E1093 Food Service Equipment	Walk in Freezer 6'X12'
Condition	Fair
Qty / UOM	1 / EA
RUL (years)	8
Location	Central Kitchen

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Walk in Freezer			IN - Beyond	Priority		
E1093	6′X12′	1.0 - EA	14880.3	Rated Life	4	2021	14,880

Item	Description
E1093 Food Service Equipment	Griddle 48"
Condition	Fair - Good
Qty / UOM	2/EA
RUL (years)	9
Location	

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Griddle			IN - Beyond Rated	Priority		
E1093	Replace Griddle 48"	2.0 - EA	3200.0	Life	4	2022	6,400

106686.13R-001.305

Item	Description
E1093 Food Service Equipment	Reach in Refrigerator 49CF
Condition	Fair - Good
Qty / UOM	1 / EA
RUL (years)	9
Location	

# **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Reach in	1.0 -		IN - Beyond	Priority		
E1093	Refrigerator 49CF	EA	4108.1	Rated Life	4	2022	4,108

Item	Description
E1093 Food Service Equipment	Ice Maker
Condition	Fair
Qty / UOM	1/EA
RUL (years)	7
Location	Central Kitchen

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
E1093	Replace Ice Maker	1.0 - EA	6200.0	IN - Beyond Rated Life	Priority 4	2020	6,200

Item	Description
E1093 Food Service Equipment	Stainless Steel Prep Table with Dual Reach in Refrigerators
Condition	Good
Qty / UOM	1 / EA
RUL (years)	12
Location	Central Kitchen

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Stainless Steel Prep						
E1093	Table with Dual Reach in Refrigerators	1.0 - EA	3200.0	IN - Beyond Rated Life	Priority 4	2025	3,200

Item	Description
E1093 Food Service Equipment	Reach in Refrigerator 68 CF
Condition	Fair - Good
Qty / UOM	1 / EA
RUL (years)	6
Location	Central Kitchen

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Reach in	1.0 -		IN - Beyond	Priority		
E1093	Refrigerator 68 CF	EA	7051.2	Rated Life	4	2019	7,051

Item	Description
E1093 Food Service Equipment	Walk in Refrigerator 8'X8'
Condition	Fair
Qty / UOM	1 / EA
RUL (years)	8
Location	Central Kitchen

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
E1093	Replace Walk in Refrigerator 8'X8'	1.0 - EA	8787.8	IN - Beyond Rated Life	Priority 4	2021	8,788

Item	Description
E1093 Food Service Equipment	Steam Table, Electric 3-Well
Condition	Good
Qty / UOM	2/EA
RUL (years)	11
Location	Central Kitchen

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Steam Table,	2.0 -		IN - Beyond	Priority		
E1093	Electric 3-Well	EA	2450.0	Rated Life	4	2024	4,900

Item	Description
E1093 Food Service Equipment	Oven
Condition	Fair
Qty / UOM	1/EA
RUL (years)	3
Location	Main Kitchen

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
E1093	Replace Oven	1.0 - EA	5413.0	IN - Beyond Rated Life	Priority 3	2016	5,413

Item	Description
E1093 Food Service Equipment	Disposal 1HP Custom
Condition	Poor
Qty / UOM	1 / EA
RUL (years)	0
Location	Central Kitchen

# **Observations/Comments:**

Garbage system is subject to frequent failures. Immediate replacement is required.

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
				IN - Beyond Rated	Priority		
E1093	Replace Disposal	1.0 - EA	12500.0	Life	3	2013	12,500



Item	Description
E1093 Food Service Equipment	Skillet
Condition	Fair
Qty / UOM	1 / EA
RUL (years)	3
Location	

# **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
				IN - Beyond Rated	Priority		
E1093	Replace Skillet	1.0 - EA	11500.0	Life	3	2016	11,500

Item	Description
E1093 Food Service Equipment	Mixer
Condition	Good
Qty / UOM	2/EA
RUL (years)	9
Location	Central Kitchen

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
				IN - Beyond Rated	Priority		
E1093	Replace Mixer	2.0 - EA	12479.0	Life	4	2022	24,958

Item	Description		
E1093 Food Service Equipment	Fryer Floor Mounted Twin Baskets		



106686.13R-001.305

Item	Description
Condition	Fair
Qty / UOM	2/EA
RUL (years)	5
Location	Central Kitchen

# **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Fryer Floor	2.0 -		IN - Beyond	Priority		
E1093	Mounted Twin Baskets	EA	2846.8	Rated Life	4	2018	5,694

# **Cost Summary:**

Year	Total Expenditures
2013	\$1 <i>7,</i> 500
2014	\$16,501
2015	\$12,800
2016	\$21,338
2017	\$6,500
2018	\$5,694
2019	\$19,651
2020	\$60,200
2021	\$46,408
2022	\$35,466
2023	\$31,624
2024	\$13,500
2025	\$3,200
2027	\$50,590
2030	\$12,800
2032	\$6,500

# G BUILDING SITEWORK SYSTEMS

# G20 SITE IMPROVEMENTS

Site Information					
ltem	Description				
Main Ingress and Egress	North Street				
Access from	W				
Additional Entrances	Park Street				
Access from	E				
Parking Count: Open lot	313				
Parking Count: Sheltered by carports	0				
Parking Count: Private garages	2				
Parking Count: Subterranean garage	0				
Parking Count: Freestanding parking structure	0				
Number of ADA Compliant Spaces	12				
Number of ADA Compliant Spaces for Vans	2				
Method of obtaining parking count	Point of contact and physical count				
Property Identification Sign-Primary	Monument Sign				
Property Identification Sign- Secondary	Structure mounted				
Illuminated Identification Signage	No				
Building Identification Sign	No				
Illuminated Sign	No				
Location of Property ID Sign	East side of the property				
Trees Present	Yes				
Shrubs Present	Yes				
Grasses Present	Yes				
Flower beds Present	Yes				
Decorative Rocks Present	N/A				
Lava Rocks Present	N/A				
Ponds Present	Yes				
Fountains Present	No				
Topography	Flat				

Item	Description
G2012 Paving & Surfacing	Asphalt Paved Drives and Parking
Condition	Poor
Qty / UOM	4200 / SY
RUL (years)	22
Location	Front drive, visitor and south staff parking

#### **Observations/Comments:**

The asphalt roadway and parking lots require milling and resurfacing due to alligator cracking and large pot holes.

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
G2012	Repair Asphalt paved roads, front and south rear parking	2,100.0 - SY	16.7	OP - Maintenance	Priority 4	2014	35,070
G2012	Cut & Patch Asphalt - full depth repairs as needed in conjunction with mill and resurfacing	200.0 - SF	2.4	OP - Maintenance	Priority 4	2014	476
02012	resumaemo	51	2	- Mantenance		2011	., 0
G2012	Seal Coat Asphalt	37,200.0 - SF	0.5	OP - Maintenance	Priority 4	2020	18,600
							,
G2012	Seal Coat Asphalt (	37,200.0 - SF	0.5	OP - Maintenance	Priority 4	2025	18,600

106686.13R-001.305

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
		37,200.0		OP -	Priority		
G2012	Seal Coat Asphalt	- SF	0.5	Maintenance	4	2030	18,600

Item	Description
G2012 Paving & Surfacing	Asphalt Swale at Maintenance Service Drive
Condition	Poor
Qty / UOM	98 / SY
RUL (years)	1
Location	Drive between Laundry and Maintenance

#### **Observations/Comments:**

The service drive between kitchen, laundry and maintenance floods during storms. Storm, sewer and distribution piping has been repaired. Additional fill, grading, stone base and an asphalt paved swale will direct surface drainage to nearby surface storm drains.

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
G2012	Replace Asphalt Swale at Maintenance Service Drive	98.0 - SY	16.5	IN - Beyond Rated Life	Priority 3	2014	1,617

Item	Description
G2022 Paving & Surfacing	Staff Parking Lot & Drives
Condition	Fair - Good
Qty / UOM	82000 / SF
RUL (years)	20
Location	Site northeast



106686.13R-001.305

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
G2022	Seal Coat Asphalt	82,000.0 - SF	0.5	OP - Maintenance	Priority 4	2017	41,000
G2022	Restripe Parking Lots	313.0 - Stall	11.0	OP - Maintenance	Priority 4	2017	3,443
G2022	Seal Coat Asphalt	82,000.0 - SF	0.5	OP - Maintenance	Priority 4	2022	41,000
G2022	Restripe Parking Lots	313.0 - Stall	11.0	OP - Maintenance	Priority 4	2024	3,443
G2022	Seal Coat Asphalt	82,000.0 - SF	0.5	OP - Maintenance	Priority 4	2027	41,000
G2022	Restripe Parking Lots	313.0 - Stall	11.0	OP - Maintenance	Priority 4	2031	3,443

106686.13R-001.305

1	Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
G	2022	Seal Coat Asphalt	82,000.0 - SF	0.5	OP - Maintenance	Priority 4	2032	41,000

Item	Description
G2041 Fences & Gates	Chain Link Fence
Condition	Poor - Fair
Qty / UOM	880 / LF
RUL (years)	1
Location	Boundry at Deer Park

#### **Observations/Comments:**

Boundary fence with Deer Park requires frequent repairs. A more secure fence is required.

#### **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
G2041	Replace Chain Link Fence	880.0 - LF	28.5	OP - Security	Priority 3	2014	25,080

Item	Description
G2041 Fences & Gates	Chain link fence at East Boundary
Condition	Fair
Qty / UOM	960 / LF
RUL (years)	10
Location	East site Boundary

# **Observations/Comments:**

The east boundary has foot traffic from high school across Park Street. The fence prevents shortcuts through the cemetary. The fence is deteriorating and will require replacement.



106686.13R-001.305

# **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
G2041	Replace Chain link fence at East Boundary	960.0 - LF	17.3	OP - Security	Priority 4	2023	16,560

Item	Description
G2041 Fences & Gates	Security Fence
Condition	Good
Qty / UOM	50 / LF
RUL (years)	7
Location	Wing C south Courtyard

# **Observations/Comments:**

Security fence is imposing to residents it contains. Full fence coverage plantings is required to fully cover fence.

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Security			IN - Beyond Rated	Priority		
G2041	Fence	50.0 - LF	29.6	Life	4	2020	1,481

Item	Description
G2045 Site Furnishings	Smoker Den
Condition	Poor
Qty / UOM	2/EA
RUL (years)	0
Location	Along east staff parking areas



# **Observations/Comments:**

Smoking shacks are provided for staff. The two shacks are in poor condition and require replacement.

#### **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Replace Smoking			IN - Beyond Rated	Priority		
G2045	Shack	2.0 - EA	1200.0	Life	3	2013	2,400
	Daulaaa Cuaaliina			INI Davianal Data d	Dui a uita a		
	Replace Smoking			IN - Beyond Rated	Priority		
G2045	Shack	2.0 - EA	1200.0	Life	3	2028	2,400

Item	Description
G2052 Erosion Control Measures	Landscape turf around building perimeter walls
Condition	Poor
Qty / UOM	35 / CSF
RUL (years)	0
Location	Bulding perimeters

# **Observations/Comments:**

Back-fill settlement along most building perimeters, particularly at inside corners, has caused rain surface drainage to concentrate along foundation walls. This is likely the primary contributor to basement and crawlspace flooding. Addition of compacted fill in these areas is recommended to create positive drainage away from all building perimeters.

106686.13R-001.305

# **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
G2052	Replace Landscape turf around building perimeter walls	35.0 - CSF	985.0	IN - Beyond Rated Life	Priority 3	2013	34,475

#### **Cost Summary:**

Year	Total Expenditures
2013	\$36,875
2014	\$62,243
2017	\$44,443
2020	\$20,081
2022	\$41,000
2023	\$16,560
2024	\$3,443
2025	\$18,600
2027	\$41,000
2028	\$2,400
2030	\$18,600
2031	\$3,443
2032	\$41,000

# **G30** SITE CIVIL/Mechanical Utilities

Item	Description		
G3013 Well Systems	Well Pump, 400GPM		
Condition	Good		
Qty / UOM	2/EA		
RUL (years)	19		
Location	Geothermal Wells		



106686.13R-001.305

# **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
G3013	Replace Well Pump, 400GPM	2.0 - EA	8650.0	IN - Beyond Rated Life	Priority 4	2032	17,300

Item	Description
G3052 Wells for Cooling/Heating	Geothermal Wells
Condition	Good
Qty / UOM	2/EA
RUL (years)	44
Location	NW Corner of Property

Item	Description
G3063 Fuel Storage Tanks	UST, Propane, 1,000 Gallon Tank
Condition	Good
Qty / UOM	4/EA
RUL (years)	22
Location	Yard, East of A Wing, North of Maintenance Garage

# **Observations/Comments:**

The buried tanks are approximately three years old and believed to be in good condition.

# **Cost Summary:**

Year	Total Expenditures
2032	\$17,300



106686.13R-001.305

#### **G40** SITE ELECTRICAL Utilities

Item	Description		
G4021 Fixtures & Transformers	Convert Entry Flag Pole Lights to Grade LED		
Condition	Poor		
Qty / UOM	50 / EA		
RUL (years)	0		
Location	Along Entry Drive		

#### **Observations/Comments:**

Flag pole fixtures above grade are frequently damaged. Halogen PAR lamps when replaced with LED are easily and frequently stolen. Replacement with recessed LED uplights is recommended.

#### **Recommendations:**

Туре	Component Description	Qty / UOM	Unit Cost (\$)	Plan Type	Priority	Year	Expenditures (\$)
	Convert Entry Flag Pole	50.0 -		IN - Beyond	Priority		
G4021	Lights to Grade LED	EA	785.0	Rated Life	3	2013	39,250
	Convert Entry Flag Pole	50.0 -		IN - Beyond	Priority		
G4021	Lights to Grade LED	EA	785.0	Rated Life	3	2028	39,250

#### **Cost Summary:**

Year	Total Expenditures
2013	\$39,250
2028	\$39,250



AND ENERGY AUDIT

106686.13R-001.305

#### ACCESSIBILITY ISSUES 2.

No accessibility issues were identified during the assessment.



## 3. ENERGY AUDIT

#### 1.1. ENERGY CONSERVATION MEASURES

EMG has identified 5 Energy Conservation Measures (ECMs) for this property.

List of Recommended Energy Conservation Measures For Vermont Veterans Home												
ECM #	Description of ECM	Projected Initial Investment	Estimated Annual Energy Savings			Estimated Cost Savings	Estimated Annual O&M Savings	Total Estimated Annual Cost Savings	Simple Payback	S.I.R.	Life Cycle Savings	Expected Useful Life (EUL)
			Propane	No.2 Oil	Electricity							
		\$	Gallons	Gallons	kWh	\$	\$	\$	Years		\$	Years
Capital	Capital Cost Recommendations											
,	Replace Inefficient HVAC Package System	£0.000	8,220	0	1.354	\$17.546	£216	\$17.863	0.50	20.96	\$256.850	20.00
1	Details: Replace Roof Top Unit at Administration	\$8,900	8,220	0	1,354	\$17,546	\$316	\$17,863	0.50	29.86	\$256,850	20.00
2	Replace Exit Signs With LED Exit Signs	\$5,612	0	0	24,966	\$2,915	\$5,237	\$8,152	0.69	17.34	\$91,709	15.00
	Details: Update remaining incandescant exit signs											
	Replace Halogen Flood Lamps With LED	\$103,791	0	0	55,298	\$6,456	\$27,500	\$33,956	3.06	3.91	\$301,576	15.00
3	Details: Along Entry Drive for Flag Poles											
	Replace Inefficient Linear Fluorescent Lamps	\$150,296	0	0	345,009	\$40,281	\$0	\$40,281	3.73	2.29	\$193,308	10.00
4	Details: Replace Remaining T-12s Adding Motion Sensors where Practical											
	Replace External Windows	\$9,900	0	271	464	\$983	\$10	\$993	9.97	1.97	\$9,569	30.00
5	Details: Single Glazed Windows Along Corridors along Chapel and Social Hall											
Total For Capital Cost		\$278,499	8,220	271	427,090	\$68,182	\$33,063	\$101,245	2.75			
	Interactive Savings Discount @ 10%		-822	-27	-42,709	-\$6,818	-\$3,306	-\$10,125				
	Total Contingency Expenses @ 15%	\$41,775										
Total for	Improvements	\$320,274	7,398	244	384,381	\$61,364	\$29,757	\$91,121	3.51			

#### 1.2. RECOMMENDED OPERATIONS AND MAINTENANCE PLAN

The quality of the maintenance and the operation of the facility's energy systems have a direct effect on its overall energy efficiency. Energy-efficiency needs to be a consideration when implementing facility modifications, equipment replacements, and general corrective actions. The following is a list of activities that should be performed as part of the routine maintenance program for the property. These actions, which have been divided into specific and general recommendations, will insure that the energy conservation measures identified in this report will remain effective. The following general recommendations should be continued or implemented.

#### **Building Envelope**

- 1. Caulking and weather stripping functional and effective at all times
- 2. Walls observed periodically and holes patched in the building envelope as required
- 3. Windows inspected periodically for damaged panes and failed thermal seals

#### Heating and Cooling

- 1. Air filters inspected periodically and replaced prior to excessive visual buildup (May increase filter costs, but will reduce fan energy costs)
- 2. Boiler tubes inspected and cleaned annually



AND ENERGY AUDIT

106686.13R-001.305

- 3. Temperature settings reduced in unoccupied areas and set points seasonally adjusted.
- 4. Control valves and dampers checked for functionality monthly and repaired, when needed
- 5. Equipment inspected for worn or damaged parts as part of a monthly maintenance check
- 6. Hot air registers and return air ductwork clean and unobstructed
- 7. Air dampers operating correctly

#### Domestic Hot Water

- 1. Domestic water heater temperature set to the minimum temperature required
- 2. Hot water piping checked routinely for damaged insulated and leaks
- 3. Tank-type water heaters flushed monthly

#### Lighting

- 1. Over-lit areas managed by bi-level switching or photocell controls
- 2. Lighting fixture reflective surfaces and translucent covers clean
- 3. Walls clean and bright to maximize lighting effectiveness
- 4. Timers and/or photocells operating correctly on exterior lighting

#### **Existing Equipment and Replacements**

- 1. Refrigerator and freezer doors closed and sealed correctly
- 2. Kitchen exhaust fans only used when needed or timers installed to limit operation
- 3. Office/computer equipment either in the "sleep" or "off" mode when not used
- 4. All other recommended equipment specific preventive maintenance actions conducted

# 4. GENERAL ASSESSMENT INFORMATION

The weather at the time of the assessment was:

Item	Description
Approximate Outdoor Temperature (degrees F)	60
Weather Conditions	Cloudy
Snow Covering Ground	No
Wind Conditions	Little to no wind

The documentation provided at the time of the assessment is as:

Item	Description
Site Plan Reviewed	Yes
Floor Plan Reviewed	Yes
Construction Drawings Reviewed	Yes
Termite Inspection Report Reviewed	No
<b>Boiler Certificates Reviewed</b>	Yes
Previous FCA Report Available	Yes
Previous Report Prepared By	Timothy D. Smith & Associates PC Architects
Previous Report Date	October 1, 2006
Document Year Built Information Obtained From	

106686.13R-001.305

### 5. CERTIFICATION

EMG has completed a Facility Condition Assessment (FCA) and Energy Audit of the subject property listed on the cover page. The FCA was performed at the Client's request using methods and procedures consistent with good commercial and customary practice conforming with ASTM E2018-08, Standard Guide for Property Condition Assessments: Baseline Property Condition Assessment Process. Within this Property Condition Report (PCR), EMG's reference to the Client follows the ASTM guide's definition of User, that is, the party that retains EMG for the preparation of a baseline PCA of the subject property.

This report is exclusively for the use and benefit of the Client identified on the first page of this report. The purpose for which this report shall be used shall be limited to the use as stated in the contract between the client and EMG.

The opinions EMG expresses in this report were formed utilizing the degree of skill and care ordinarily exercised by any prudent architect or engineer in the same community under similar circumstances. EMG assumes no responsibility or liability for the accuracy of information contained within this report that has been obtained from the Client or the Client's representatives, from other interested parties, or from the public domain. The conclusions presented represent EMG's professional judgment based on information obtained during the course of this assignment. EMG's evaluations, analyses, and opinions are not representations regarding the building design, structural soundness, or actual value of the property. Factual information regarding operations, conditions, and test data provided by the Client or the Client's representative has been assumed to be correct and complete. The conclusions presented within this report are based on the data provided, observations made, and conditions that existed specifically on the date of the assessment. EMG certifies that EMG has no undisclosed interest in the subject property, that EMG's relationship with the Client is at arm's-length, and that EMG's employment and compensation are not contingent upon the findings or estimated costs to remedy any noted deficiencies due to deferred maintenance and/or any noted component or system replacements.

EMG's FCA cannot wholly eliminate the uncertainty regarding the presence of physical deficiencies and/or the performance of a subject property's building systems. Preparation of a FCA in accordance with ASTM E2018-08 is intended to reduce, but not eliminate, the uncertainty regarding the potential for component or system failure and to reduce the potential that such component or system failure may not be initially observed. This FCA was prepared recognizing the inherent subjective nature of EMG's opinions as to such issues as workmanship, quality of original installation, and estimating the remaining useful life of any given component or system. It should be understood that EMG's suggested remedy may be determined under time constraints or may be formed without the aid of engineering calculations, testing, exploratory probing, the removal of materials, or design. Furthermore, there may be other alternate or more appropriate schemes or methods to remedy the noted physical deficiencies. EMG's opinions are generally formed without detailed knowledge from individuals familiar with the performance of noted components or systems.

AND ENERGY AUDIT

106686.13R-001.305

Any questions regarding this report should be directed to the Program Manager listed on the cover page of this report.

**Prepared By:** Jeff Stannard and Frank Lee, Field Observers

Daniel White

**Reviewed By:** 

Danny White Report reviewer for

Marge Mitnick, Program Manager

106686.13R-001.305

## 6. APPENDICES

APPENDIX A: Photographic Record

APPENDIX B: Site Plan

APPENDIX C: Records of Communication

APPENDIX D: Supporting Documentation

APPENDIX E: Pre-Survey Questionnaire

APPENDIX F: Energy Conservation Measures



AND ENERGY AUDIT

106686.13R-001.305

# APPENDIX A: PHOTOGRAPHIC RECORD









Chapel



B Wing entrance



Original building







A Wing



Rear of A Wing



Dementia courtyard



Old boiler laundry building



Old boiler and laundry



Brick veneer - upper floor



Elevator penthouse






Vertical and horizontal wood siding



Vertical wood siding



Wood cornice of original house



Garage wood siding





EIFS finish at North Village Wing



South elevation of North Village Wing




Brick chimney



Window sealant









Fixed windows



Exterior door



TPO roofing, North Wing



In-Service Social Building



In-Service Social Building



TPO roof membrane



TPO roof over central dining








Flat roof over entrance

Main roof finishes



Main roof finishes



Asphalt shingle roof on original building




Old boiler and maintenance shingle roofs



Asphalt shingle roof on old boiler building




Plexi-glass skylights



Plexi-glass skylights






Automatic accessible door



Automatic accessible door




Vinyl floor tile



Room finishes





Hydraulic elevator equipment



Elevator cab



Elevator hydraulics



Laundry hot-water steam-fed tank





Oi-fired steam boiler, domestic hot water



Oil-fired steam boiler



Geothermal system circulation pumps



Common area AHU





Heat pump



Heat pump



Well pump controller



New service transformer





Electrical distribution panels



Main electric service switchgear



Staff parking



Addressable fire alarm system panel





Network distribution and control systems -



Diesel generator



Propane generator



Diesel generator






Diesel generator



Diesel generator




Commercial washers



Compressed oxygen control and manifold






Cook hood with fire suppression



Cook hood with fire suppression



Reach in refrigerator




Steam table






ENERGY SAVER
CONDENSATE
CONTROL

Walk in refrigerator





Walk in refrigerator



Ice maker











Oven



Conveyor dishwasher







Disposal



Convection steamer



Four drawer warmer





Four drawer warmer



Reach in freezer



Thermal food delivery carts



Stove broiler oven combo








Griddle

Mixer



3-compartment sink with drain



Custom corner sink





Walk in freezer



Walk in freezer



South Crescent Drive



Asphalt pavement at Maintenance Service Drive





Fence

Fence



Chain link fence at east boundary



Security fence along Dementia Courtyard



Security fence along Dementia Courtyard



Security fence along Dementia Courtyard



Smoking shack



Smoking shack





Poor site garding at building perimeter



Poor site grading at building perimeter



Poor site grading at building perimeters




Geothermal well site



AND ENERGY AUDIT

106686.13R-001.305








Entry flag poles

AND ENERGY AUDIT

106686.13R-001.305

# APPENDIX B: SITE PLAN





## FACILITY CONDITION ASSESSMENT

AND ENERGY AUDIT

106686.13R-001.305

## APPENDIX C: RECORDS OF COMMUNICATION



## FACILITY CONDITION ASSESSMENT

AND ENERGY AUDIT

106686.13R-001.305

RECORD OF COMMUNICATION

Date: October 14, 2013 Time: All day

Project Number: 106686.13R-001.305 Recorded by: Jeff Stannard and Frank Lee, Field

Observer/Project Manager

Project Name: Vermont Veterans' Home

**Communication with:** Peter Hack and Dick Franz

of: Vermont Veterans' Home
Phone: Peter Hack w) 802.233.4258

Dick Franz w) 802.447.6528, c) 802.375.4475

**Communication via:** 

Office Visitation/ Meeting

RE:

Onsite interview and survey.

**Summary of Communication:** 

AND ENERGY AUDIT

106686.13R-001.305

## APPENDIX D: SUPPORTING DOCUMENTATION



## 20 YEAR EXPENDITURE FORECAST

Vermont Veterans' Home 325 North Street Bennington, Vermont

Element No.	Component Description	Asset	Location	Action	Estimated Useful Life or Replacement Cycle	Remaining Useful Life (Yrs)	Quantity	Unit of Measurement	Unit Cost	Plan Type	Priority	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022
					(Yrs)							0 Deferred	1 Scheduled	2 Scheduled	3 Scheduled	4 Scheduled	5 Scheduled	6 Scheduled	7 Scheduled	8 Scheduled	9 Scheduled
A. SUBSTRU	ICTURE		1	1	1		1	1	1	<u> </u>	ı	Deletteu	Scrieduled	Scrieduled	Scrieduled	Scrieduled	Scrieduled	Scrieduled	Scrieduled	Scrieduled	Scrieduled
				<u> </u>						A. SUBSTRUCTURE	SUB-TOTALS	\$0	Sn.	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B. SHELL			1			1		1	1		1		•		The state of the s			· ·	•		
B20	EXTERIOR ENCLOSURE		I																		
B2011	Brick Veneer - Upper Floor Wood Siding	Brick Exteriors Vertical wood siding	Most exterior walls In-Service & Social Hal	Point Brick Exterior Walls where required General Painting Cost Per SF, Minor Prep	10 10	5	20.00 675.00	CSF SF	\$948.00 \$1.41	OP - Maintenance OP - Maintenance	Priority 4 Priority 4	\$0 \$952	\$0 \$0	\$0 \$0	\$0 \$0	\$0 \$0	\$18,960 \$0	\$0 \$0	\$0 \$0	\$0 \$0	\$0 \$0
B2011	Wood Siding	Vertical wood siding		Work, Up to 4-Story Bldg.  Ill Replace Vertical wood siding	25	11	675.00	SF	\$12.68	IN - Beyond Rated Life	Priority 4	\$932	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
	EIFS with Stucco Over Cement Board	EIFS with Stucco Over Cement Board	North Village Wing	Color Coat 100% of Asset: EIFS	0	19	44.00	CSF	\$218.00	OP - Maintenance	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2011	EIFS with Stucco Over Cement Board	EIFS with Stucco Over Cement Board	North Village Wing	Repair 10% of Asset: EIFS with Stucco Over Cement Board	8	3	5.00	CSF	\$476.00	OP - Maintenance	Priority 4	\$0	\$0	\$0	\$2,380	\$0	\$0	\$0	\$0	\$0	\$0
B2011	Solid Wood Lap Siding	Wood Lap Siding and Trim	Origional Bldg and Mainte. Garage	Paint Existing Wood Siding and trim, One Coat Spray with Medium Prep and Clean Up	10	2	5,200.00	SF	\$1.23	OP - Maintenance	Priority 4	\$0	\$0	\$6,396	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2011	Caulking, Polyurethane, 1/4"X1/4"	Caulk sealant at joints and openings	All exterior walls	Replace Caulk sealant at joints and openings	15	6	3,000.00	LF	\$3.84	OP - Maintenance	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$11,520	\$0	\$0	\$0
B2011 B2021	Solid Masonry  Aluminum Window , 4-0 X 6-0,First Floor	Brick Chimney Corridor Windows	Boiler Building Corridor at Dining and	Repair 100% of Asset: Brick Chimney  Replace Corridor Windows	10 25	0	1.00	EA EA	\$25,000.00 \$1,276.99	OP - Maintenance IN - Beyond Rated Life	Priority 4 Priority 3	\$0 \$22,986	\$25,000 \$0	\$0 \$0	\$0 \$0	\$0 \$0	\$0 \$0	\$0 \$0	\$0 \$0	\$0 \$0	\$0 \$0
B2021	3' X 4' Aluminum Window Operable	Casement Windows	Chapel Administration and D	Replace Casement Windows	25	2	64.00	EA	\$911.00	IN - Beyond Rated Life	Priority 3	\$0	\$0	\$58,304	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2032	3'-0" X 7'-0" Steel, Insulated Core, Ptd. Door	Exterior Steel Doors	All entrances	Repair 8% of Asset: 3'-0" X 7'-0" Steel,	4	1	4.00	EA	\$1,098.00	IN - Reliability	Priority 3	\$0	\$4,392	\$0	\$0	\$0	\$4,392	\$0	\$0	\$0	\$4,392
P20	ROOFING		<u> </u>	Insulated Core, Ptd. Door	<u> </u>	1	<u> </u>	<u> </u>	<u> </u>		*		<u> </u>	<u> </u>	<u> </u>	·	•	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	•
B3011	Tpo, Roof 45 Mills, Full Adhered	TPO Roof on Entrance, Dining and East Wing	Entrance, Dining and East Wing	Replace TPO Roof on Entrance, Dining and East Wing	20	0	250.00	SQ	\$714.09	IN - Reliability	Priority 3	\$178,523	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3011	Wood Shingle , Historic Structure	Wood Roof Shingles	In-Service Social	Replace Wood Roof Shingles	25	15	25.00	SQ	\$817.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3011	Asphalt Shingles, Removal and with Premium Grade	Asphalt Shingles Original House	House, Boiler and Maintenance Buildngs	Replace Asphalt Shingles Original House	30	3	120.00	sq	\$430.00	IN - Reliability	Priority 3	\$0	\$0	\$0	\$51,600	\$0	\$0	\$0	\$0	\$0	\$0
B3011	Tpo, Roof 45 Mills, Full Adhered	TPO Roofs on B. C and D Wings	B, C, & D Wings	Replace TPO Roofs on B. C and D Wings	20	19	250.00	SQ	\$714.09	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3011	Tpo, Roof 45 Mills, Full Adhered	TPO Roof North Wings		Replace TPO Roof North Wings	20	18	300.00	SQ	\$714.09	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3011	Tpo, Roof 45 Mills, Full Adhered	TPO Roof on A Wing and D Dayroom		Replace TPO Roof on A Wing and D Dayroom	99	18	300.00	SQ	\$1.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3021	Plexi-Glass Skylight to 10 SF	Plexi-Glass Skylights	Flat Roofs	Replace Plexi-Glass Skylights	20	17	25.00	EA	\$328.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3021	B3021 Glazed Roof Openings	Plexi-Glass Skylights	Flat Roofs	Replace Plexi-Glass Skylights	20	3	15.00	EA	\$1.00	IN - Beyond Rated Life	Priority 3	\$0	\$0	\$0	\$15	\$0	\$0	\$0	\$0	\$0	\$0
C. INTERIOR											CUD TOTAL C	£000 400	\$20.202	E04700	¢E2.00E		622.252	644 500	60	\$0	\$4,392
										B. SHELL	L SUB-TUTALS	\$202,460	923,332	\$64,700	\$55,995	\$0	\$23,352	\$11,520	\$0	φU	ψ4,552
C. INTERIOR	RS .					I				B. SHELL	L SUB-TUTALS	\$202,460	\$29,392	\$64,700	\$33, <del>99</del> 3	\$0	\$23,3 <b>3</b> 2	\$11,520	\$0	φυ	ψ <del>1</del> ,002
C10	INTERIOR CONSTRUCTION			Renair 2% of Asset: Automatic Accessible																	
C10 C1021		Automatic Accessible Door, Wood		Repair 2% of Asset: Automatic Accessible Door, Wood with Glass Panels	2	1	2.00	EA	\$6,500.00	OP - Maintenance	Priority 4	\$202,450	\$13,000	\$0	\$13,000	\$0	\$13,000	\$11,520	\$13,000	\$0	\$13,000
C10 C1021 C30 C3024	INTERIOR CONSTRUCTION Automatic Accessible Door, Wood with Glass	Automatic Accessible Door, Wood  Vinyl Composition Floor Tiles	Throughout interiors		2	1	2.00				Priority 4	\$0									
C10 C1021 C30 C3024	INTERIOR CONSTRUCTION Automatic Accessible Door, Wood with Glass Panels INTERIOR FINISHES Vinyl Tile		Throughout interiors	Door, Wood with Glass Panels	2 5	1 1				OP - Maintenance	Priority 4	\$0	\$13,000 \$30,488	\$0	\$13,000 \$0		\$13,000 \$0	\$0 \$30,488	\$13,000 \$0	\$0	\$13,000 \$0
C10 C1021	INTERIOR CONSTRUCTION Automatic Accessible Door, Wood with Glass Panels INTERIOR FINISHES Vinyl Tile		Throughout interiors	Door, Wood with Glass Panels	2 5	1				OP - Maintenance	Priority 4	\$0	\$13,000 \$30,488	\$0	\$13,000 \$0	\$0	\$13,000 \$0	\$0 \$30,488	\$13,000 \$0	\$0	\$13,000 \$0
C10 C1021 C30 C3024	INTERIOR CONSTRUCTION Automatic Accessible Door, Wood with Glass Panels INTERIOR FINISHES Vinyl Tile		Throughout interiors	Door, Wood with Glass Panels	2 5	1				OP - Maintenance	Priority 4	\$0	\$13,000 \$30,488	\$0	\$13,000 \$0	\$0	\$13,000 \$0	\$0 \$30,488	\$13,000 \$0	\$0	\$13,000 \$0
C10 C1021 C30 C3024	INTERIOR CONSTRUCTION Automatic Accessible Door, Wood with Glass Panels INTERIOR FINISHES Vinyl Tile	Vinyl Composition Floor Tiles	Throughout interiors  B/C Wing	Door, Wood with Glass Panels	5	1			\$67.75	OP - Maintenance	Priority 4 Priority 4 S SUB-TOTALS	\$0	\$13,000 \$30,488	\$0	\$13,000 \$0	\$0	\$13,000 \$0	\$0 \$30,488	\$13,000 \$0	\$0	\$13,000 \$0
C10 C1021 C30 C3024 D. SERVICE: D10 D1011	INTERIOR CONSTRUCTION Automatic Accessible Door, Wood with Glass Panels INTERIOR FINISHES Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC	Vinyl Composition Floor Tiles  Hydraulic Elevator, Small Cab	B/C Wing	Door, Wood with Glass Panels  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab	5	1	1.00	SY	\$67.75 \$67.75	OP - Maintenance IN - Appearance C. INTERIORS IN - Beyond Rated Life	Priority 4 Priority 4 S SUB-TOTALS Priority 3	\$0	\$13,000 \$30,488 \$43,488	\$0 \$0 \$0	\$13,000 \$0 \$13,000	\$0	\$13,000 \$0 \$13,000	\$0 \$30,488 \$30,488	\$13,000 \$0 \$13,000	\$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$3,000
C10 C1021 C30 C3024  D. SERVICE: D10 D1011 D30 D3022.1	INTERIOR CONSTRUCTION Automatic Accessible Door, Wood with Glass Panels INTERIOR FINISHES Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC Heating Water Distribution Pump 3 HP	Vinyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps	B/C Wing  Basement/Crawl Spaces	Door, Wood with Glass Panels  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps	30	1 9	1.00	EA EA	\$67.75 \$24,940.22 \$6,941.00	OP - Maintenance IN - Appearance C. INTERIORS IN - Beyond Rated Life IN - Beyond Rated Life	Priority 4  Priority 4  SUB-TOTALS  Priority 3  Priority 4	\$0 \$0 \$0 \$0 \$0	\$13,000 \$30,488 \$43,488 \$24,940	\$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0	\$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0	\$0 \$30,488 \$30,488 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0	\$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$242,935
C10 C1021 C30 C3024  D. SERVICE  D10 D1011 D30 D3022.1 D3041.1	INTERIOR CONSTRUCTION Automatic Accessible Door, Wood with Glass Panels INTERIOR FINISHES Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity HVAC Heating Water Distribution Pump 3 HP Air Handler 4,000 to 8,000 CFM	Vinyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3	B/C Wing  Basement/Crawl Spaces A Wing	Door, Wood with Glass Panels  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3	30 30 15 20	1 9 18	1.00 35.00 1.00	SY  EA  EA  EA	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00	OP - Maintenance IN - Appearance C. INTERIORS IN - Beyond Rated Life IN - Beyond Rated Life IN - Beyond Rated Life	Priority 4 Priority 4 SUB-TOTALS Priority 3 Priority 4 Priority 4	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$30,488 \$43,488 \$24,940 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0	\$0 \$30,488 \$30,488 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$242,935 \$0
C10 C1021 C30 C3024  D. SERVICE: D10 D1011 D30 D3022.1 D3041.1	INTERIOR CONSTRUCTION Automatic Accessible Door, Wood with Glass Panels INTERIOR FINISHES Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC Heating Water Distribution Pump 3 HP Air Handler 4,000 to 8,000 CFM Air Handler 2500-3000 CFM	Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3 AHU #2	B/C Wing  Basement/Crawl Spaces A Wing North Wing	Door, Wood with Glass Panels  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps  Replace AHU #3  Replace AHU #2	30 30 15 20 15	9 18 13	1.00 1.00 35.00 1.00	EA EA EA EA	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00	OP - Maintenance  IN - Appearance  C. INTERIORS  IN - Beyond Rated Life	Priority 4  Priority 4  Priority 3  Priority 3  Priority 4  Priority 4  Priority 4	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$30,488 \$43,488 \$24,940 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0	\$0 \$30,488 \$30,488 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$242,935 \$0 \$0
C10 C1021 C30 C3024  D. SERVICE D10 D1011 D30 D3022.1 D3041.1 D3041.1	INTERIOR CONSTRUCTION Automatic Accessible Door, Wood with Glass Panels INTERIOR FINISHES Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC Heating Water Distribution Pump 3 HP Air Handler 4,000 to 8,000 CFM Air Handler 2500-3000 CFM Air Handler 3600-3800 CFM	Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3 AHU #2 AHU #1	B/C Wing  Basement/Crawl Spaces A Wing North Wing North Wing	Door, Wood with Glass Panels  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #2  Replace AHU #1	30 30 5 15 20 15	9 18 18 13	1.00 1.00 35.00 1.00 1.00	EA EA EA EA EA	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$6,233.00	OP - Maintenance  IN - Appearance C. INTERIORS  IN - Beyond Rated Life	Priority 4  Priority 4  SUB-TOTALS  Priority 3  Priority 4  Priority 4  Priority 4  Priority 4	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$30,488 \$43,488 \$24,940 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0	\$0 \$30,488 \$30,488 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$242,935 \$0 \$0 \$0
C10 C1021 C30 C3024  D. SERVICE: D10 D1011 D30 D3022.1 D3041.1	INTERIOR CONSTRUCTION Automatic Accessible Door, Wood with Glass Panels INTERIOR FINISHES Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC Heating Water Distribution Pump 3 HP Air Handler 4,000 to 8,000 CFM Air Handler 2500-3000 CFM Air Handler 3600-3800 CFM Heat Pump Water Source, 4-Ton	Winyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3 AHU #2 AHU #1 Heat Pump System	B/C Wing  Basement/Crawl Spaces A Wing  North Wing  North Wing  East Wing	Door, Wood with Glass Panels  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps  Replace AHU #3  Replace AHU #2  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project	30 30 15 20 15 15	9 18 13 13	1.00 1.00 35.00 1.00 1.00 1.00	EA EA EA LS	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$6,233.00 \$140,300.00	OP - Maintenance  IN - Appearance  C. INTERIORS  IN - Beyond Rated Life  FN - Modernization	Priority 4  Priority 4  Priority 3  Priority 4  Priority 4  Priority 4  Priority 4  Priority 4  Priority 4	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$30,488 \$43,488 \$24,940 \$0 \$0 \$0 \$0 \$140,300	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$30,488 \$30,488 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$242,935 \$0 \$0 \$0 \$0
C10 C1021 C30 C3024  D. SERVICE D10 D1011 D30 D3022.1 D3041.1 D3041.1	INTERIOR CONSTRUCTION Automatic Accessible Door, Wood with Glass Panels INTERIOR FINISHES Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC Heating Water Distribution Pump 3 HP Air Handler 4,000 to 8,000 CFM Air Handler 2500-3000 CFM Air Handler 3600-3800 CFM Heat Pump Water Source, 4-Ton D3069 Other Controls & Instrumentation	Winyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3 AHU #2 AHU #1 Heat Pump System  Well Pump Controller	B/C Wing  Basement/Crawl Spaces A Wing  North Wing  North Wing  East Wing  Geothermal Wells	Repair 5% of Asset: Floor tile replacments  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #2  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.	30 30 15 20 15 15 0	9 18 13 13 1 1 0	1.00 1.00 35.00 1.00 1.00 1.00 1.00	EA EA EA LS EA	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$6,233.00 \$140,300.00 \$1,500.00	OP - Maintenance  IN - Appearance  C. INTERIORS  IN - Beyond Rated Life  IN - Reliability	Priority 4  Priority 4  Priority 3  Priority 4  Priority 4  Priority 4  Priority 4  Priority 4  Priority 3  Priority 3	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$30,488 \$43,488 \$24,940 \$0 \$0 \$0 \$0 \$0 \$140,300 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$30,488 \$30,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$242,935 \$0 \$0 \$0 \$0
C10 C1021 C30 C3024  D. SERVICE  D10 D1011 D30 D3022.1 D3041.1 D3041.1 D3041.1	INTERIOR CONSTRUCTION Automatic Accessible Door, Wood with Glass Panels INTERIOR FINISHES Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC Heating Water Distribution Pump 3 HP Air Handler 4,000 to 8,000 CFM Air Handler 2500-3000 CFM Air Handler 3600-3800 CFM Heat Pump Water Source, 4-Ton D3069 Other Controls & Instrumentation D3069 Other Controls & Instrumentation	Winyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3 AHU #2 AHU #1 Heat Pump System	B/C Wing  Basement/Crawl Spaces A Wing  North Wing  North Wing  East Wing	Repair 5% of Asset: Floor tile replacments  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #2  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to	30 30 15 20 15 15	9 18 13 13	1.00 1.00 35.00 1.00 1.00 1.00	EA EA EA LS	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$6,233.00 \$140,300.00	OP - Maintenance  IN - Appearance  C. INTERIORS  IN - Beyond Rated Life  FN - Modernization	Priority 4  Priority 4  Priority 3  Priority 4  Priority 4  Priority 4  Priority 4  Priority 4  Priority 4	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$30,488 \$43,488 \$24,940 \$0 \$0 \$0 \$0 \$140,300	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$30,488 \$30,488 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$242,935 \$0 \$0 \$0 \$0
C10 C1021 C30 C3024  D. SERVICE  D10 D1011 D30 D3022.1 D3041.1 D3041.1 D3041.1	INTERIOR CONSTRUCTION Automatic Accessible Door, Wood with Glass Panels INTERIOR FINISHES Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC Heating Water Distribution Pump 3 HP Air Handler 4,000 to 8,000 CFM Air Handler 2500-3000 CFM Air Handler 3600-3800 CFM Heat Pump Water Source, 4-Ton D3069 Other Controls & Instrumentation	Winyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps  AHU #3  AHU #2  AHU #1  Heat Pump System  Well Pump Controller  Well Pump Controller	B/C Wing  Basement/Crawl Spaces A Wing  North Wing  North Wing  East Wing  Geothermal Wells  Geothermal Wells	Repair 5% of Asset: Floor tile replacments  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.  Replace Well Pump Controller  Replace Air Compressor, Dry Pipe Sprinkler	30 30 15 20 15 15 0 0	1 9 18 13 13 1 1 0	1.00 1.00 35.00 1.00 1.00 1.00 1.00 1.00	EA EA EA LS EA EA	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$6,233.00 \$140,300.00 \$1,500.00 \$3.43	OP - Maintenance  IN - Appearance  C. INTERIORS  IN - Beyond Rated Life  IN - Reliability  IN - Beyond Rated Life	Priority 4  Priority 4  Priority 3  Priority 4  Priority 4  Priority 4  Priority 4  Priority 3  Priority 3  Priority 3	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$30,488 \$43,488 \$24,940 \$0 \$0 \$0 \$0 \$140,300 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$30,488 \$30,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
C10 C1021 C30 C3024  D. SERVICE  D10 D1011 D30 D3022.1 D3041.1 D3041.1 D3041.1 D3069	INTERIOR CONSTRUCTION Automatic Accessible Door, Wood with Glass Panels INTERIOR FINISHES Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC Heating Water Distribution Pump 3 HP Air Handler 4,000 to 8,000 CFM Air Handler 3600-3800 CFM Heat Pump Water Source, 4-Ton D3069 Other Controls & Instrumentation D3069 Other Controls & Instrumentation FIRE PROTECTION SYSTEMS Air Compressor for Dry Pipe System 520 Gal, 11HP	Winyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3 AHU #2 AHU #1 Heat Pump System  Well Pump Controller	B/C Wing  Basement/Crawl Spaces A Wing  North Wing  North Wing  East Wing  Geothermal Wells	Repair 5% of Asset: Floor tile replacments  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #2  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.  Replace Well Pump Controller	30 30 15 20 15 15 0	9 18 13 13 1 1 0	1.00 1.00 35.00 1.00 1.00 1.00 1.00	EA EA EA LS EA	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$6,233.00 \$140,300.00 \$1,500.00 \$3.43	OP - Maintenance  IN - Appearance  C. INTERIORS  IN - Beyond Rated Life  IN - Reliability	Priority 4  Priority 4  Priority 3  Priority 4  Priority 4  Priority 4  Priority 4  Priority 3  Priority 3  Priority 3	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$30,488 \$43,488 \$24,940 \$0 \$0 \$0 \$0 \$0 \$140,300 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$30,488 \$30,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$242,935 \$0 \$0 \$0 \$0
C10 C1021 C30 C3024  D. SERVICE  D10 D1011 D30 D3022.1 D3041.1 D3041.1 D3041.1 D3069	INTERIOR CONSTRUCTION Automatic Accessible Door, Wood with Glass Panels INTERIOR FINISHES Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC Heating Water Distribution Pump 3 HP Air Handler 4,000 to 8,000 CFM Air Handler 2500-3000 CFM Air Handler 3600-3800 CFM Heat Pump Water Source, 4-Ton D3069 Other Controls & Instrumentation D3069 Other Controls & Instrumentation FIRE PROTECTION SYSTEMS Air Compressor for Dry Pipe System 520 Gal, 1HP  ELECTRICAL SYSTEMS Call for Aid System with Central Monitoring	Winyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps  AHU #3  AHU #2  AHU #1  Heat Pump System  Well Pump Controller  Well Pump Controller	B/C Wing  Basement/Crawl Spaces A Wing  North Wing  North Wing  East Wing  Geothermal Wells  Geothermal Wells	Repair 5% of Asset: Floor tile replacments  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.  Replace Well Pump Controller  Replace Air Compressor, Dry Pipe Sprinkler	30 30 15 20 15 15 0 0	1 9 18 13 13 1 1 0	1.00 1.00 35.00 1.00 1.00 1.00 1.00 1.00	EA EA EA LS EA EA	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$6,233.00 \$140,300.00 \$1,500.00 \$3.43	OP - Maintenance  IN - Appearance  C. INTERIORS  IN - Beyond Rated Life  IN - Reliability  IN - Beyond Rated Life	Priority 4  Priority 4  Priority 3  Priority 4  Priority 4  Priority 4  Priority 4  Priority 3  Priority 4  Priority 4  Priority 3  Priority 4  Priority 4  Priority 4	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$30,488 \$43,488 \$24,940 \$0 \$0 \$0 \$0 \$140,300 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$30,488 \$30,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
C10 C1021 C30 C3024  D.SERVICE  D10 D1011  D30 D3022.1  D3041.1  D3041.1  D3051.1  D3069  D40 D4011	INTERIOR CONSTRUCTION Automatic Accessible Door, Wood with Glass Panels INTERIOR FINISHES Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC Heating Water Distribution Pump 3 HP Air Handler 4,000 to 8,000 CFM Air Handler 2500-3000 CFM Air Handler 3600-3800 CFM Heat Pump Water Source, 4-Ton D3069 Other Controls & Instrumentation  D3069 Other Controls & Instrumentation  FIRE PROTECTION SYSTEMS Air Compressor for Dry Pipe System 520 Gal, 11HP  ELECTRICAL SYSTEMS	Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3 AHU #2 AHU #1 Heat Pump System Well Pump Controller Well Pump Controller Air Compressor, Dry Pipe Sprinkler System	B/C Wing  Basement/Crawl Spaces A Wing North Wing North Wing East Wing Geothermal Wells Geothermal Wells Basement/Crawl Spaces	Repair 5% of Asset: Floor tile replacments  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps  Replace AHU #3  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.  Replace Well Pump Controller  Replace Air Compressor, Dry Pipe Sprinkler System  Replace Call for Aid Posts in Staff Parking	5 30 30 15 20 15 15 0 0 25	1 9 18 13 13 1 0 19	1.00 1.00 35.00 1.00 1.00 1.00 1.00 1.00	EA	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$140,300.00 \$1,500.00 \$3,43	OP - Maintenance  IN - Appearance  C. INTERIORS  IN - Beyond Rated Life  IN - Reliability  IN - Beyond Rated Life  IN - Beyond Rated Life	Priority 4  Priority 4  Priority 3  Priority 4  Priority 4  Priority 4  Priority 4  Priority 3  Priority 3  Priority 4  Priority 4  Priority 4  Priority 4  Priority 3  Priority 4  Priority 3	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$30,488 \$43,488 \$24,940 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$30,488 \$30,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
C10 C1021 C30 C3024  D. SERVICE D10 D1011 D30 D3022.1 D3041.1 D3041.1 D3051.1 D3069 D40 D4011 D50 D5034	INTERIOR CONSTRUCTION Automatic Accessible Door, Wood with Glass Panels INTERIOR FINISHES Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC Heating Water Distribution Pump 3 HP Air Handler 4,000 to 8,000 CFM Air Handler 2500-3000 CFM Air Handler 3600-3800 CFM Heat Pump Water Source, 4-Ton D3069 Other Controls & Instrumentation D3069 Other Controls & Instrumentation FIRE PROTECTION SYSTEMS Air Compressor for Dry Pipe System 520 Gal, 11HP  ELECTRICAL SYSTEMS Call for Aid System with Central Monitoring Capability	Vinyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3 AHU #2 AHU #1 Heat Pump System Well Pump Controller Well Pump Controller Air Compressor, Dry Pipe Sprinkler System  Call for Aid Posts in Staff Parking	B/C Wing  Basement/Crawl Spaces  A Wing  North Wing  Rest Wing  Geothermal Wells  Geothermal Wells  Basement/Crawl Spaces  Staff Parking  Basement Mechanical Room  Patient Mgt Stations &	Repair 5% of Asset: Floor tile replacments  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #2  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.  Replace Well Pump Controller  Replace Air Compressor, Dry Pipe Sprinkler System  Replace Call for Aid Posts in Staff Parking Replace Central Fire Alarm Control Panel Replace Network distribution and control	5 30 30 15 20 15 15 0 0 25	1 9 18 13 13 1 0 19	1.00 35.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	EA EA EA EA EA EA EA EA EA	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$6,233.00 \$140,300.00 \$3,43 \$1,679.09	OP - Maintenance  IN - Appearance  C. INTERIORS  IN - Beyond Rated Life  FN - Modernization  IN - Reliability  IN - Beyond Rated Life  IN - Beyond Rated Life  IN - Beyond Rated Life	Priority 4  Priority 4  Priority 3  Priority 4  Priority 4  Priority 4  Priority 4  Priority 3  Priority 3  Priority 4  Priority 4  Priority 4  Priority 4  Priority 3  Priority 4  Priority 4  Priority 4	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$30,488 \$43,488 \$24,940 \$0 \$0 \$0 \$0 \$0 \$140,300 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$30,488 \$30,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$0 \$242,935 \$0 \$0 \$0 \$0 \$0 \$0
C10 C1021 C30 C3024  D10 D10 D1011 D30 D3022.1 D3041.1 D3041.1 D3051.1 D3069  D40 D4011 D50 D5034 D5037	INTERIOR CONSTRUCTION Automatic Accessible Door, Wood with Glass Panels INTERIOR FINISHES Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC Heating Water Distribution Pump 3 HP Air Handler 4,000 to 8,000 CFM Air Handler 2500-3000 CFM Air Handler 3600-3800 CFM Heat Pump Water Source, 4-Ton D3069 Other Controls & Instrumentation D3069 Other Controls & Instrumentation FIRE PROTECTION SYSTEMS Air Compressor for Dry Pipe System 520 Gal, 1HP  ELECTRICAL SYSTEMS Call for Aid System with Central Monitoring Capability Fire Alarm Panel Addressable, with Voice	Vinyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3  AHU #2  AHU #1  Heat Pump System  Well Pump Controller  Well Pump Controller  Call for Aid Posts in Staff Parking  Central Fire Alarm Control Panel	B/C Wing  Basement/Crawl Spaces A Wing North Wing North Wing East Wing Geothermal Wells Geothermal Wells  Basement/Crawl Spaces  Staff Parking Basement Mechanical Room	Repair 5% of Asset: Floor tile replacments  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.  Replace Well Pump Controller  Replace Air Compressor, Dry Pipe Sprinkler System  Replace Call for Aid Posts in Staff Parking Replace Cantral Fire Alarm Control Panel	5  30  30  15  20  15  15  0  0  25  20  15  15	1 9 18 13 13 1 1 0 1 19 18 18 2 2 9	1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	EA EA EA EA EA EA EA EA EA	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$6,233.00 \$140,300.00 \$3,43 \$1,679.09	OP - Maintenance  IN - Appearance C. INTERIORS  IN - Beyond Rated Life IN - Reliability IN - Beyond Rated Life	Priority 4  Priority 3  Priority 4  Priority 3	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$30,488 \$43,488 \$24,940 \$0 \$0 \$0 \$0 \$140,300 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$30,488 \$30,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$12,115
C10 C1021 C30 C3024  D10 D1010 D1011 D30 D3022.1 D3041.1 D3041.1 D3051.1 D3069 D40 D4011 D50 D5034 D5037 D5039	INTERIOR CONSTRUCTION Automatic Accessible Door, Wood with Glass Panels INTERIOR FINISHES Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC Heating Water Distribution Pump 3 HP Air Handler 4,000 to 8,000 CFM Air Handler 2500-3000 CFM Air Handler 3600-3800 CFM Heat Pump Water Source, 4-Ton D3069 Other Controls & Instrumentation D3069 Other Controls & Instrumentation FIRE PROTECTION SYSTEMS Air Compressor for Dry Pipe System 520 Gal, 1HP  ELECTRICAL SYSTEMS Call for Aid System with Central Monitoring Capability Fire Alarm Panel Addressable, with Voice LAN System - Heavy Density	Vinyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3  AHU #2  AHU #1  Heat Pump System  Well Pump Controller  Well Pump Controller  Call for Aid Posts in Staff Parking  Central Fire Alarm Control systems	B/C Wing  Basement/Crawl Spaces  A Wing  North Wing  North Wing  East Wing  Geothermal Wells  Geothermal Wells  Basement/Crawl Spaces  Staff Parking  Basement Mcchanical Room  Patient Mgt Stations & Central Records	Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3 Replace AHU #1 Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption. Replace AHI Pump Controller  Replace AHI Compressor, Dry Pipe Sprinkler System Replace Call for Aid Posts in Staff Parking Replace Central Fire Alarm Control Panel Replace Central Fire Alarm Control Panel Replace Network distribution and control systems	30 30 15 20 15 15 0 0 25 20	1 9 18 13 13 1 1 0 19 19 18 18 2 9 0 0	1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	EA E	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$1,500.00 \$3,43 \$1,679.09 \$5,500.00 \$12,114.90 \$1.28	OP - Maintenance  IN - Appearance  C. INTERIORS  IN - Beyond Rated Life  IN - Reliability  IN - Beyond Rated Life	Priority 4  Priority 3  Priority 4  Priority 3	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$30,488 \$43,488 \$24,940 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$30,488 \$30,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$242,935 \$0 \$0 \$0 \$0 \$0 \$0 \$0
C10 C1021 C30 C3024  D10 D1010 D1011 D30 D3022.1 D3041.1 D3041.1 D3051.1 D3069  D40 D4011 D50 D5034 D5037 D5039 D5092	INTERIOR CONSTRUCTION Automatic Accessible Door, Wood with Glass Panels INTERIOR FINISHES Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC Heating Water Distribution Pump 3 HP Air Handler 4,000 to 8,000 CFM Air Handler 2500-3000 CFM Air Handler 3600-3800 CFM Heat Pump Water Source, 4-Ton D3069 Other Controls & Instrumentation  FIRE PROTECTION SYSTEMS Air Compressor for Dry Pipe System 520 Gal, 1HP  Call for Aid System with Central Monitoring Capability Fire Alarm Panel Addressable, with Voice LAN System - Heavy Density Generator, Natural Gas, 100 kW, Diesel Generator, 45 kW	Vinyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps  AHU #3  AHU #2  AHU #1  Heat Pump System  Well Pump Controller  Well Pump Controller  Call for Aid Posts in Staff Parking  Central Fire Alarm Control Panel  Network distribution and control systems  Propane Generator Module, 100kW	B/C Wing  Basement/Crawl Spaces A Wing North Wing North Wing East Wing Geothermal Wells Geothermal Wells Basement/Crawl Spaces  Staff Parking Basement Mechanical Room Patient Mgt Stations & Central Records Outside B Wing	Repair 5% of Asset: Floor tile replacments  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.  Replace Well Pump Controller  Replace Air Compressor, Dry Pipe Sprinkler System  Replace Call for Aid Posts in Staff Parking Replace Central Fire Alarm Control Panel Replace Network distribution and control systems  Replace Propane Generator Module, 100kW	30 30 15 20 15 15 0 0 25 25	1 1 9 18 13 13 1 1 0 0 19 18 18 2 9 0 0 12	1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	EA E	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$1,500.00 \$3,43 \$1,679.09 \$5,500.00 \$12,114.90 \$1.28	IN - Appearance  C. INTERIORS  IN - Beyond Rated Life  IN - Beyond Rated Life	Priority 4  Priority 4  Priority 3  Priority 4  Priority 4  Priority 4  Priority 4  Priority 3  Priority 3  Priority 4  Priority 3  Priority 4  Priority 4  Priority 3  Priority 4  Priority 4  Priority 3  Priority 4  Priority 3  Priority 4  Priority 3  Priority 3	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$30,488 \$43,488 \$24,940 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$30,488 \$30,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
C10 C1021 C30 C3024  D10 D1011 D30 D3022.1 D3041.1 D3041.1 D3051.1 D3069  D40 D4011 D50 D5034 D5037 D5039 D5092	INTERIOR CONSTRUCTION Automatic Accessible Door, Wood with Glass Panels INTERIOR FINISHES Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC Heating Water Distribution Pump 3 HP Air Handler 4,000 to 8,000 CFM Air Handler 2500-3000 CFM Air Handler 3600-3800 CFM Heat Pump Water Source, 4-Ton D3069 Other Controls & Instrumentation D3069 Other Controls & Instrumentation FIRE PROTECTION SYSTEMS Air Compressor for Dry Pipe System 520 Gal, 1HP  ELECTRICAL SYSTEMS Call for Aid System with Central Monitoring Capabiliary Panel Addressable, with Voice LAN System - Heavy Density Generator, Natural Gas, 100 kW,	Vinyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps  AHU #3  AHU #2  AHU #1  Heat Pump System  Well Pump Controller  Well Pump Controller  Call for Aid Posts in Staff Parking  Central Fire Alarm Control Panel  Network distribution and control systems  Propane Generator Module, 100kW	B/C Wing  Basement/Crawl Spaces A Wing North Wing North Wing East Wing Geothermal Wells Geothermal Wells Basement/Crawl Spaces  Staff Parking Basement Mechanical Room Patient Mgt Stations & Central Records Outside B Wing	Repair 5% of Asset: Floor tile replacments  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.  Replace Well Pump Controller  Replace Air Compressor, Dry Pipe Sprinkler System  Replace Call for Aid Posts in Staff Parking Replace Central Fire Alarm Control Panel Replace Network distribution and control systems  Replace Propane Generator Module, 100kW	30 30 15 20 15 15 0 0 25 25	1 1 9 18 13 13 1 1 0 0 19 18 18 2 9 0 0 12	1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	EA E	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$1,500.00 \$3,43 \$1,679.09 \$5,500.00 \$12,114.90 \$1.28	IN - Appearance  C. INTERIORS  IN - Beyond Rated Life  IN - Beyond Rated Life	Priority 4  Priority 4  Priority 3  Priority 4  Priority 4  Priority 4  Priority 4  Priority 3  Priority 3  Priority 4  Priority 3  Priority 4  Priority 4  Priority 3  Priority 4  Priority 4  Priority 3  Priority 4  Priority 3  Priority 4  Priority 3  Priority 3	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$30,488 \$43,488 \$24,940 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$30,488 \$30,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$13,000 \$0 \$13,000 \$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0

Powered by iPlan™ iPlan Capital Expenditure Report - Version 4.3 1 11/14/2013 4:35 PM

					Estimated Useful																
Element No.	Component Description	Asset	Location	Action	Life or F Replacement Cycle (Yrs)	Remaining Useful Life (Yrs)	Quantity	Unit of Measurement	Unit Cost	Plan Type	Priority	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022
E1016	EQUIPMENT Commercial Washers 75 Lb	Commercial Washers	Laundry Room	Replace Commercial Washers	20	14	2.00	EA	\$25,295.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1016	Commercial Washers 50Lb	Commercial Washers	Laundry Room	Replace Commercial Washers	20	10	2.00	EA	\$13,312.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1028	E1028 Medical Equipment	Compressed oxygen control and manifold	Rear of B Wing	Replace Compressed oxygen control and	10	0	1.00	EA	\$5,000.00	IN - Beyond Rated Life	Priority 3	\$5,000	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	E1093 Food Service Equipment	Tilting Skillet	Central Kitchen	Replace Tilting Skillet	15	6	1.00		\$9,800.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$9,800	\$0	\$0	\$0
E1093	Fryer Floor Mounted Twin Baskets	Fryer Floor Mounted Twin Baskets	Central Kitchen	Replace Fryer Floor Mounted Twin Baskets	20	5	2.00	EA	\$2,846.76	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$5,694	\$0	\$0	\$0	\$0
E1093	Steam Table, Electric 5-Well	Steam Table, Electric 3-Well	Central Kitchen	Replace Steam Table, Electric 3-Well	20	11	2.00	EA	\$2,450.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	Ice Maker w/ Storage Bin	Ice Maker	Central Kitchen	Replace Ice Maker	15	7	1.00	EA	\$6,200.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$6,200	\$0	\$0
E1093	Griddle, Thermostatic Controls, 36" Wide ,	Griddle 48"		Replace Griddle 48"	20	9	2.00	EA	\$3,200.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$6,400
E1093	Electric E1093 Food Service Equipment	Cook hood with Fire Supression	Central Kitchen	Replace Cook hood with Fire Supression	25	8	4.00		\$5,685.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$22,740	\$0
E1093	Walk in Refrigerator 8'X8'	Walk in Refrigerator 8'X8'	Central Kitchen	Replace Walk in Refrigerator 8'X8'	20	8	1.00	EA	\$8,787.80	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$8,788	\$0
E1093	Kitchen Equipment Steamer Electric 27 kW	Skillet		Replace Skillet	20	3	1.00	EA	\$11,500.00	IN - Beyond Rated Life	Priority 3	\$0	\$0	\$0	\$11,500	\$0	\$0	\$0	\$0	\$0	\$0
E1093	E1093 Food Service Equipment	Vegatable Peeler	Central Kitchen	Replace Vegatable Peeler	15	4	1.00	EA	\$6,500.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$6,500	\$0	\$0	\$0	\$0	\$0
E1093	E1093 Food Service Equipment	Exhaust Hood 4 ft X 4 ft	Central Kitchen	Replace Exhaust Hood 4 ft X 4 ft	99	1	1.00		\$1.00	IN - Beyond Rated Life	Priority 3	\$0	\$1	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	E1093 Food Service Equipment	Thermal Food Delivery Carts	Central Kitchen	Replace Thermal Food Delivery Carts	15	7	12.00		\$4,500.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$54,000	\$0	\$0
E1093	Walk in Freezer 8'X12'				20	-		EA				\$0	\$0	\$0	\$0	\$0	\$0		\$0		
E1093		Walk in Freezer 6'X12'  Reach in Refrigerator 68 Cf	Central Kitchen Central Kitchen	Replace Walk in Freezer 6'X12'	15	6	1.00	EA EA	\$14,880.32 \$7,051.24	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0 \$0	\$0 \$0	\$0 \$7,051	\$0	\$14,880 \$0	\$0 \$0
	Reach in Refrigerator 68 Cf		+	Replace Reach in Refrigerator 68 Cf				EA		IN - Beyond Rated Life	Priority 4										
E1093	E1093 Food Service Equipment	Four Drawer Warmer	Central Kitchen	Replace Four Drawer Warmer	15	6	1.00		\$2,800.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$2,800	\$0	\$0	\$0
E1093	E1093 Food Service Equipment	Conveyor Dishwasher		Replace Conveyor Dishwasher	20	1	1.00		\$16,500.00	IN - Beyond Rated Life	Priority 3	\$0	\$16,500	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	Hobart Legacy, Mixer, Planetary, 60Qt.	Mixer	Central Kitchen	Replace Mixer	20	9	2.00	EA	\$12,478.99	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$24,958
E1093	Electric Convection Oven, Single Deck Stainless Steel Prep Table with Dual Reach in	Oven Stainless Steel Prep Table with Dual Reach in	Main Kitchen	Replace Oven  Replace Stainless Steel Prep Table with Dual	20	3	1.00	EA	\$5,412.96	IN - Beyond Rated Life	Priority 3	\$0	\$0	\$0	\$5,413	\$0	\$0	\$0	\$0	\$0	\$0
E1093	Refrigerators	Refrigerators	Central Kitchen	Reach in Refrigerators	20	12	1.00	EA	\$3,200.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	E1093 Food Service Equipment	3 Compartment Sink with Drain boards	Central Kitchen	Replace 3 Compartment Sink with Drain board	ds 20	3	3.00		\$1,475.00	IN - Beyond Rated Life	Priority 3	\$0	\$0	\$0	\$4,425	\$0	\$0	\$0	\$0	\$0	\$0
E1093	E1093 Food Service Equipment	Convection Steamer	Central Kitchen	Replace Convection Steamer	15	2	1.00	EA	\$12,800.00	IN - Beyond Rated Life	Priority 3	\$0	\$0	\$12,800	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	E1093 Food Service Equipment	Stove Broiler Oven Combo	Central Kitchen	Replace Stove Broiler Oven Combo	20	11	1.00		\$8,600.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	Reach in Freezer 44 Cf	Reach in Refrigerator 49CF		Replace Reach in Refrigerator 49CF	15	9	1.00	EA	\$4,108.13	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$4,108
E1093	Garbage Disposal-3HP Restaurant Type	Disposal Trough -1HP Custom	Central Kitchen	Replace Disposal Trough -1HP Custom	20	0	1.00	EA	\$12,500.00	IN - Beyond Rated Life	Priority 3	\$12,500	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E CRECIAL	ONSTRUCTION AND DEMOLITION								E. EQUIP	MENT & FURNISHING	SUB-TOTALS	\$17,500	\$16,501	\$12,800	\$21,338	\$6,500	\$5,694	\$19,651	\$60,200	\$46,408	\$35,466
F. SPECIAL	UNSTRUCTION AND DEMOLITION																				
C. PLUI PING	CITEMODY							F. SPECIA	AL CONSTRUCTION	ON AND DEMOLITION S	SUB-TOTALS	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G. BUILDING	SHEWORK																				
G20	SITE IMPROVEMENTS		_		1																
G2012	Asphalt Roadway-Without Base	Asphalt Swale Drive at Maintenance Service Drive	Drive between Laundry and Maintenance	Replace Asphalt Swale Drive at Maintenance Service Drive	20	1	98.00	SY	\$16.50	IN - Beyond Rated Life	Priority 3	\$0	\$1,617	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
	Asphalt, Mill 1.5" / Resurface 2.0" - Roadways	Asphalt Paved Drives and Parking	Front drive, visitor and south staff parking	d Cut & Patch Asphalt - full depth repairs as needed in conjunction with mill and	0	1	200.00	SF	\$2.38	OP - Maintenance	Priority 4	\$0	\$476	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2012	Asphalt, Mill 1.5" / Resurface 2.0" - Roadways	Asphalt Paved Drives and Parking	Front drive, visitor and	resurfacing  d Repair 100% of Asset: Asphalt paved roads, front and south rear parking	0	1	2,100.00	SY	\$16.70	OP - Maintenance	Priority 4	\$0	\$35,070	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
	Asphalt, Mill 1.5" / Resurface 2.0" - Roadways	Asphalt Paved Drives and Parking	Front drive, visitor and south staff parking		5	7	37,200.00	SF	\$0.50	OP - Maintenance	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$18,600	\$0	\$0
G2022	Driveway Asphalt Paving	Staff Parking Lot & Drives	Site northeast	Restripe Parking Lots	7	4	313.00	Stall	\$11.00	OP - Maintenance	Priority 4	\$0	\$0	\$0	\$0	\$3,443	\$0	\$0	\$0	\$0	\$0
G2041	Driveway Asphalt Paving Chain Link Fence, 6-Foot High	Staff Parking Lot & Drives Security Fence	Site northeast Wing C south	Seal Coat Asphalt (Up to 10000 SF)  Replace Security Fence	20	7	82,000.00 50.00	SF LF	\$0.50 \$29.61	OP - Maintenance IN - Beyond Rated Life	Priority 4 Priority 4	\$0 \$0	\$0 \$0	\$0 \$0	\$0 \$0	\$41,000 \$0	\$0 \$0	\$0 \$0	\$0 \$1,481	\$0 \$0	\$41,000 \$0
G2041	3-Foot High Chain Link Fence,	Chain link fence at East Boundary	Courtyard East site Boundry	Replace Chain link fence at East Boundary	30	10	960.00	LF	\$17.25	OP - Security	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2041	Install New Chain Link Fencing	Chain Link Fence	Boundry at Deer Park	Replace Chain Link Fence	30	1	880.00	LF	\$28.50	OP - Security	Priority 3	\$0	\$25,080	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2045	G2045 Site Furnishings	Smoker Den	Along east staff parking areas	Replace Smoker Den	15	0	2.00	EA	\$1,200.00	IN - Beyond Rated Life	Priority 3	\$2,400	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2052	Establishment of Ground Cover at Bare Areas	Landscape turf around building perimeter walls		Replace Landscape turf around building perimeter walls	25	0	35.00	CSF	\$985.00	IN - Beyond Rated Life	Priority 3	\$34,475	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G30	SITE CIVIL/MECHANICAL UTILITIES													1			1	1		T T	T
G3013	Well Pump 30 HP, 100 to 300 Gpm	Well Pump, 400GPM	Geothermal Wells	Replace Well Pump, 400GPM	25	19	2.00	EA	\$8,650.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G40	SITE ELECTRICAL UTILITIES			· 	1			I				I		I	I	I	I	I	I		<u> </u>
G4021	Landscape Ground Mounted Uplight Fixture Only	Convert Entry Flag Pole Lights to Grade LED	Along Entry Drive	Replace Convert Entry Flag Pole Lights to Grade LED	15	0	50.00	EA	\$785.00	IN - Beyond Rated Life	Priority 3	\$39,250	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
	1=A			10.000						BUILDING SITEWORK S	SUB-TOTAL S	\$76.125	\$62.243	\$0	\$0	\$44,443	\$0	S0	\$20,081	\$n	\$41,000
Z. GENERAL								ı	G.	D. DING SHEWORK	COLIGIALS	ψ10,123	<b>402,243</b>	<del>- 40</del>	40	ψ <del>τι, 140</del>	<del>- Ju</del>	φυ	<b>\$20,001</b>	Ψ	<b>\$41,000</b>
	I.	1	I	1	1			1	1			1	l	1	1	ı	L	1	1	L	1
										7 CENEDAL	SUB-TOTAL S	l ¢n	Fn -	Fn	F0	l ¢n	l en	l 60	l ¢n	¢n.	¢n.
										Z. GENERAL : Expenditure Totals per Ye Total Cost (Inflated @ 4%	ear	\$0 \$515,185 \$515,185	\$0 \$373,068 \$387,990	\$0 \$105,000 \$113,568	\$0 \$88,333 \$99,363	\$0 \$50,943 \$59,596	\$0 \$42,046 \$51,155	\$0 \$61,659 \$78,018	\$0 \$93,281 \$122,751	\$0 \$46,408 \$63,513	\$0 \$348,908 \$496,605

## 20 YEAR EXPENDITURE FORECAST

Vermont Veterans' Home 325 North Street Bennington, Vermont

Element No.	Component Description	Asset	Location	Action	Estimated Useful Life or	Remaining Useful	Quantity	Unit of	Unit Cost	Plan Type	Priority	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
					Replacement Cycle (Yrs)	e Life (Yrs)		Measurement				10	11	12	13	14	15	16	17	18	19
A. SUBSTRU	ICTURE											Scheduled	Scheduled	Scheduled	Scheduled	Scheduled	Scheduled	Scheduled	Scheduled	Scheduled	Scheduled
										A. SUBSTRUCTURE	SUID TOTALS	¢0	<b>\$0</b>	ė o	60	ėo.	¢0	60	ė0.	¢0	60
B. SHELL							T			A. SOBSTRUCTORE	- SOB-TOTALS	ŞŪ	30	30	<del>\$</del> 0	φU	<b>40</b>	<b>\$</b> 0	φU	φυ	φυ
B20	EXTERIOR ENCLOSURE		l										l								
B2011	Brick Veneer - Upper Floor Wood Siding	Brick Exteriors Vertical wood siding	Most exterior walls In-Service & Social Hal	Point Brick Exterior Walls where required  General Painting Cost Per SF, Minor Prep	10 10	5	20.00 675.00	CSF SF	\$948.00 \$1.41	OP - Maintenance OP - Maintenance	Priority 4 Priority 4	\$0 \$952	\$0 \$0	\$0 \$0	\$0 \$0	\$0 \$0	\$18,960 \$0	\$0 \$0	\$0 \$0	\$0 \$0	\$0 \$0
B2011	Wood Siding	Vertical wood siding		" Work, Up to 4-Story Bldg.  Il Replace Vertical wood siding	25	11	675.00	SF	\$12.68	IN - Beyond Rated Life	Priority 4	\$0	\$8,559	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D0044	EIFS with Stucco Over Cement Board	EIFS with Stucco Over Cement Board	North Village Wing	Color Coat 100% of Asset: EIFS	0	19	44.00	CSF	\$218.00	OP - Maintenance	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$9,592
B2011	EIFS with Stucco Over Cement Board	EIFS with Stucco Over Cement Board	North Village Wing	Repair 10% of Asset: EIFS with Stucco Over Cement Board	8	3	5.00	CSF	\$476.00	OP - Maintenance	Priority 4	\$0	\$2,380	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,380
B2011	Solid Wood Lap Siding	Wood Lap Siding and Trim	Origional Bldg and Mainte. Garage	Paint Existing Wood Siding and trim, One Coat, Spray with Medium Prep and Clean Up		2	5,200.00	SF	\$1.23	OP - Maintenance	Priority 4	\$0	\$0	\$6,396	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2011 B2011	Caulking, Polyurethane, 1/4"X1/4"  Solid Masonry	Caulk sealant at joints and openings  Brick Chimney	All exterior walls  Boiler Building	Replace Caulk sealant at joints and openings  Repair 100% of Asset: Brick Chimney	15 10	6	3,000.00 1.00	LF EA	\$3.84 \$25,000.00	OP - Maintenance OP - Maintenance	Priority 4 Priority 4	\$0 \$0	\$0 \$25,000	\$0 \$0	\$0 \$0	\$0 \$0	\$0 \$0	\$0 \$0	\$0 \$0	\$0 \$0	\$0 \$0
B2021	Aluminum Window , 4-0 X 6-0,First Floor	Corridor Windows	Corridor at Dining and Chapel		25	0	18.00	EA	\$1,276.99	IN - Beyond Rated Life	Priority 3	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2021	3' X 4' Aluminum Window Operable	Casement Windows	Administration and D wing	Replace Casement Windows	25	2	64.00	EA	\$911.00	IN - Beyond Rated Life	Priority 3	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2032	3'-0" X 7'-0" Steel, Insulated Core, Ptd. Door	Exterior Steel Doors	All entrances	Repair 8% of Asset: 3'-0" X 7'-0" Steel, Insulated Core, Ptd. Door	4	1	4.00	EA	\$1,098.00	IN - Reliability	Priority 3	\$0	\$0	\$0	\$4,392	\$0	\$0	\$0	\$4,392	\$0	\$0
B30 B3011	ROOFING Tpo, Roof 45 Mills, Full Adhered	TPO Poof on Entrance Dining and East William	Entrance, Dining and	Replace TPO Roof on Entrance, Dining and	20	0	250.00	80	\$74.4.00	IN - Dollahillar	Drigains 2	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3011	Wood Shingle , Historic Structure	TPO Roof on Entrance, Dining and East Wing Wood Roof Shingles	East Wing In-Service Social	East Wing Replace Wood Roof Shingles	25	15	250.00 25.00	SQ SQ	\$714.09 \$817.00	IN - Reliability  IN - Beyond Rated Life	Priority 3 Priority 4	\$0 \$0	\$0	\$0	\$0	\$0	\$20,425	\$0 \$0	\$0	\$0	\$0
B3011	Asphalt Shingles, Removal and with Premium Grade	Acabalt Shingles Original House	Building House, Boiler and Maintenance Buildngs	Poplace Asphalt Shingles Original House	30	3	120.00	sq	\$430.00	IN - Reliability	Priority 3	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3011	Tpo, Roof 45 Mills, Full Adhered	TPO Roofs on B. C and D Wings	B, C, & D Wings	Replace TPO Roofs on B. C and D Wings	20	19	250.00	SQ	\$714.09	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$178,523
B3011	Tpo, Roof 45 Mills, Full Adhered	TPO Roof North Wings		Replace TPO Roof North Wings	20	18	300.00	SQ	\$714.09	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$214,227	\$0
B3011	Tpo, Roof 45 Mills, Full Adhered	TPO Roof on A Wing and D Dayroom		Replace TPO Roof on A Wing and D Dayroom	99	18	300.00	SQ	\$1.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$300	\$0
B3021	Plexi-Glass Skylight to 10 SF	Plexi-Glass Skylights	Flat Roofs	Replace Plexi-Glass Skylights	20	17	25.00	EA	\$328.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$8,200	\$0	\$0
B3021	B3021 Glazed Roof Openings	Plexi-Glass Skylights	Flat Roofs	Replace Plexi-Glass Skylights	20	3	15.00	EA	\$1.00	IN - Beyond Rated Life	Priority 3	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C. INTERIOR	25									B. SHELL	L SUB-TOTALS	\$952	\$35,939	\$6,396	\$4,392	\$0	\$39,385	\$0	\$12,592	\$214,527	\$190,495
C10 C1021	INTERIOR CONSTRUCTION Automatic Accessible Door, Wood with Glass			I																	
	Panels	Automatic Accessible Door, Wood		Repair 2% of Asset: Automatic Accessible Door, Wood with Glass Panels	2	1	2.00	EA	\$6,500.00	OP - Maintenance	Priority 4	\$0	\$13,000	\$0	\$13,000	\$0	\$13,000	\$0	\$13,000	\$0	\$13,000
C30	Panels INTERIOR FINISHES		Throughout interiors	Door, Wood with Glass Panels	2	1								\$0	\$13,000	\$0	\$13,000		\$13,000	\$0	\$13,000
C30 C3024	Panels		Throughout interiors		5	1	2.00			IN - Appearance	Priority 4	\$0	\$30,488	\$0	\$0	\$0	\$0	\$30,488	\$0	\$0	\$0
C30 C3024 D. SERVICE	Panels  INTERIOR FINISHES  Vinyl Tile		Throughout interiors	Door, Wood with Glass Panels	5	1				IN - Appearance	Priority 4	\$0	\$30,488	\$0	\$0	\$0 \$0 \$0	\$0	\$30,488	\$0	\$0	\$0
	Panels INTERIOR FINISHES Vinyl Tile CONVEYING SYSTEMS	Vinyl Composition Floor Tiles		Door, Wood with Glass Panels  Repair 5% of Asset: Floor tile replacments	5	1	450.00	SY	\$67.75	IN - Appearance C. INTERIORS	Priority 4	\$0	\$30,488 \$43,488	\$0	\$0 \$13,000	\$0	\$0 \$13,000	\$30,488 \$30,488	\$0 \$13,000	\$0	\$0 \$13,000
	Panels INTERIOR FINISHES Vinyl Tile	Vinyl Composition Floor Tiles	Throughout interiors  B/C Wing	Door, Wood with Glass Panels	5 30	1				IN - Appearance	Priority 4	\$0	\$30,488	\$0	\$0	\$0	\$0	\$30,488	\$0	\$0	\$0
D. SERVICES D10 D1011 D30	Panels INTERIOR FINISHES Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC	Vinyl Composition Floor Tiles  Hydraulic Elevator, Small Cab		Door, Wood with Glass Panels  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab	30	1	1.00	SY EA	\$67.75 \$24,940.22	IN - Appearance  C. INTERIORS  IN - Beyond Rated Life	Priority 4  S SUB-TOTALS  Priority 3	\$0 \$0 \$0	\$30,488 \$43,488 \$43,000 \$0	\$0 \$0 \$0	\$0 \$13,000 \$0	\$0	\$0 \$13,000 \$0	\$30,488 \$30,488 \$30,488	\$0 \$13,000 \$0	\$0 \$0 \$0	\$0 \$13,000 \$0
D. SERVICE: D10 D1011 D30 D3022.1	Panels  INTERIOR FINISHES Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC Heating Water Distribution Pump 3 HP	Vinyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps	B/C Wing  Basement/Crawl Spaces	Door, Wood with Glass Panels  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps	30	1 1 9	1.00	EA EA	\$67.75 \$24,940.22 \$6,941.00	IN - Appearance  C. INTERIORS  IN - Beyond Rated Life  IN - Beyond Rated Life	Priority 4  S SUB-TOTALS  Priority 3  Priority 4	\$0 \$0 \$0 \$0	\$30,488 \$43,488 \$0 \$0	\$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0	\$0	\$0 \$13,000 \$0 \$0	\$30,488 \$30,488 \$0 \$0	\$0 \$13,000 \$0 \$0	\$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0
D. SERVICES D10 D1011 D30	Panels INTERIOR FINISHES Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC	Vinyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps  AHU #3	B/C Wing  Basement/Crawl Spaces A Wing	Door, Wood with Glass Panels  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab	30	1	1.00 35.00 1.00	SY EA	\$67.75 \$24,940.22	IN - Appearance C. INTERIORS IN - Beyond Rated Life IN - Beyond Rated Life IN - Beyond Rated Life	Priority 4  S SUB-TOTALS  Priority 3  Priority 4  Priority 4	\$0 \$0 \$0	\$30,488 \$43,488 \$43,000 \$0	\$0 \$0 \$0	\$0 \$13,000 \$0	\$0	\$0 \$13,000 \$0	\$30,488 \$30,488 \$30,488	\$0 \$13,000 \$0	\$0 \$0 \$0	\$0 \$13,000 \$0
D. SERVICE: D10 D1011 D30 D3022.1 D3041.1	Panels  INTERIOR FINISHES Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC Heating Water Distribution Pump 3 HP Air Handler 4,000 to 8,000 CFM	Vinyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps	B/C Wing  Basement/Crawl Spaces	Door, Wood with Glass Panels  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps  Replace AHU #3	30 30 15 20	1 1 9 9 18	1.00	EA EA EA	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00	IN - Appearance  C. INTERIORS  IN - Beyond Rated Life  IN - Beyond Rated Life	Priority 4  S SUB-TOTALS  Priority 3  Priority 4  Priority 4  Priority 4	\$0 \$0 \$0 \$0 \$0 \$0	\$30,488 \$43,488 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0	\$30,488 \$30,488 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$4,780	\$0 \$13,000 \$0 \$0 \$0
D. SERVICES D10 D1011 D30 D3022.1 D3041.1	Panels  INTERIOR FINISHES  Vinyl Tile  CONVEYING SYSTEMS  Elevator Hydraulic System, 3,500 Lb Capacity  HVAC  Heating Water Distribution Pump 3 HP  Air Handler 4,000 to 8,000 CFM  Air Handler 2500-3000 CFM	Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3 AHU #2	B/C Wing  Basement/Crawl Spaces A Wing North Wing	Door, Wood with Glass Panels  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #2  Replace AHU #1  Expand heat pump system into East Wing to	30 30 15 20 15	1 1 9 18 13	1.00 1.00 35.00 1.00	EA EA EA EA	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00	IN - Appearance C. INTERIORS IN - Beyond Rated Life	Priority 4  S SUB-TOTALS  Priority 3  Priority 4  Priority 4  Priority 4	\$0 \$0 \$0 \$0 \$0 \$0 \$0	\$30,488 \$43,488 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$3,204	\$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0 \$0	\$30,488 \$30,488 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$4,780 \$0	\$0 \$13,000 \$0 \$0 \$0 \$0
D. SERVICES D10 D1011 D30 D3022.1 D3041.1 D3041.1 D3041.1	Panels  INTERIOR FINISHES  Vinyl Tile  CONVEYING SYSTEMS  Elevator Hydraulic System, 3,500 Lb Capacity  HVAC  Heating Water Distribution Pump 3 HP  Air Handler 4,000 to 8,000 CFM  Air Handler 2500-3000 CFM  Air Handler 3600-3800 CFM	Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3 AHU #1	B/C Wing  Basement/Crawl Spaces A Wing  North Wing  North Wing	Door, Wood with Glass Panels  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #2  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to	30 30 15 20 15	1 1 9 18 13 13	1.00 1.00 35.00 1.00 1.00	EA EA EA EA EA	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$6,233.00	IN - Appearance  C. INTERIORS  IN - Beyond Rated Life	Priority 4  S SUB-TOTALS  Priority 3  Priority 4  Priority 4  Priority 4  Priority 4	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$30,488 \$43,488 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0 \$3,204 \$6,233	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0	\$30,488 \$30,488 \$0 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$4,780 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0
D. SERVICE: D10 D1011 D30 D3022.1 D3041.1 D3041.1	Panels  INTERIOR FINISHES  Vinyl Tile  CONVEYING SYSTEMS  Elevator Hydraulic System, 3,500 Lb Capacity  HVAC  Heating Water Distribution Pump 3 HP  Air Handler 4,000 to 8,000 CFM  Air Handler 2500-3000 CFM  Air Handler 3600-3800 CFM  Heat Pump Water Source, 4-Ton	Winyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3  AHU #2  AHU #1  Heat Pump System	B/C Wing  Basement/Crawl Spaces A Wing North Wing North Wing East Wing	Door, Wood with Glass Panels  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #2  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project	30 30 15 20 15 15	1 1 9 18 13 13	1.00 1.00 35.00 1.00 1.00 1.00	EA EA EA LS	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$6,233.00 \$140,300.00	IN - Appearance  C. INTERIORS  IN - Beyond Rated Life  FN - Modernization	Priority 4  Priority 3  Priority 4  Priority 4  Priority 4  Priority 4  Priority 4  Priority 3	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$30,488 \$43,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0 \$3,204 \$6,233 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0	\$30,488 \$30,488 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$4,780 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0
D. SERVICE: D10 D1011 D30 D3022.1 D3041.1 D3041.1 D3041.1	Panels  INTERIOR FINISHES  Vinyl Tile  CONVEYING SYSTEMS  Elevator Hydraulic System, 3,500 Lb Capacity  HVAC  Heating Water Distribution Pump 3 HP  Air Handler 4,000 to 8,000 CFM  Air Handler 2500-3000 CFM  Air Handler 3600-3800 CFM  Heat Pump Water Source, 4-Ton  D3069 Other Controls & Instrumentation  D3069 Other Controls & Instrumentation  FIRE PROTECTION SYSTEMS	Vinyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps  AHU #3  AHU #2  AHU #1  Heat Pump System  Well Pump Controller  Well Pump Controller	B/C Wing  Basement/Crawl Spaces A Wing North Wing North Wing East Wing Geothermal Wells Geothermal Wells	Repair 5% of Asset: Floor tile replacments  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #2  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.  Replace Well Pump Controller	30 30 15 20 15 15 0 0	1 1 9 18 13 13 1 1 0	1.00 1.00 35.00 1.00 1.00 1.00 1.00 1.00	EA EA EA LS EA EA	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$6,233.00 \$140,300.00 \$1,500.00 \$3.43	IN - Appearance  C. INTERIORS  IN - Beyond Rated Life  FN - Modernization  IN - Reliability  IN - Beyond Rated Life	Priority 4  S SUB-TOTALS  Priority 3  Priority 4  Priority 4  Priority 4  Priority 4  Priority 3  Priority 3  Priority 3	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$30,488 \$43,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$13,000 \$0 \$0 \$3,204 \$6,233 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$30,488 \$30,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$4,780 \$0 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
D. SERVICE: D10 D1011 D30 D3022.1 D3041.1 D3041.1 D3041.1	Panels  INTERIOR FINISHES  Vinyl Tile  CONVEYING SYSTEMS  Elevator Hydraulic System, 3,500 Lb Capacity  HVAC  Heating Water Distribution Pump 3 HP  Air Handler 4,000 to 8,000 CFM  Air Handler 2500-3000 CFM  Air Handler 3600-3800 CFM  Heat Pump Water Source, 4-Ton  D3069 Other Controls & Instrumentation  D3069 Other Controls & Instrumentation  FIRE PROTECTION SYSTEMS	Vinyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3 AHU #2 AHU #1 Heat Pump System Well Pump Controller	B/C Wing  Basement/Crawl Spaces A Wing North Wing North Wing East Wing Geothermal Wells	Repair 5% of Asset: Floor tile replacments  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #2  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.	30 30 15 20 15 15 0	1 1 9 18 13 13 13 1 0 0	1.00 1.00 35.00 1.00 1.00 1.00	EA EA EA LS EA	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$6,233.00 \$140,300.00 \$1,500.00	IN - Appearance  C. INTERIORS  IN - Beyond Rated Life  IN - Modernization  IN - Reliability	Priority 4  S SUB-TOTALS  Priority 3  Priority 4  Priority 4  Priority 4  Priority 4  Priority 3  Priority 3  Priority 3	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$30,488 \$43,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$13,000 \$0 \$0 \$0 \$3,204 \$6,233 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$30,488 \$30,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$4,780 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0
D. SERVICE D10 D1011 D30 D3022.1 D3041.1 D3041.1 D3051.1 D3069	Panels  INTERIOR FINISHES  Vinyl Tile  CONVEYING SYSTEMS  Elevator Hydraulic System, 3,500 Lb Capacity  HVAC  Heating Water Distribution Pump 3 HP  Air Handler 4,000 to 8,000 CFM  Air Handler 2500-3000 CFM  Air Handler 3600-3800 CFM  Heat Pump Water Source, 4-Ton  D3069 Other Controls & Instrumentation  D3069 Other Controls & Instrumentation  FIRE PROTECTION SYSTEMS  Air Compressor for Dry Pipe System 520 Gal, 1HP  ELECTRICAL SYSTEMS  Gall for Aid System with Central Monitoring	Winyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3 AHU #2 AHU #1 Heat Pump System  Well Pump Controller  Well Pump Controller  Air Compressor, Dry Pipe Sprinkler System	B/C Wing  Basement/Crawl Spaces A Wing North Wing North Wing East Wing Geothermal Wells Geothermal Wells Basement/Crawl	Door, Wood with Glass Panels  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #2  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.  Replace Well Pump Controller  Replace Air Compressor, Dry Pipe Sprinkler	30 30 15 20 15 15 0 0	1 1 9 18 13 13 1 1 0	1.00 1.00 35.00 1.00 1.00 1.00 1.00 1.00	EA EA EA LS EA EA	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$6,233.00 \$140,300.00 \$1,500.00 \$3.43	IN - Appearance  C. INTERIORS  IN - Beyond Rated Life  FN - Modernization  IN - Reliability  IN - Beyond Rated Life	Priority 4  Priority 4  Priority 4  Priority 4  Priority 4  Priority 4  Priority 3  Priority 3  Priority 3  Priority 4  Priority 4  Priority 4  Priority 4  Priority 4	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$30,488 \$43,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$13,000 \$0 \$0 \$3,204 \$6,233 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$30,488 \$30,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$4,780 \$0 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
D. SERVICES  D10  D1011  D30  D3022.1  D3041.1  D3041.1  D3051.1  D3069  D40  D4011	Panels  INTERIOR FINISHES  Vinyl Tile  CONVEYING SYSTEMS  Elevator Hydraulic System, 3,500 Lb Capacity  HVAC  Heating Water Distribution Pump 3 HP  Air Handler 4,000 to 8,000 CFM  Air Handler 2500-3000 CFM  Air Handler 3600-3800 CFM  Heat Pump Water Source, 4-Ton  D3069 Other Controls & Instrumentation  D3069 Other Controls & Instrumentation  FIRE PROTECTION SYSTEMS  Air Compressor for Dry Pipe System 520 Gal, 11HP  ELECTRICAL SYSTEMS	Winyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3 AHU #2 AHU #1 Heat Pump System  Well Pump Controller  Well Pump Controller  Air Compressor, Dry Pipe Sprinkler System	B/C Wing  Basement/Crawl Spaces A Wing North Wing North Wing East Wing Geothermal Wells Geothermal Wells Basement/Crawl Spaces	Door, Wood with Glass Panels  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.  Replace Well Pump Controller  Replace Air Compressor, Dry Pipe Sprinkler System	5 30 30 15 20 15 15 0 0 25	1 9 18 13 13 1 0 19	1.00 35.00 1.00 1.00 1.00 1.00 1.00 1.00	EA EA EA EA EA EA EA EA EA	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$6,233.00 \$140,300.00 \$1,500.00 \$3,43	IN - Appearance  C. INTERIORS  IN - Beyond Rated Life  FN - Modernization  IN - Reliability  IN - Beyond Rated Life  IN - Beyond Rated Life	Priority 4  S SUB-TOTALS  Priority 3  Priority 4  Priority 4  Priority 4  Priority 3  Priority 3  Priority 3  Priority 4  Priority 4  Priority 4  Priority 4  Priority 3	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$30,488 \$43,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$13,000 \$0 \$0 \$3,204 \$6,233 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$30,488 \$30,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$4,780 \$0 \$0 \$0 \$0 \$1,679	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
D. SERVICE  D10  D1011  D30  D3022.1  D3041.1  D3041.1  D3051.1  D3069  D40  D4011  D50  D5034	Panels  INTERIOR FINISHES  Vinyl Tile  CONVEYING SYSTEMS  Elevator Hydraulic System, 3,500 Lb Capacity  HVAC  Heating Water Distribution Pump 3 HP  Air Handler 4,000 to 8,000 CFM  Air Handler 2500-3000 CFM  Air Handler 3600-3800 CFM  Heat Pump Water Source, 4-Ton  D3069 Other Controls & Instrumentation  D3069 Other Controls & Instrumentation  FIRE PROTECTION SYSTEMS  Air Compressor for Dry Pipe System 520 Gal, 1HP  ELECTRICAL SYSTEMS  Call for Aid System with Central Monitoring Capability	Vinyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3  AHU #2  AHU #1  Heat Pump System  Well Pump Controller  Well Pump Controller  Air Compressor, Dry Pipe Sprinkler System  Call for Aid Posts in Staff Parking	B/C Wing  Basement/Crawl Spaces A Wing North Wing North Wing East Wing Geothermal Wells Geothermal Wells Basement/Crawl Spaces Staff Parking Basement Mechanical Room	Replace Hydraulic Elevator, Small Cab  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.  Replace Well Pump Controller  Replace Air Compressor, Dry Pipe Sprinkler System  Replace Call for Aid Posts in Staff Parking	5 30 30 15 20 15 15 0 0 25	1 9 18 13 13 1 0 19	1.00 35.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	EA EA EA EA EA EA EA EA	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$140,300.00 \$1,500.00 \$3,43	IN - Appearance  C. INTERIORS  IN - Beyond Rated Life  FN - Modernization  IN - Reliability  IN - Beyond Rated Life  IN - Beyond Rated Life  IN - Beyond Rated Life	Priority 4  Priority 3  Priority 4  Priority 4  Priority 4  Priority 3  Priority 3  Priority 3  Priority 4  Priority 4  Priority 4  Priority 3  Priority 4  Priority 4  Priority 4	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$30,488 \$43,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$13,000 \$0 \$0 \$3,204 \$6,233 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$30,488 \$30,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$4,780 \$0 \$0 \$0 \$0 \$0 \$1,679	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
D. SERVICE  D10  D101  D30  D3022.1  D3041.1  D3041.1  D3051.1  D3069  D40  D4011  D50  D5034  D5037	Panels  INTERIOR FINISHES  Vinyl Tile  CONVEYING SYSTEMS  Elevator Hydraulic System, 3,500 Lb Capacity  HVAC  Heating Water Distribution Pump 3 HP  Air Handler 4,000 to 8,000 CFM  Air Handler 2500-3000 CFM  Air Handler 3600-3800 CFM  Heat Pump Water Source, 4-Ton  D3069 Other Controls & Instrumentation  D3069 Other Controls & Instrumentation  FIRE PROTECTION SYSTEMS  Air Compressor for Dry Pipe System 520 Gal, 1HP  ELECTRICAL SYSTEMS  Call for Aid System with Central Monitoring Capability  Fire Alarm Panel Addressable, with Voice	Vinyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3  AHU #2  AHU #1  Heat Pump System  Well Pump Controller  Well Pump Controller  Call for Aid Posts in Staff Parking  Central Fire Alarm Control Panel	B/C Wing  Basement/Crawl Spaces A Wing North Wing North Wing East Wing Geothermal Wells Geothermal Wells Spaces  Staff Parking Basement Mechanical Room	Replace Hydraulic Elevator, Small Cab  Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.  Replace Well Pump Controller  Replace Call for Aid Posts in Staff Parking Replace Call for Aid Posts in Staff Parking Replace Central Fire Alarm Control Panel Replace Network distribution and control	5 30 30 15 20 15 15 0 0 25 20 15 15	1 1 1 9 18 13 13 1 0 19 18 2 9	1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	EA	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$1,500.00 \$1,500.00 \$3,43	IN - Appearance  C. INTERIORS  IN - Beyond Rated Life  FN - Modernization  IN - Reliability  IN - Beyond Rated Life	Priority 4  Priority 3  Priority 4  Priority 4  Priority 4  Priority 3  Priority 3  Priority 4  Priority 4  Priority 3  Priority 4  Priority 4  Priority 4  Priority 4  Priority 4  Priority 4  Priority 3	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$30,488 \$43,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$13,000 \$0 \$0 \$0 \$3,204 \$6,233 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$30,488 \$30,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$4,780 \$0 \$0 \$0 \$0 \$1,679	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
D. SERVICE  D10 D1011  D30 D3022.1 D3041.1 D3041.1 D3051.1  D3069  D40 D4011  D50 D5034 D5037 D5039	Panels  INTERIOR FINISHES  Vinyl Tile  CONVEYING SYSTEMS  Elevator Hydraulic System, 3,500 Lb Capacity  HVAC  Heating Water Distribution Pump 3 HP  Air Handler 4,000 to 8,000 CFM  Air Handler 2500-3000 CFM  Air Handler 3600-3800 CFM  Heat Pump Water Source, 4-Ton  D3069 Other Controls & Instrumentation  D3069 Other Controls & Instrumentation  FIRE PROTECTION SYSTEMS  Air Compressor for Dry Pipe System 520 Gal, 1HP  ELECTRICAL SYSTEMS  Call for Aid System with Central Monitoring Capability  Fire Alarm Panel Addressable, with Voice  LAN System - Heavy Density	Vinyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3 AHU #2 AHU #1 Heat Pump System Well Pump Controller Well Pump Controller Call for Aid Posts in Staff Parking Central Fire Alarm Control Panel Network distribution and control systems	B/C Wing  Basement/Crawl Spaces A Wing North Wing North Wing East Wing Geothermal Wells Geothermal Wells Basement/Crawl Spaces  Staff Parking Basement Mechanical Room Patient Mgt Stations & Central Records	Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.  Replace AHI Ump Controller  Replace Air Compressor, Dry Pipe Sprinkler System  Replace Central Fire Alarm Control Panel Replace Central Fire Alarm Control Panel Replace Network distribution and control systems	5 30 30 15 20 15 15 0 0 25 20 15 15 15 15	1 1 1 9 18 13 13 10 19 18 18	1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	EA E	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$140,300.00 \$1,500.00 \$3,43 \$1,679.09 \$5,500.00 \$12,114.90 \$1.28	IN - Appearance  C. INTERIORS  IN - Beyond Rated Life	Priority 4  Priority 3  Priority 4  Priority 4  Priority 4  Priority 3  Priority 3  Priority 4  Priority 4  Priority 3  Priority 4  Priority 4  Priority 4  Priority 4  Priority 4  Priority 4  Priority 3	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$30,488 \$43,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$13,000 \$0 \$0 \$0 \$3,204 \$6,233 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$30,488 \$30,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$4,780 \$0 \$0 \$0 \$0 \$0 \$1,679	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
D. SERVICE D10 D1011 D30 D3022.1 D3041.1 D3041.1 D3041.1 D3051.1 D3069 D40 D4011 D50 D5034 D5037 D5039 D5092 D5092	Panels  INTERIOR FINISHES  Vinyl Tile  CONVEYING SYSTEMS  Elevator Hydraulic System, 3,500 Lb Capacity  HVAC  Heating Water Distribution Pump 3 HP  Air Handler 4,000 to 8,000 CFM  Air Handler 2500-3000 CFM  Air Handler 3600-3800 CFM  Heat Pump Water Source, 4-Ton  D3069 Other Controls & Instrumentation  FIRE PROTECTION SYSTEMS  Air Compressor for Dry Pipe System 520 Gal, 1HP  ELECTRICAL SYSTEMS  Call for Aid System with Central Monitoring Capability  Fire Alarm Panel Addressable, with Voice  LAN System - Heavy Density  Generator, Natural Gas, 100 kW,  Diesel Generator, 45 kW	Vinyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps  AHU #3  AHU #1  Heat Pump System  Well Pump Controller  Well Pump Controller  Call for Aid Posts in Staff Parking  Central Fire Alarm Control Panel  Network distribution and control systems  Propane Generator Module, 100kW	B/C Wing  Basement/Crawl Spaces A Wing North Wing North Wing East Wing Geothermal Wells Geothermal Wells Basement/Crawl Spaces Staff Parking Basement Mechanical Room Room Central Records Outside B Wing	Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.  Replace Well Pump Controller  Replace Call for Aid Posts in Staff Parking Replace Central Fire Alarm Control Panel Replace Network distribution and control systems  Replace Network distribution and control systems  Replace Propane Generator Module, 100kW	5 30 30 15 20 15 15 0 0 25 25 20 15 15 15 15 30	1  1  9  18  13  13  1  0  19  18  2  9  0  12	1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	EA E	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$1,500.00 \$1,500.00 \$5,500.00 \$12,114.90 \$1.28	IN - Appearance  C. INTERIORS  IN - Beyond Rated Life  IN - Beyond Rated Life	Priority 4  Priority 3  Priority 4  Priority 4  Priority 4  Priority 3  Priority 3  Priority 3  Priority 4  Priority 3  Priority 4  Priority 4  Priority 4  Priority 4  Priority 4  Priority 4  Priority 3  Priority 4  Priority 3  Priority 4  Priority 4	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$30,488 \$43,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$13,000 \$0 \$0 \$0 \$3,204 \$6,233 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$30,488 \$30,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$4,780 \$0 \$0 \$0 \$0 \$0 \$0 \$1,679	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
D. SERVICE  D10 D1011  D30 D3022.1 D3041.1 D3041.1 D3051.1  D3051.1  D3069  D40 D4011  D50 D5034 D5037 D5039 D5092 D5092	Panels  INTERIOR FINISHES  Vinyl Tile  CONVEYING SYSTEMS  Elevator Hydraulic System, 3,500 Lb Capacity  HVAC  Heating Water Distribution Pump 3 HP  Air Handler 4,000 to 8,000 CFM  Air Handler 2500-3000 CFM  Air Handler 3600-3800 CFM  Heat Pump Water Source, 4-Ton  D3069 Other Controls & Instrumentation  FIRE PROTECTION SYSTEMS  Air Compressor for Dry Pipe System 520 Gal, 11HP  ELECTRICAL SYSTEMS  Call for Aid System with Central Monitoring Capability  Fire Alarm Panel Addressable, with Voice  LAN System - Heavy Density  Generator, Natural Gas, 100 kW,	Vinyl Composition Floor Tiles  Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps  AHU #3  AHU #1  Heat Pump System  Well Pump Controller  Well Pump Controller  Call for Aid Posts in Staff Parking  Central Fire Alarm Control Panel  Network distribution and control systems  Propane Generator Module, 100kW	B/C Wing  Basement/Crawl Spaces A Wing North Wing North Wing East Wing Geothermal Wells Geothermal Wells Basement/Crawl Spaces Staff Parking Basement Mechanical Room Room Central Records Outside B Wing	Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.  Replace Well Pump Controller  Replace Call for Aid Posts in Staff Parking Replace Central Fire Alarm Control Panel Replace Network distribution and control systems  Replace Network distribution and control systems  Replace Propane Generator Module, 100kW	5 30 30 15 20 15 15 0 0 25 25 20 15 15 15 15 30	1  1  9  18  13  13  1  0  19  18  2  9  0  12	1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	EA E	\$67.75 \$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$1,500.00 \$1,500.00 \$5,500.00 \$12,114.90 \$1.28	IN - Appearance  C. INTERIORS  IN - Beyond Rated Life  IN - Beyond Rated Life	Priority 4  Priority 4  Priority 4  Priority 4  Priority 4  Priority 4  Priority 3  Priority 3  Priority 4  Priority 4  Priority 3  Priority 4  Priority 4  Priority 4  Priority 3  Priority 4  Priority 3  Priority 4  Priority 3  Priority 4  Priority 3  Priority 3  Priority 4  Priority 3	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$30,488 \$43,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$13,000 \$0 \$0 \$0 \$3,204 \$6,233 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$30,488 \$30,488 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$1,679 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$13,000 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0

Powered by iPlan™ iPlan Capital Expenditure Report - Version 4.3 3 11/14/2013 4:35 PM

					Father at addition of all																
Element No.	Component Description	Asset	Location	Action	Estimated Useful Life or Replacement Cycle (Yrs)	Remaining Useful Life (Yrs)	Quantity	Unit of Measurement	Unit Cost	Plan Type	Priority	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
E10	EQUIPMENT				(1.5)																
E1016	Commercial Washers 75 Lb	Commercial Washers	Laundry Room	Replace Commercial Washers	20	14	2.00	EA	\$25,295.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$50,590	\$0	\$0	\$0	\$0	\$0
E1016	Commercial Washers 50Lb	Commercial Washers	Laundry Room	Replace Commercial Washers  Replace Compressed oxygen control and	20	10	2.00	EA	\$13,312.00	IN - Beyond Rated Life	Priority 4	\$26,624	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1028	E1028 Medical Equipment	Compressed oxygen control and manifold	Rear of B Wing	manifold	10	0	1.00	EA	\$5,000.00	IN - Beyond Rated Life	Priority 3	\$5,000	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	E1093 Food Service Equipment	Tilting Skillet	Central Kitchen	Replace Tilting Skillet	15	6	1.00		\$9,800.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	Fryer Floor Mounted Twin Baskets	Fryer Floor Mounted Twin Baskets	Central Kitchen	Replace Fryer Floor Mounted Twin Baskets	20	5	2.00	EA	\$2,846.76	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	Steam Table, Electric 5-Well	Steam Table, Electric 3-Well	Central Kitchen	Replace Steam Table, Electric 3-Well	20	11	2.00	EA	\$2,450.00	IN - Beyond Rated Life	Priority 4	\$0	\$4,900	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	Ice Maker w/ Storage Bin	Ice Maker	Central Kitchen	Replace Ice Maker	15	7	1.00	EA	\$6,200.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	Griddle, Thermostatic Controls, 36" Wide , Electric	Griddle 48"		Replace Griddle 48"	20	9	2.00	EA	\$3,200.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	E1093 Food Service Equipment	Cook hood with Fire Supression	Central Kitchen	Replace Cook hood with Fire Supression	25	8	4.00		\$5,685.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	Walk in Refrigerator 8'X8'	Walk in Refrigerator 8'X8'	Central Kitchen	Replace Walk in Refrigerator 8'X8'	20	8	1.00	EA	\$8,787.80	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	Kitchen Equipment Steamer Electric 27 kW	Skillet		Replace Skillet	20	3	1.00	EA	\$11,500.00	IN - Beyond Rated Life	Priority 3	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	E1093 Food Service Equipment	Vegatable Peeler	Central Kitchen	Replace Vegatable Peeler	15	4	1.00	EA	\$6,500.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$6,500
E1093	E1093 Food Service Equipment	Exhaust Hood 4 ft X 4 ft	Central Kitchen	Replace Exhaust Hood 4 ft X 4 ft	99	1	1.00		\$1.00	IN - Beyond Rated Life	Priority 3	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	E1093 Food Service Equipment	Thermal Food Delivery Carts	Central Kitchen	Replace Thermal Food Delivery Carts	15	7	12.00		\$4,500.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	Walk in Freezer 8'X12'	Walk in Freezer 6'X12'	Central Kitchen	Replace Walk in Freezer 6'X12'	20	8	1.00	EA	\$14,880.32	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	Reach in Refrigerator 68 Cf	Reach in Refrigerator 68 Cf	Central Kitchen	Replace Reach in Refrigerator 68 Cf	15	6	1.00	EA	\$7,051.24	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	E1093 Food Service Equipment	Four Drawer Warmer	Central Kitchen	Replace Four Drawer Warmer	15	6	1.00		\$2,800.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	E1093 Food Service Equipment	Conveyor Dishwasher		Replace Conveyor Dishwasher	20	1	1.00		\$16,500.00	IN - Beyond Rated Life	Priority 3	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	Hobart Legacy, Mixer, Planetary, 60Qt.	Mixer	Central Kitchen	Replace Mixer	20	9	2.00	EA	\$12,478.99	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	Electric Convection Oven, Single Deck	Oven	Main Kitchen	Replace Oven	20	3	1.00	EA	\$5,412.96	IN - Beyond Rated Life	Priority 3	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	Stainless Steel Prep Table with Dual Reach in Refrigerators	Stainless Steel Prep Table with Dual Reach in Refrigerators	Central Kitchen	Replace Stainless Steel Prep Table with Dual Reach in Refrigerators	20	12	1.00	EA	\$3,200.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$3,200	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	E1093 Food Service Equipment	3 Compartment Sink with Drain boards	Central Kitchen	Replace 3 Compartment Sink with Drain boards	20	3	3.00		\$1,475.00	IN - Beyond Rated Life	Priority 3	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	E1093 Food Service Equipment	Convection Steamer	Central Kitchen	Replace Convection Steamer	15	2	1.00	EA	\$12,800.00	IN - Beyond Rated Life	Priority 3	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$12,800	\$0	\$0
E1093	E1093 Food Service Equipment	Stove Broiler Oven Combo	Central Kitchen	Replace Stove Broiler Oven Combo	20	11	1.00		\$8,600.00	IN - Beyond Rated Life	Priority 4	\$0	\$8,600	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	Reach in Freezer 44 Cf	Reach in Refrigerator 49CF		Replace Reach in Refrigerator 49CF	15	9	1.00	EA	\$4,108.13	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1093	Garbage Disposal-3HP Restaurant Type	Disposal Trough -1HP Custom	Central Kitchen	Replace Disposal Trough -1HP Custom	20	0	1.00	EA	\$12,500.00	IN - Beyond Rated Life	Priority 3	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
				·					E. EQUI	PMENT & FURNISHING	SUB-TOTALS	\$31.624	\$13,500	\$3,200	\$0	\$50,590	\$0	\$0	\$12,800	\$0	\$6.500
F. SPECIAL	CONSTRUCTION AND DEMOLITION		1		I																
								F. SPECIA	AL CONSTRUCT	TION AND DEMOLITION	SUB-TOTALS	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G. BUILDING	SITEWORK				I																
G20	SITE IMPROVEMENTS				T											1					
G2012	Asphalt Roadway-Without Base	Asphalt Swale Drive at Maintenance Service Drive	Drive between Launc and Maintenance	Iry Replace Asphalt Swale Drive at Maintenance Service Drive	20	1	98.00	SY	\$16.50	IN - Beyond Rated Life	Priority 3	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
	Asphalt, Mill 1.5" / Resurface 2.0" - Roadways	Asphalt Paved Drives and Parking	Front drive, visitor as	needed in conjunction with mill and	0	1	200.00	SF	\$2.38	OP - Maintenance	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2012	Asphalt, Mill 1.5" / Resurface 2.0" - Roadways	Asphalt Paved Drives and Parking	Front drive, visitor a	resurfacing  nd Repair 100% of Asset: Asphalt paved roads,	0	1	2,100.00	SY	\$16.70	OP - Maintenance	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
			Front drive, visitor a	front and south rear parking  Ind Seal Coat Asphalt (Up to 10000 SF)	5	7	37,200.00	SF	\$0.50	OP - Maintenance	Priority 4	\$0	\$0	\$18,600	\$0	\$0	\$0	\$0	\$18,600	\$0	\$0
G2022	Driveway Asphalt Paving	Staff Parking Lot & Drives	south staff parking Site northeast	Restripe Parking Lots	7	4	313.00	Stall	\$11.00	OP - Maintenance	Priority 4	\$0	\$3,443	\$0	\$0	\$0	\$0	\$0	\$0	\$3,443	\$0
G2041	Driveway Asphalt Paving Chain Link Fence, 6-Foot High	Staff Parking Lot & Drives Security Fence	Site northeast Wing C south	Seal Coat Asphalt (Up to 10000 SF)  Replace Security Fence	5 20	7	82,000.00 50.00	SF LF	\$0.50 \$29.61	OP - Maintenance IN - Beyond Rated Life	Priority 4 Priority 4	\$0 \$0	\$0 \$0	\$0 \$0	\$0 \$0	\$41,000 \$0	\$0 \$0	\$0 \$0	\$0 \$0	\$0 \$0	\$41,000 \$0
G2041	3-Foot High Chain Link Fence,	Chain link fence at East Boundary	Courtyard East site Boundry	Replace Chain link fence at East Boundary	30	10	960.00	LF	\$17.25	OP - Security	Priority 4	\$16,560	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2041	Install New Chain Link Fencing	Chain Link Fence		Replace Chain Link Fence	30	1	880.00	LF	\$28.50	OP - Security	Priority 3	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2045	G2045 Site Furnishings	Smoker Den	Along east staff parking areas	Replace Smoker Den	15	0	2.00	EA	\$1,200.00	IN - Beyond Rated Life	Priority 3	\$0	\$0	\$0	\$0	\$0	\$2,400	\$0	\$0	\$0	\$0
G2052	Establishment of Ground Cover at Bare Areas	Landscape turf around building perimeter wal	Is Bulding perimeters	Replace Landscape turf around building perimeter walls	25	0	35.00	CSF	\$985.00	IN - Beyond Rated Life	Priority 3	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G30	SITE CIVIL/MECHANICAL UTILITIES																				
G3013	Well Pump 30 HP, 100 to 300 Gpm	Well Pump, 400GPM	Geothermal Wells	Replace Well Pump, 400GPM	25	19	2.00	EA	\$8,650.00	IN - Beyond Rated Life	Priority 4	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$17,300
G40	SITE ELECTRICAL UTILITIES																				
G4021	Landscape Ground Mounted Uplight Fixture Only	Convert Entry Flag Pole Lights to Grade LED	Along Entry Drive	Replace Convert Entry Flag Pole Lights to Grade LED	15	0	50.00	EA	\$785.00	IN - Beyond Rated Life	Priority 3	\$0	\$0	\$0	\$0	\$0	\$39,250	\$0	\$0	\$0	\$0
									G	BUILDING SITEWORK	SUB-TOTALS	\$16,560	\$3,443	\$18,600	\$0	\$41,000	\$41,650	\$0	\$18,600	\$3,443	\$58,300
Z. GENERAL																					
				·						Z. GENERAL	SUB-TOTALS	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
										Expenditure Totals per Y Total Cost (Inflated @ 4%	/ear	\$49,136 \$72,733	\$96,370 \$148,356	\$71,576 \$114 595	\$26,829 \$44,672	\$91,590 \$158,604	\$311,635 \$561,237	\$30,488 \$57,103		\$224,429 \$454,652	\$268,298 \$565,263
										.o.u. oost (iiiiateu 🥪 47	po. 11.)	\$12,133	Ç170,000	¥117,030	V44,07Z	¥100,00 <del>4</del>	4301,£31	<b>401,100</b>	\$104,00Z	<b>↓101,03</b> 2	4000,E00

## 20 YEAR EXPENDITURE FORECAST

Vermont Veterans' Home 325 North Street Bennington, Vermont

	Component Description	Asset	Location	Action	Estimated Useful Life or Replacement Cycle	Remaining Useful Life (Yrs)	Quantity	Unit of Measurement	Unit Cost	Plan Type	Priority	Total	Total
					(Yrs)	Life (115)		Weasurement					
. SUBSTRUC	CTURE	-	1			1	<u> </u>		ľ	ı		Deferred	Scheduled
										A. SUBSTRUCTURE	SUP TOTALS	¢0	\$0
. SHELL	ı		-	ı					ı	A. SOBSTRUCTURE	30B-TOTAL3	\$0	<b>\$</b> 0
20	EXTERIOR ENCLOSURE												
	Brick Veneer - Upper Floor	Brick Exteriors	Most exterior walls	Point Brick Exterior Walls where required	10	5	20.00	CSF	\$948.00	OP - Maintenance	Priority 4	\$0	\$37,920
2011	Wood Siding	Vertical wood siding	In-Service & Social Hall	General Painting Cost Per SF, Minor Prep Work, Up to 4-Story Bldg.	10	0	675.00	SF	\$1.41	OP - Maintenance	Priority 4	\$952	\$952
	Wood Siding EIFS with Stucco Over Cement Board	Vertical wood siding  EIFS with Stucco Over Cement Board		Replace Vertical wood siding	25 0	11	675.00	SF CSF	\$12.68	IN - Beyond Rated Life	Priority 4	\$0 \$0	\$8,559
2011	EIFS with Stucco Over Cement Board	EIFS with Stucco Over Cement Board	North Village Wing North Village Wing	Color Coat 100% of Asset: EIFS Repair 10% of Asset: EIFS with Stucco Over	8	19 3	44.00 5.00	CSF	\$218.00 \$476.00	OP - Maintenance OP - Maintenance	Priority 4 Priority 4	\$0	\$9,592 \$7,140
2011	Solid Wood Lap Siding	Wood Lap Siding and Trim	Origional Bldg and Mainte. Garage	Cement Board Paint Existing Wood Siding and trim, One Coat, Spray with Medium Prep and Clean Up	10	2	5,200.00	SF	\$1.23	OP - Maintenance	Priority 4	\$0	\$12,792
2011	Caulking, Polyurethane, 1/4"X1/4"	Caulk sealant at joints and openings	All exterior walls	Replace Caulk sealant at joints and openings	15	6	3,000.00	LF	\$3.84	OP - Maintenance	Priority 4	\$0	\$11,520
2011	Solid Masonry	Brick Chimney	Boiler Building	Repair 100% of Asset: Brick Chimney	10	1	1.00	EA	\$25,000.00	OP - Maintenance	Priority 4	\$0	\$50,000
2021	Aluminum Window , 4-0 X 6-0,First Floor	Corridor Windows	Corridor at Dining and Chapel	Replace Corridor Windows	25	0	18.00	EA	\$1,276.99	IN - Beyond Rated Life	Priority 3	\$22,986	\$0
2021	3' X 4' Aluminum Window Operable	Casement Windows	Administration and D wing	Replace Casement Windows	25	2	64.00	EA	\$911.00	IN - Beyond Rated Life	Priority 3	\$0	\$58,304
2032	3'-0" X 7'-0" Steel, Insulated Core, Ptd. Door	Exterior Steel Doors	All entrances	Repair 8% of Asset: 3'-0" X 7'-0" Steel, Insulated Core, Ptd. Door	4	1	4.00	EA	\$1,098.00	IN - Reliability	Priority 3	\$0	\$21,960
30	ROOFING					L							
3011	Tpo, Roof 45 Mills, Full Adhered	TPO Roof on Entrance, Dining and East Wing	Entrance, Dining and East Wing	Replace TPO Roof on Entrance, Dining and East Wing	20	0	250.00	sq	\$714.09	IN - Reliability	Priority 3	\$178,523	\$0
3011	Wood Shingle , Historic Structure	Wood Roof Shingles	In-Service Social Building	Replace Wood Roof Shingles	25	15	25.00	SQ	\$817.00	IN - Beyond Rated Life	Priority 4	\$0	\$20,425
	Asphalt Shingles, Removal and with Premium Grade	Asphalt Shingles Original House	House, Boiler and Maintenance Buildngs	Replace Asphalt Shingles Original House	30	3	120.00	SQ	\$430.00	IN - Reliability	Priority 3	\$0	\$51,600
3011	Tpo, Roof 45 Mills, Full Adhered	TPO Roofs on B. C and D Wings	B, C, & D Wings	Replace TPO Roofs on B. C and D Wings	20	19	250.00	SQ	\$714.09	IN - Beyond Rated Life	Priority 4	\$0	\$178,523
3011	Tpo, Roof 45 Mills, Full Adhered	TPO Roof North Wings		Replace TPO Roof North Wings	20	18	300.00	SQ	\$714.09	IN - Beyond Rated Life	Priority 4	\$0	\$214,227
3011	Tpo, Roof 45 Mills, Full Adhered	TPO Roof on A Wing and D Dayroom		Replace TPO Roof on A Wing and D Dayroom	99	18	300.00	SQ	\$1.00	IN - Beyond Rated Life	Priority 4	\$0	\$300
3021	Plexi-Glass Skylight to 10 SF	Plexi-Glass Skylights	Flat Roofs	Replace Plexi-Glass Skylights	20	17	25.00	EA	\$328.00	IN - Beyond Rated Life	Priority 4	\$0	\$8,200
3021	B3021 Glazed Roof Openings	Plexi-Glass Skylights	Flat Roofs	Replace Plexi-Glass Skylights	20	3	15.00	EA	\$1.00	IN - Beyond Rated Life	Priority 3	\$0	\$15
										B. SHELL	SUB-TOTALS	\$202,460	\$692,028
. INTERIORS			I	I		I							
1021	INTERIOR CONSTRUCTION Automatic Accessible Door, Wood with Glass Panels	Automatic Accessible Door, Wood		Repair 2% of Asset: Automatic Accessible Door, Wood with Glass Panels	2	1	2.00	EA	\$6,500.00	OP - Maintenance	Priority 4	\$0	\$130,000
	raileis			DOOL, WOOD WILLI Glass Fallels				l .					
	INTERIOR FINISHES			l			ı	I	1				
	INTERIOR FINISHES Vinyl Tile	Vinyl Composition Floor Tiles	Throughout interiors	Repair 5% of Asset: Floor tile replacments	5	1	450.00	SY	\$67.75	IN - Appearance	Priority 4	\$0	\$121,950
3024			Throughout interiors	Repair 5% of Asset: Floor tile replacments	5	1	450.00	SY	\$67.75	IN - Appearance C. INTERIORS			
		Vinyl Composition Floor Tiles	Throughout interiors	Repair 5% of Asset: Floor tile replacments	5	1	450.00	SY	\$67.75				
. SERVICES	Vinyl Tile  CONVEYING SYSTEMS				5	1				C. INTERIORS	SUB-TOTALS	\$0	\$251,950
. SERVICES	Vinyl Tile		Throughout interiors  B/C Wing	Repair 5% of Asset: Floor tile replacments  Repair 5% of Asset: Floor tile replacments  Replace Hydraulic Elevator, Small Cab	5	1	1.00	SY	\$67.75 \$24,940.22				
3024 . SERVICES 10 10111	Vinyl Tile  CONVEYING SYSTEMS  Elevator Hydraulic System, 3,500 Lb Capacity  HVAC		B/C Wing	Replace Hydraulic Elevator, Small Cab		1	1.00	EA	\$24,940.22	C. INTERIORS  IN - Beyond Rated Life	Priority 3	\$0 \$0	\$251,950 \$24,940
. SERVICES 10 10 11011 130 3022.1	Vinyl Tile  CONVEYING SYSTEMS  Elevator Hydraulic System, 3,500 Lb Capacity  HVAC  Heating Water Distribution Pump 3 HP	Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps	B/C Wing  Basement/Crawl Spaces	Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps	15	9	1.00	EA EA	\$24,940.22 \$6,941.00	C. INTERIORS  IN - Beyond Rated Life  IN - Beyond Rated Life	Priority 3  Priority 4	\$0 \$0	\$251,950 \$24,940 \$242,935
3024 . SERVICES 10 10111	Vinyl Tile  CONVEYING SYSTEMS  Elevator Hydraulic System, 3,500 Lb Capacity  HVAC	Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps  AHU #3	B/C Wing Basement/Crawl	Replace Hydraulic Elevator, Small Cab		1 1 9 18	1.00	EA	\$24,940.22	C. INTERIORS  IN - Beyond Rated Life	Priority 3	\$0 \$0	\$251,950 \$24,940
3024  . SERVICES  10 10111  30 3022.1 3041.1	Vinyl Tile  CONVEYING SYSTEMS  Elevator Hydraulic System, 3,500 Lb Capacity  HVAC  Heating Water Distribution Pump 3 HP  Air Handler 4,000 to 8,000 CFM  Air Handler 2500-3000 CFM	Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps  AHU #3  AHU #2	B/C Wing  Basement/Crawl Spaces	Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps	15 20 15	9 18 13	1.00	EA EA EA	\$24,940.22 \$6,941.00	C. INTERIORS  IN - Beyond Rated Life  IN - Beyond Rated Life	Priority 3  Priority 4	\$0 \$0 \$0 \$0 \$0	\$251,950 \$24,940 \$242,935
3024  . SERVICES  10 10111  30 3022.1 3041.1	Vinyl Tile  CONVEYING SYSTEMS  Elevator Hydraulic System, 3,500 Lb Capacity  HVAC  Heating Water Distribution Pump 3 HP  Air Handler 4,000 to 8,000 CFM	Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps  AHU #3	B/C Wing  Basement/Crawl Spaces A Wing	Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3 Replace AHU #2 Replace AHU #1	15 20	9 18	1.00 35.00 1.00	EA EA	\$24,940.22 \$6,941.00 \$4,780.00	C. INTERIORS  IN - Beyond Rated Life	Priority 3  Priority 4  Priority 4	\$0 \$0 \$0 \$0	\$24,940 \$24,935 \$4,780
3024  . SERVICES  10 10111  30 3022.1 3041.1 3041.1 3051.1	Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC Heating Water Distribution Pump 3 HP Air Handler 4,000 to 8,000 CFM Air Handler 2500-3000 CFM Air Handler 3600-3800 CFM Heat Pump Water Source, 4-Ton	Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps  AHU #3  AHU #2	Basement/Crawl Spaces A Wing	Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #2  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project	15 20 15	9 18 13	1.00 35.00 1.00	EA EA EA EA LS	\$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00	IN - Beyond Rated Life FN - Modernization	Priority 4 Priority 4 Priority 4	\$0 \$0 \$0 \$0 \$0 \$0 \$0	\$24,940 \$242,935 \$4,780 \$3,204
3024  . SERVICES  10 10111  30 3022.1 3041.1 3041.1 3051.1	Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC Heating Water Distribution Pump 3 HP Air Handler 4,000 to 8,000 CFM Air Handler 2500-3000 CFM Air Handler 3600-3800 CFM	Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps  AHU #3  AHU #2  AHU #1	B/C Wing  Basement/Crawl Spaces A Wing  North Wing	Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #2  Replace AHU #1  Expand heat pump system into East Wing to	15 20 15 15	9 18 13	1.00 35.00 1.00 1.00	EA EA EA EA	\$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$6,233.00	C. INTERIORS  IN - Beyond Rated Life	Priority 3  Priority 4  Priority 4  Priority 4  Priority 4	\$0 \$0 \$0 \$0 \$0 \$0	\$24,940 \$242,935 \$4,780 \$3,204 \$6,233
3024  . SERVICES  10  10111  30  3022.1  3041.1  3041.1  3051.1	Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC Heating Water Distribution Pump 3 HP Air Handler 4,000 to 8,000 CFM Air Handler 2500-3000 CFM Air Handler 3600-3800 CFM Heat Pump Water Source, 4-Ton	Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps  AHU #3  AHU #2  AHU #1  Heat Pump System	B/C Wing  Basement/Crawl Spaces A Wing  North Wing  North Wing  East Wing	Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #2  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to	15 20 15 15	9 18 13 13	1.00 35.00 1.00 1.00 1.00	EA EA EA EA LS	\$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$6,233.00 \$140,300.00	IN - Beyond Rated Life FN - Modernization	Priority 4 Priority 4 Priority 4 Priority 4 Priority 4 Priority 4 Priority 3	\$0 \$0 \$0 \$0 \$0 \$0 \$0	\$24,940 \$242,935 \$4,780 \$3,204 \$6,233 \$140,300
3024  . SERVICES  10 10111  30 3022.1 3041.1 3041.1 3051.1 3069	Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC Heating Water Distribution Pump 3 HP Air Handler 4,000 to 8,000 CFM Air Handler 2500-3000 CFM Air Handler 3600-3800 CFM Heat Pump Water Source, 4-Ton D3069 Other Controls & Instrumentation D3069 Other Controls & Instrumentation FIRE PROTECTION SYSTEMS	Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3  AHU #2  AHU #1  Heat Pump System  Well Pump Controller	B/C Wing  Basement/Crawl Spaces A Wing  North Wing  North Wing  East Wing  Geothermal Wells  Geothermal Wells	Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #2  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.  Replace Well Pump Controller	15 20 15 15 0	9 18 13 13 1 1	1.00 35.00 1.00 1.00 1.00 1.00	EA EA EA EA LS EA	\$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$6,233.00 \$140,300.00 \$1,500.00 \$3.43	IN - Beyond Rated Life IN - Reliability	Priority 4 Priority 4 Priority 4 Priority 4 Priority 4 Priority 4 Priority 3 Priority 3	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$1,500	\$24,940 \$24,940 \$242,935 \$4,780 \$3,204 \$6,233 \$140,300 \$0
3024  . SERVICES  10  1011  30  3022.1  3041.1  3041.1  3051.1  3069	CONVEYING SYSTEMS  Elevator Hydraulic System, 3,500 Lb Capacity  HVAC  Heating Water Distribution Pump 3 HP  Air Handler 4,000 to 8,000 CFM  Air Handler 2500-3000 CFM  Air Handler 3600-3800 CFM  Heat Pump Water Source, 4-Ton  D3069 Other Controls & Instrumentation	Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3  AHU #2  AHU #1  Heat Pump System  Well Pump Controller	B/C Wing  Basement/Crawl Spaces A Wing  North Wing  North Wing  East Wing  Geothermal Wells	Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #2  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.	15 20 15 15 0	9 18 13 13 1 1	1.00 35.00 1.00 1.00 1.00 1.00	EA EA EA EA LS EA	\$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$6,233.00 \$140,300.00 \$1,500.00	IN - Beyond Rated Life IN - Reliability	Priority 4 Priority 4 Priority 4 Priority 4 Priority 4 Priority 4 Priority 3 Priority 3	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$1,500	\$24,940 \$24,940 \$242,935 \$4,780 \$3,204 \$6,233 \$140,300 \$0
3024  10	CONVEYING SYSTEMS  Elevator Hydraulic System, 3,500 Lb Capacity  HVAC  Heating Water Distribution Pump 3 HP  Air Handler 4,000 to 8,000 CFM  Air Handler 2500-3000 CFM  Air Handler 3600-3800 CFM  Heat Pump Water Source, 4-Ton  D3069 Other Controls & Instrumentation  BIRE PROTECTION SYSTEMS  Air Compressor for Dry Pipe System 520 Gal, 1HP  ELECTRICAL SYSTEMS	Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3 AHU #2 AHU #1 Heat Pump System Well Pump Controller Well Pump Controller	Basement/Crawl Spaces A Wing North Wing North Wing East Wing Geothermal Wells Geothermal Wells	Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #2  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.  Replace Well Pump Controller  Replace Air Compressor, Dry Pipe Sprinkler	15 20 15 15 0 0	9 18 13 13 1 1 0	1.00 35.00 1.00 1.00 1.00 1.00 1.00	EA EA EA EA LS EA EA	\$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$6,233.00 \$140,300.00 \$1,500.00 \$3.43	IN - Beyond Rated Life FN - Modernization IN - Reliability IN - Beyond Rated Life	Priority 3  Priority 4  Priority 4  Priority 4  Priority 4  Priority 3  Priority 3  Priority 4	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$24,940 \$242,935 \$4,780 \$3,204 \$6,233 \$140,300 \$0 \$3
3024  10   1011  30   3022.1  3041.1  3041.1  3051.1  40   4011  50   5034	Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC Heating Water Distribution Pump 3 HP Air Handler 4,000 to 8,000 CFM Air Handler 2500-3000 CFM Air Handler 3600-3800 CFM Heat Pump Water Source, 4-Ton D3069 Other Controls & Instrumentation D3069 Other Controls & Instrumentation FIRE PROTECTION SYSTEMS Air Compressor for Dry Pipe System 520 Gal, 1HP	Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3 AHU #2 AHU #1 Heat Pump System Well Pump Controller Well Pump Controller	B/C Wing  Basement/Crawl Spaces A Wing North Wing North Wing East Wing Geothermal Wells  Basement/Crawl Spaces  Staff Parking	Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #2  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.  Replace Well Pump Controller  Replace Air Compressor, Dry Pipe Sprinkler	15 20 15 15 0 0 25	9 18 13 13 1 1 0	1.00 35.00 1.00 1.00 1.00 1.00 1.00	EA EA EA LS EA EA EA EA	\$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$6,233.00 \$140,300.00 \$1,500.00 \$3.43	IN - Beyond Rated Life FN - Modernization IN - Reliability IN - Beyond Rated Life	Priority 3  Priority 4  Priority 4  Priority 4  Priority 4  Priority 3  Priority 3  Priority 4	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$24,940 \$242,935 \$4,780 \$3,204 \$6,233 \$140,300 \$0 \$3
3024  10	CONVEYING SYSTEMS  Elevator Hydraulic System, 3,500 Lb Capacity  HVAC  Heating Water Distribution Pump 3 HP  Air Handler 4,000 to 8,000 CFM  Air Handler 2500-3000 CFM  Air Handler 3600-3800 CFM  Heat Pump Water Source, 4-Ton  D3069 Other Controls & Instrumentation  D3069 Other Controls & Instrumentation  FIRE PROTECTION SYSTEMS  Air Compressor for Dry Pipe System 520 Gal, 1HP  ELECTRICAL SYSTEMS  Call for Aid System with Central Monitoring	Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3 AHU #2 AHU #1 Heat Pump System Well Pump Controller Well Pump Controller Air Compressor, Dry Pipe Sprinkler System	B/C Wing  Basement/Crawl Spaces A Wing North Wing North Wing East Wing Geothermal Wells  Basement/Crawl Spaces  Staff Parking Basement Mechanical Room	Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #2  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.  Replace Well Pump Controller  Replace Air Compressor, Dry Pipe Sprinkler System  Replace Call for Aid Posts in Staff Parking  Replace Call for Aid Posts in Staff Parking	15 20 15 15 0 0 25	9 18 13 13 1 0 19	1.00 35.00 1.00 1.00 1.00 1.00 1.00 1.00	EA EA EA LS EA EA EA	\$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$6,233.00 \$140,300.00 \$1,500.00 \$3,43	IN - Beyond Rated Life IN - Reliability IN - Reliability IN - Beyond Rated Life IN - Beyond Rated Life	Priority 4 Priority 4 Priority 4 Priority 4 Priority 4 Priority 3 Priority 3 Priority 4 Priority 4	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$1,500 \$0	\$24,940 \$242,935 \$4,780 \$3,204 \$6,233 \$140,300 \$0 \$3
3024  10   1011  30   3022.1  3041.1  3041.1  3051.1  40   4011  50   5034	CONVEYING SYSTEMS  Elevator Hydraulic System, 3,500 Lb Capacity  HVAC  Heating Water Distribution Pump 3 HP  Air Handler 4,000 to 8,000 CFM  Air Handler 3600-3800 CFM  Heat Pump Water Source, 4-Ton  D3069 Other Controls & Instrumentation  D3069 Other Controls & Instrumentation  FIRE PROTECTION SYSTEMS  Air Compressor for Dry Pipe System 520 Gal, 1HP  ELECTRICAL SYSTEMS  Call for Aid System with Central Monitoring Capability	Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3  AHU #2  AHU #1  Heat Pump System  Well Pump Controller  Well Pump Controller  Air Compressor, Dry Pipe Sprinkler System  Call for Aid Posts in Staff Parking	B/C Wing  Basement/Crawl Spaces A Wing  North Wing  North Wing  East Wing  Geothermal Wells  Basement/Crawl Spaces  Staff Parking  Basement Mechanical	Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #2  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.  Replace Well Pump Controller  Replace Air Compressor, Dry Pipe Sprinkler System  Replace Call for Aid Posts in Staff Parking  Replace Call for Aid Posts in Staff Parking	15 20 15 15 0 0 25	9 18 13 13 1 0 19	1.00 35.00 1.00 1.00 1.00 1.00 1.00 1.00	EA EA EA LS EA EA EA EA	\$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$6,233.00 \$140,300.00 \$3,43 \$1,679.09	IN - Beyond Rated Life FN - Modernization IN - Reliability IN - Beyond Rated Life IN - Beyond Rated Life IN - Beyond Rated Life	Priority 4 Priority 4 Priority 4 Priority 4 Priority 4 Priority 3 Priority 3 Priority 4 Priority 4 Priority 3	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$1,500 \$0	\$24,940 \$242,935 \$4,780 \$3,204 \$6,233 \$140,300 \$0 \$3
3024  . SERVICES  10 10111  30 3022.1 3041.1 3041.1 3051.1 3069  40 4011 50 5034 5037 5039	CONVEYING SYSTEMS  Elevator Hydraulic System, 3,500 Lb Capacity  HVAC  Heating Water Distribution Pump 3 HP  Air Handler 4,000 to 8,000 CFM  Air Handler 2500-3000 CFM  Air Handler 3600-3800 CFM  Heat Pump Water Source, 4-Ton  D3069 Other Controls & Instrumentation  FIRE PROTECTION SYSTEMS  Air Compressor for Dry Pipe System 520 Gal, 1HP  ELECTRICAL SYSTEMS  Call for Aid System with Central Monitoring Capability  Fire Alarm Panel Addressable, with Voice	Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3  AHU #2  AHU #1  Heat Pump System  Well Pump Controller  Well Pump Controller  Air Compressor, Dry Pipe Sprinkler System  Call for Aid Posts in Staff Parking  Central Fire Alarm Control Panel	B/C Wing  Basement/Crawl Spaces A Wing  North Wing  North Wing  East Wing  Geothermal Wells  Geothermal Wells  Basement/Crawl Spaces  Staff Parking  Basement Mechanical Room Patient Mgt Stations &	Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.  Replace Well Pump Controller  Replace Air Compressor, Dry Pipe Sprinkler System  Replace Call for Aid Posts in Staff Parking Replace Central Fire Alarm Control Panel Replace Central Fire Alarm Control Panel	15 20 15 15 0 0 25 20	9 18 13 13 1 1 0 19	1.00 35.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	EA	\$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$1,500.00 \$1,500.00 \$3,43	IN - Beyond Rated Life IN - Reliability IN - Beyond Rated Life	Priority 4 Priority 4 Priority 4 Priority 4 Priority 4 Priority 3 Priority 4 Priority 4 Priority 3 Priority 4 Priority 4	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$1,500 \$0 \$0	\$24,940 \$242,935 \$4,780 \$3,204 \$6,233 \$140,300 \$0 \$3
3024  . SERVICES  10 10111  30 3022.1 3041.1 3041.1 3051.1 3069  40 4011  50 5034 5037 5039 5092	Vinyl Tile  CONVEYING SYSTEMS Elevator Hydraulic System, 3,500 Lb Capacity  HVAC Heating Water Distribution Pump 3 HP Air Handler 4,000 to 8,000 CFM Air Handler 2500-3000 CFM Air Handler 3600-3800 CFM Heat Pump Water Source, 4-Ton D3069 Other Controls & Instrumentation  FIRE PROTECTION SYSTEMS Air Compressor for Dry Pipe System 520 Gal, 1HP  ELECTRICAL SYSTEMS Call for Aid System with Central Monitoring Capability Fire Alarm Panel Addressable, with Voice LAN System - Heavy Density	Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3  AHU #2  AHU #1  Heat Pump System  Well Pump Controller  Well Pump Controller  Air Compressor, Dry Pipe Sprinkler System  Call for Aid Posts in Staff Parking  Central Fire Alarm Control Panel  Network distribution and control systems	B/C Wing  Basement/Crawl Spaces A Wing  North Wing  North Wing  East Wing  Geothermal Wells  Geothermal Wells  Basement/Crawl Spaces  Staff Parking  Basement Mechanical Room Patient Mgt Stations & Central Records	Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3  Replace AHU #2  Replace AHU #1  Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption.  Replace Well Pump Controller  Replace Air Compressor, Dry Pipe Sprinkler System  Replace Call for Aid Posts in Staff Parking Replace Central Fire Alarm Control Panel Replace Network distribution and control systems	15 20 15 15 0 0 25 20	9 18 13 13 1 0 19 18	1.00 35.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	EA EA EA LS EA EA EA EA SF	\$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$1,500.00 \$1,500.00 \$3,43 \$1,679.09 \$5,500.00 \$12,114.90 \$1.28	IN - Beyond Rated Life IN - Reliability IN - Beyond Rated Life	Priority 4 Priority 4 Priority 4 Priority 4 Priority 3 Priority 4 Priority 3 Priority 4 Priority 4 Priority 4 Priority 4	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$1,500 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$24,940 \$24,940 \$242,935 \$4,780 \$3,204 \$6,233 \$140,300 \$0 \$3 \$1,679
3024  SERVICES  10 10111  30 3022.1 3041.1 3041.1 3051.1 3069  40 4011 50 5034 5037 5039 5092 5092	CONVEYING SYSTEMS  Elevator Hydraulic System, 3,500 Lb Capacity  HVAC  Heating Water Distribution Pump 3 HP  Air Handler 4,000 to 8,000 CFM  Air Handler 2500-3000 CFM  Air Handler 3600-3800 CFM  Heat Pump Water Source, 4-Ton  D3069 Other Controls & Instrumentation  FIRE PROTECTION SYSTEMS  Air Compressor for Dry Pipe System 520 Gal, 1HP  ELECTRICAL SYSTEMS  Call for Aid System with Central Monitoring Capability  Fire Alarm Panel Addressable, with Voice  LAN System - Heavy Density  Generator, Natural Gas, 100 kW,	Hydraulic Elevator, Small Cab  Geothermal System Circulation Pumps AHU #3 AHU #2 AHU #1 Heat Pump System Well Pump Controller Well Pump Controller  Air Compressor, Dry Pipe Sprinkler System  Call for Aid Posts in Staff Parking Central Fire Alarm Control Panel Network distribution and control systems Propane Generator Module, 100kW	B/C Wing  Basement/Crawl Spaces A Wing  North Wing  North Wing  East Wing  Geothermal Wells  Geothermal Wells  Basement/Crawl Spaces  Staff Parking  Basement Mechanical Room Patient Mgt Stations & Central Records  Outside B Wing	Replace Hydraulic Elevator, Small Cab  Replace Geothermal System Circulation Pumps Replace AHU #3 Replace AHU #2 Replace AHU #1 Expand heat pump system into East Wing to complete geothermal project Provide system grounding as required to eliminate electrical disruption. Replace Well Pump Controller  Replace Air Compressor, Dry Pipe Sprinkler System  Replace Call for Aid Posts in Staff Parking Replace Central Fire Alarm Control Panel Replace Network distribution and control systems  Replace Propane Generator Module, 100kW	15 20 15 15 0 0 25 20 15 15 30	9 18 13 13 1 0 19 18 2 9 0	1.00 35.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	EA EA EA LS EA	\$24,940.22 \$6,941.00 \$4,780.00 \$3,204.00 \$140,300.00 \$1,500.00 \$3.43 \$1,679.09 \$1,2114.90 \$1.28 \$43,380.00	IN - Beyond Rated Life IN - Reliability IN - Beyond Rated Life	Priority 4 Priority 4 Priority 4 Priority 4 Priority 3 Priority 3 Priority 4 Priority 4 Priority 3 Priority 4 Priority 4 Priority 4 Priority 4 Priority 4	\$0 \$0 \$0 \$0 \$0 \$0 \$1,500 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$24,940 \$24,940 \$242,935 \$4,780 \$3,204 \$6,233 \$140,300 \$0 \$3 \$1,679 \$55,000 \$12,115 \$217,600 \$43,380

Powered by iPlan™ iPlan Capital Expenditure Report - Version 4.3 5 11/14/2013 4:35 PM

					Estimated Useful								
Element No.	Component Description	Asset	Location	Action	Life or Replacement Cycle (Yrs)	Remaining Useful Life (Yrs)	Quantity	Unit of Measurement	Unit Cost	Plan Type	Priority	Total	Total
E1016	Commercial Washers 75 Lb	Commercial Washers	Laundry Room	Replace Commercial Washers	20	14	2.00	EA	\$25,295.00	IN - Beyond Rated Life	Priority 4	\$0	\$50,590
E1016	Commercial Washers 50Lb	Commercial Washers	Laundry Room	Replace Commercial Washers	20	10	2.00	EA	\$13,312.00	IN - Beyond Rated Life	Priority 4	\$0	\$26,624
E1028	E1028 Medical Equipment	Compressed oxygen control and manifold	Rear of B Wing	Replace Compressed oxygen control and manifold	10	0	1.00	EA	\$5,000.00	IN - Beyond Rated Life	Priority 3	\$5,000	\$5,000
E1093	E1093 Food Service Equipment	Tilting Skillet	Central Kitchen	Replace Tilting Skillet	15	6	1.00		\$9,800.00	IN - Beyond Rated Life	Priority 4	\$0	\$9,800
E1093	Fryer Floor Mounted Twin Baskets	Fryer Floor Mounted Twin Baskets	Central Kitchen	Replace Fryer Floor Mounted Twin Baskets	20	5	2.00	EA	\$2,846.76	IN - Beyond Rated Life	Priority 4	\$0	\$5,694
E1093	Steam Table, Electric 5-Well	Steam Table, Electric 3-Well	Central Kitchen	Replace Steam Table, Electric 3-Well	20	11	2.00	EA	\$2,450.00	IN - Beyond Rated Life	Priority 4	\$0	\$4,900
E1093	Ice Maker w/ Storage Bin	Ice Maker	Central Kitchen	Replace Ice Maker	15	7	1.00	EA	\$6,200.00	IN - Beyond Rated Life	Priority 4	\$0	\$6,200
E1093	Griddle, Thermostatic Controls, 36" Wide , Electric	Griddle 48"		Replace Griddle 48"	20	9	2.00	EA	\$3,200.00	IN - Beyond Rated Life	Priority 4	\$0	\$6,400
E1093	E1093 Food Service Equipment	Cook hood with Fire Supression	Central Kitchen	Replace Cook hood with Fire Supression	25	8	4.00		\$5,685.00	IN - Beyond Rated Life	Priority 4	\$0	\$22,740
E1093	Walk in Refrigerator 8'X8'	Walk in Refrigerator 8'X8'	Central Kitchen	Replace Walk in Refrigerator 8'X8'	20	8	1.00	EA	\$8,787.80	IN - Beyond Rated Life	Priority 4	\$0	\$8,788
E1093	Kitchen Equipment Steamer Electric 27 kW	Skillet		Replace Skillet	20	3	1.00	EA	\$11,500.00	IN - Beyond Rated Life	Priority 3	\$0	\$11,500
E1093	E1093 Food Service Equipment	Vegatable Peeler	Central Kitchen	Replace Vegatable Peeler	15	4	1.00	EA	\$6,500.00	IN - Beyond Rated Life	Priority 4	\$0	\$13,000
E1093	E1093 Food Service Equipment	Exhaust Hood 4 ft X 4 ft	Central Kitchen	Replace Exhaust Hood 4 ft X 4 ft	99	1	1.00		\$1.00	IN - Beyond Rated Life	Priority 3	\$0	\$1
E1093	E1093 Food Service Equipment	Thermal Food Delivery Carts		Replace Thermal Food Delivery Carts	15	7	12.00		\$4,500.00	IN - Beyond Rated Life	Priority 4	\$0	\$54,000
E1093	Walk in Freezer 8'X12'	Walk in Freezer 6'X12'		Replace Walk in Freezer 6'X12'	20	8	1.00	EA	\$14,880.32	IN - Beyond Rated Life	Priority 4	\$0	\$14,880
E1093	Reach in Refrigerator 68 Cf	Reach in Refrigerator 68 Cf		Replace Reach in Refrigerator 68 Cf	15	6	1.00	EA	\$7,051.24	IN - Beyond Rated Life	Priority 4	\$0	\$7,051
E1093	E1093 Food Service Equipment	Four Drawer Warmer	Central Kitchen	Replace Four Drawer Warmer	15	6	1.00	LA	\$2,800.00	IN - Beyond Rated Life	Priority 4	\$0	\$2,800
-			Central Kitchen	-								-	
E1093	E1093 Food Service Equipment	Conveyor Dishwasher	O	Replace Conveyor Dishwasher	20	1	1.00	F4	\$16,500.00	IN - Beyond Rated Life	Priority 3	\$0	\$16,500
E1093	Hobart Legacy, Mixer, Planetary, 60Qt.	Mixer	Central Kitchen	Replace Mixer	20	9	2.00	EA	\$12,478.99	IN - Beyond Rated Life	Priority 4	\$0	\$24,958
E1093	Electric Convection Oven, Single Deck Stainless Steel Prep Table with Dual Reach in	Oven Stainless Steel Prep Table with Dual Reach in	Main Kitchen	Replace Oven Replace Stainless Steel Prep Table with Dual	20	3	1.00	EA	\$5,412.96	IN - Beyond Rated Life	Priority 3	\$0	\$5,413
E1093	Refrigerators	Refrigerators	Central Kitchen	Reach in Refrigerators	20	12	1.00	EA	\$3,200.00	IN - Beyond Rated Life	Priority 4	\$0	\$3,200
E1093	E1093 Food Service Equipment	3 Compartment Sink with Drain boards		Replace 3 Compartment Sink with Drain boards	20	3	3.00		\$1,475.00	IN - Beyond Rated Life	Priority 3	\$0	\$4,425
E1093	E1093 Food Service Equipment	Convection Steamer		Replace Convection Steamer	15	2	1.00	EA	\$12,800.00	IN - Beyond Rated Life	Priority 3	\$0	\$25,600
E1093	E1093 Food Service Equipment	Stove Broiler Oven Combo	Central Kitchen	Replace Stove Broiler Oven Combo	20	11	1.00		\$8,600.00	IN - Beyond Rated Life	Priority 4	\$0	\$8,600
E1093	Reach in Freezer 44 Cf	Reach in Refrigerator 49CF		Replace Reach in Refrigerator 49CF	15	9	1.00	EA	\$4,108.13	IN - Beyond Rated Life	Priority 4	\$0	\$4,108
E1093	Garbage Disposal-3HP Restaurant Type	Disposal Trough -1HP Custom	Central Kitchen	Replace Disposal Trough -1HP Custom	20	0	1.00	EA	\$12,500.00	IN - Beyond Rated Life	Priority 3	\$12,500	\$0
E SDECIAL C	ONSTRUCTION AND DEMOLITION								E. EQUIP	MENT & FURNISHING	SUB-TOTALS	\$17,500	\$342,772
1. SI EGIAL G	Entertion And Bennier Hon	l											
G. BUILDING	SITEWORK							F. SPECIA	L CONSTRUCTI	ON AND DEMOLITION	SUB-TOTALS	\$0	\$0
C. BOILDING		I											
G20	SITE IMPROVEMENTS												
G2012	Asphalt Roadway-Without Base	Asphalt Swale Drive at Maintenance Service Drive	and Maintenance	Replace Asphalt Swale Drive at Maintenance Service Drive Cut & Patch Asphalt - full depth repairs as	20	1	98.00	SY	\$16.50	IN - Beyond Rated Life	Priority 3	\$0	\$1,617
	Asphalt, Mill 1.5" / Resurface 2.0" - Roadways	Asphalt Paved Drives and Parking	Front drive, visitor and south staff parking	needed in conjunction with mill and resurfacing	0	1	200.00	SF	\$2.38	OP - Maintenance	Priority 4	\$0	\$476
G2012	Asphalt, Mill 1.5" / Resurface 2.0" - Roadways	Asphalt Paved Drives and Parking		Repair 100% of Asset: Asphalt paved roads, front and south rear parking	0	1	2,100.00	SY	\$16.70	OP - Maintenance	Priority 4	\$0	\$35,070
			Front drive violes and										
	Asphalt, Mill 1.5" / Resurface 2.0" - Roadways	Asphalt Paved Drives and Parking	south stail parking	Seal Coat Asphalt (Up to 10000 SF)	5	7	37,200.00	SF	\$0.50	OP - Maintenance	Priority 4	\$0	\$55,800
G2022	Asphalt, Mill 1.5" / Resurface 2.0" - Roadways  Driveway Asphalt Paving  Driveway Asphalt Paving	Asphalt Paved Drives and Parking Staff Parking Lot & Drives Staff Parking Lot & Drives	south staff parking Site northeast	Seal Coat Asphalt (Up to 10000 SF)  Restripe Parking Lots Seal Coat Asphalt (Up to 10000 SF)	5 7 5	7 4 4	37,200.00 313.00 82,000.00	SF Stall SF	\$0.50 \$11.00 \$0.50	OP - Maintenance OP - Maintenance OP - Maintenance	Priority 4 Priority 4 Priority 4	\$0 \$0 \$0	\$55,800 \$10,329 \$164,000
G2022 G2041	Driveway Asphalt Paving	Staff Parking Lot & Drives	south staff parking Site northeast	Restripe Parking Lots	7	4	313.00	Stall	\$11.00	OP - Maintenance	Priority 4	\$0	\$10,329 \$164,000 \$1,481
G2041 G2041	Driveway Asphalt Paving Driveway Asphalt Paving Chain Link Fence, 6-Foot High 3-Foot High Chain Link Fence,	Staff Parking Lot & Drives Staff Parking Lot & Drives Security Fence Chain link fence at East Boundary	south staff parking Site northeast Site northeast Wing C south Courtyard East site Boundry	Restripe Parking Lots Seal Coat Asphalt (Up to 10000 SF) Replace Security Fence Replace Chain link fence at East Boundary	7 5 20 30	4 4 7 10	313.00 82,000.00 50.00 960.00	Stall SF LF LF	\$11.00 \$0.50 \$29.61 \$17.25	OP - Maintenance OP - Maintenance IN - Beyond Rated Life OP - Security	Priority 4 Priority 4 Priority 4 Priority 4	\$0 \$0 \$0 \$0	\$10,329 \$164,000 \$1,481 \$16,560
G2041 G2041 G2041	Driveway Asphalt Paving Driveway Asphalt Paving Chain Link Fence, 6-Foot High 3-Foot High Chain Link Fence, Install New Chain Link Fencing	Staff Parking Lot & Drives Staff Parking Lot & Drives Security Fence Chain link fence at East Boundary Chain Link Fence	south staff parking Site northeast Site northeast Wing C south Courtyard East site Boundry Boundry at Deer Park Along east staff	Restripe Parking Lots Seal Coat Asphalt (Up to 10000 SF) Replace Security Fence Replace Chain link fence at East Boundary Replace Chain Link Fence	7 5 20 30 30	4 4 7 10 1	313.00 82,000.00 50.00 960.00 880.00	Stall SF LF LF LF	\$11.00 \$0.50 \$29.61 \$17.25 \$28.50	OP - Maintenance OP - Maintenance IN - Beyond Rated Life OP - Security OP - Security	Priority 4 Priority 4 Priority 4 Priority 4 Priority 3	\$0 \$0 \$0 \$0 \$0	\$10,329 \$164,000 \$1,481 \$16,560 \$25,080
G2041 G2041 G2041 G2045	Driveway Asphalt Paving Driveway Asphalt Paving Chain Link Fence, 6-Foot High 3-Foot High Chain Link Fence, Install New Chain Link Fencing G2045 Site Furnishings	Staff Parking Lot & Drives Staff Parking Lot & Drives Security Fence Chain link fence at East Boundary Chain Link Fence Smoker Den	south staff parking Site northeast Site northeast Wing C south Courtyard East site Boundry Boundry at Deer Park Along east staff parking areas	Restripe Parking Lots Seal Coat Asphalt (Up to 10000 SF)  Replace Security Fence Replace Chain link fence at East Boundary Replace Chain Link Fence	7 5 20 30 30	4 4 7 10 1	313.00 82,000.00 50.00 960.00 880.00	Stall SF LF LF LF EA	\$11.00 \$0.50 \$29.61 \$17.25 \$28.50 \$1,200.00	OP - Maintenance OP - Maintenance IN - Beyond Rated Life OP - Security OP - Security IN - Beyond Rated Life	Priority 4 Priority 4 Priority 4 Priority 4 Priority 3 Priority 3	\$0 \$0 \$0 \$0 \$0 \$0 \$0	\$10,329 \$164,000 \$1,481 \$16,560 \$25,080 \$2,400
G2041 G2041 G2041	Driveway Asphalt Paving Driveway Asphalt Paving Chain Link Fence, 6-Foot High 3-Foot High Chain Link Fence, Install New Chain Link Fencing	Staff Parking Lot & Drives Staff Parking Lot & Drives Security Fence Chain link fence at East Boundary Chain Link Fence	south staff parking Site northeast Site northeast Wing C south Courtyard East site Boundry Boundry at Deer Park Along east staff parking areas	Restripe Parking Lots Seal Coat Asphalt (Up to 10000 SF) Replace Security Fence Replace Chain link fence at East Boundary Replace Chain Link Fence	7 5 20 30 30	4 4 7 10 1	313.00 82,000.00 50.00 960.00 880.00	Stall SF LF LF LF	\$11.00 \$0.50 \$29.61 \$17.25 \$28.50	OP - Maintenance OP - Maintenance IN - Beyond Rated Life OP - Security OP - Security	Priority 4 Priority 4 Priority 4 Priority 4 Priority 3	\$0 \$0 \$0 \$0 \$0	\$10,329 \$164,000 \$1,481 \$16,560 \$25,080
G2041 G2041 G2041 G2045 G2052	Driveway Asphalt Paving Driveway Asphalt Paving Chain Link Fence, 6-Foot High 3-Foot High Chain Link Fence, Install New Chain Link Fencing G2045 Site Furnishings	Staff Parking Lot & Drives Staff Parking Lot & Drives Security Fence Chain link fence at East Boundary Chain Link Fence Smoker Den	south staff parking Site northeast Site northeast Wing C south Courtyard East site Boundry Boundry at Deer Park Along east staff parking areas Bulding perimeters	Restripe Parking Lots Seal Coat Asphalt (Up to 10000 SF) Replace Security Fence Replace Chain link fence at East Boundary Replace Chain Link Fence Replace Smoker Den Replace Landscape turf around building	7 5 20 30 30	4 4 7 10 1	313.00 82,000.00 50.00 960.00 880.00	Stall SF LF LF LF EA	\$11.00 \$0.50 \$29.61 \$17.25 \$28.50 \$1,200.00	OP - Maintenance OP - Maintenance IN - Beyond Rated Life OP - Security OP - Security IN - Beyond Rated Life	Priority 4 Priority 4 Priority 4 Priority 4 Priority 3 Priority 3	\$0 \$0 \$0 \$0 \$0 \$0 \$0	\$10,329 \$164,000 \$1,481 \$16,560 \$25,080 \$2,400
G2041 G2041 G2041 G2045 G2052 G30 G3013	Driveway Asphalt Paving Driveway Asphalt Paving Chain Link Fence, 6-Foot High 3-Foot High Chain Link Fence, Install New Chain Link Fencing G2045 Site Furnishings Establishment of Ground Cover at Bare Areas SITE CIVIL/MECHANICAL UTILITIES Well Pump 30 HP, 100 to 300 Gpm  SITE ELECTRICAL UTILITIES	Staff Parking Lot & Drives Staff Parking Lot & Drives Security Fence Chain link fence at East Boundary Chain Link Fence Smoker Den Landscape turf around building perimeter walls	south staff parking Site northeast Site northeast Wing C south Courtyard East site Boundry Boundry at Deer Park Along east staff parking areas Bulding perimeters	Restripe Parking Lots Seal Coat Asphalt (Up to 10000 SF) Replace Security Fence Replace Chain link fence at East Boundary Replace Chain Link Fence Replace Smoker Den Replace Landscape turf around building perimeter walls	7 5 20 30 30 15 25	4 4 7 10 1 0	313.00 82,000.00 50.00 960.00 880.00 2.00 35.00	Stall SF LF LF LF CSF	\$11.00 \$0.50 \$29.61 \$17.25 \$28.50 \$1,200.00 \$985.00	OP - Maintenance OP - Maintenance IN - Beyond Rated Life OP - Security OP - Security IN - Beyond Rated Life IN - Beyond Rated Life	Priority 4 Priority 4 Priority 4 Priority 4 Priority 3 Priority 3 Priority 3	\$0 \$0 \$0 \$0 \$0 \$0 \$2,400 \$34,475	\$10,329 \$164,000 \$1,481 \$16,560 \$25,080 \$2,400
G2041 G2041 G2041 G2045 G2052 G30 G3013	Driveway Asphalt Paving Driveway Asphalt Paving Chain Link Fence, 6-Foot High 3-Foot High Chain Link Fence, Install New Chain Link Fencing G2045 Site Furnishings Establishment of Ground Cover at Bare Areas SITE CIVIL/MECHANICAL UTILITIES Well Pump 30 HP, 100 to 300 Gpm	Staff Parking Lot & Drives Staff Parking Lot & Drives Security Fence Chain link fence at East Boundary Chain Link Fence Smoker Den Landscape turf around building perimeter walls	south staff parking Site northeast Site northeast Site northeast Wing C south Courtyard East site Boundry Boundry at Deer Park Along east staff parking areas Bulding perimeters  Geothermal Wells	Restripe Parking Lots Seal Coat Asphalt (Up to 10000 SF) Replace Security Fence Replace Chain link fence at East Boundary Replace Chain Link Fence Replace Smoker Den Replace Landscape turf around building perimeter walls	7 5 20 30 30 15 25	4 4 7 10 1 0	313.00 82,000.00 50.00 960.00 880.00 2.00 35.00	Stall SF LF LF LF CSF	\$11.00 \$0.50 \$29.61 \$17.25 \$28.50 \$1,200.00 \$985.00	OP - Maintenance OP - Maintenance IN - Beyond Rated Life OP - Security OP - Security IN - Beyond Rated Life IN - Beyond Rated Life	Priority 4 Priority 4 Priority 4 Priority 4 Priority 3 Priority 3 Priority 3	\$0 \$0 \$0 \$0 \$0 \$0 \$2,400 \$34,475	\$10,329 \$164,000 \$1,481 \$16,560 \$25,080 \$2,400
G2041 G2041 G2041 G2045 G2052 G30 G3013 G40 G4021	Driveway Asphalt Paving Driveway Asphalt Paving Driveway Asphalt Paving Chain Link Fence, 6-Foot High 3-Foot High Chain Link Fence, Install New Chain Link Fencing G2045 Site Furnishings Establishment of Ground Cover at Bare Areas SITE CIVIL/MECHANICAL UTILITIES Well Pump 30 HP, 100 to 300 Gpm  SITE ELECTRICAL UTILITIES Landscape Ground Mounted Uplight Fixture	Staff Parking Lot & Drives Staff Parking Lot & Drives Security Fence Chain link fence at East Boundary Chain Link Fence Smoker Den Landscape turf around building perimeter walls Well Pump, 400GPM	south staff parking Site northeast Site northeast Site northeast Wing C south Courtyard East site Boundry Boundry at Deer Park Along east staff parking areas Bulding perimeters  Geothermal Wells	Restripe Parking Lots Seal Coat Asphalt (Up to 10000 SF)  Replace Security Fence Replace Chain link fence at East Boundary Replace Chain Link Fence  Replace Smoker Den  Replace Landscape turf around building perimeter wails  Replace Well Pump, 400GPM  Replace Convert Entry Flag Pole Lights to	7 5 20 30 30 15 25	4 4 7 10 1 0 0	313.00 82,000.00 50.00 960.00 880.00 2.00 35.00	Stall SF LF LF LF CSF EA	\$11.00 \$0.50 \$29.61 \$17.25 \$28.50 \$1,200.00 \$985.00	OP - Maintenance OP - Maintenance IN - Beyond Rated Life OP - Security OP - Security IN - Beyond Rated Life IN - Beyond Rated Life IN - Beyond Rated Life	Priority 4 Priority 4 Priority 4 Priority 4 Priority 4 Priority 3 Priority 3 Priority 3 Priority 4	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$2,400 \$34,475	\$10,329 \$184,000 \$1,481 \$16,560 \$25,080 \$2,400 \$0
G2041 G2041 G2041 G2045 G2052 G30 G3013	Driveway Asphalt Paving Driveway Asphalt Paving Driveway Asphalt Paving Chain Link Fence, 6-Foot High 3-Foot High Chain Link Fence, Install New Chain Link Fencing G2045 Site Furnishings Establishment of Ground Cover at Bare Areas SITE CIVIL/MECHANICAL UTILITIES Well Pump 30 HP, 100 to 300 Gpm  SITE ELECTRICAL UTILITIES Landscape Ground Mounted Uplight Fixture	Staff Parking Lot & Drives Staff Parking Lot & Drives Security Fence Chain link fence at East Boundary Chain Link Fence Smoker Den Landscape turf around building perimeter walls Well Pump, 400GPM	south staff parking Site northeast Site northeast Site northeast Wing C south Courtyard East site Boundry Boundry at Deer Park Along east staff parking areas Bulding perimeters  Geothermal Wells	Restripe Parking Lots Seal Coat Asphalt (Up to 10000 SF)  Replace Security Fence Replace Chain link fence at East Boundary Replace Chain Link Fence  Replace Smoker Den  Replace Landscape turf around building perimeter wails  Replace Well Pump, 400GPM  Replace Convert Entry Flag Pole Lights to	7 5 20 30 30 15 25	4 4 7 10 1 0 0	313.00 82,000.00 50.00 960.00 880.00 2.00 35.00	Stall SF LF LF LF CSF EA	\$11.00 \$0.50 \$29.61 \$17.25 \$28.50 \$1,200.00 \$985.00	OP - Maintenance OP - Maintenance IN - Beyond Rated Life OP - Security OP - Security IN - Beyond Rated Life	Priority 4 Priority 4 Priority 4 Priority 4 Priority 4 Priority 3 Priority 3 Priority 3 Priority 4	\$0 \$0 \$0 \$0 \$0 \$0 \$2,400 \$34,475	\$10,329 \$164,000 \$1,481 \$16,560 \$25,080 \$2,400 \$0 \$17,300
G2041 G2041 G2041 G2045 G2052 G30 G3013 G40 G4021	Driveway Asphalt Paving Driveway Asphalt Paving Driveway Asphalt Paving Chain Link Fence, 6-Foot High 3-Foot High Chain Link Fence, Install New Chain Link Fencing G2045 Site Furnishings Establishment of Ground Cover at Bare Areas SITE CIVIL/MECHANICAL UTILITIES Well Pump 30 HP, 100 to 300 Gpm  SITE ELECTRICAL UTILITIES Landscape Ground Mounted Uplight Fixture	Staff Parking Lot & Drives Staff Parking Lot & Drives Security Fence Chain link fence at East Boundary Chain Link Fence Smoker Den Landscape turf around building perimeter walls Well Pump, 400GPM	south staff parking Site northeast Site northeast Site northeast Wing C south Courtyard East site Boundry Boundry at Deer Park Along east staff parking areas Bulding perimeters  Geothermal Wells	Restripe Parking Lots Seal Coat Asphalt (Up to 10000 SF)  Replace Security Fence Replace Chain link fence at East Boundary Replace Chain Link Fence  Replace Smoker Den  Replace Landscape turf around building perimeter wails  Replace Well Pump, 400GPM  Replace Convert Entry Flag Pole Lights to	7 5 20 30 30 15 25	4 4 7 10 1 0 0	313.00 82,000.00 50.00 960.00 880.00 2.00 35.00	Stall SF LF LF LF CSF EA	\$11.00 \$0.50 \$29.61 \$17.25 \$28.50 \$1,200.00 \$985.00	OP - Maintenance OP - Maintenance IN - Beyond Rated Life OP - Security OP - Security IN - Beyond Rated Life	Priority 4 Priority 4 Priority 4 Priority 4 Priority 4 Priority 3 Priority 3 Priority 3 Priority 4 Priority 4  Priority 4  SUB-TOTALS	\$0 \$0 \$0 \$0 \$0 \$0 \$2,400 \$34,475 \$0 \$39,250	\$10,329 \$164,000 \$1,481 \$16,560 \$25,080 \$2,400 \$0 \$17,300

Current Replacement Value \$56,000,000 Date Completed: October 18, 2013

**Property Name: Vermont Veterans' Home** 

EMG Project Number: 106686.13R-001.305

			A	bbrevi	iated Accessibility Checklist	
	Building History	Yes	No	Unk	Comments	Field Instructions
1	Has an ADA survey previously been completed for this property?	<b>~</b>			With each current renovation	NOTE: Questions 1-6 are to be answered by the POC and are also on the Pre-Survey Questionnaire. If the POC does not complete this section of the PSQ, then the answers should be "Unk".
2	Have any ADA improvements been made to the property?	<			Continuously	
3	Does a Transition Plan / Barrier Removal Plan exist for the property?		<b>✓</b>			
4	Has building ownership or management received any ADA related complaints that have not been resolved?		<b>√</b>			
5	Is any litigation pending related to ADA issues?		<b>✓</b>			
	Parking	Yes	No	NA	Comments	Field Instructions
1	Are there sufficient accessible parking spaces with respect to the total number of reported spaces?	<b>*</b>			<ol> <li>Total # marked stalls: 313</li> <li>Total # accessible car: 12</li> <li>Total# van/bus accessible: 2</li> </ol>	NA if ADA parking not required. The space must have pavement markings, sign, have access aisle and be relatively level to count.  See special count requirements for Outpatient Hospitals and Rehab/PT Outpatient facilities in the Hot Sheet above
2	Are there sufficient van-accessible parking spaces available?	~				NA if ADA parking not required. The space must have pavement markings, van signage, access aisle, be relatively level and meet size requirements to count. One of out every six ADA stalls should be van accessible.

			A	bbrevi	ated Accessibility Checklist	
	Parking (cont.)	Yes	No	NA	Comments	Field Instructions
3	Are accessible spaces marked with the International Symbol of Accessibility? Are there signs reading "Van Accessible" at van spaces?	<b>~</b>				NA if ADA parking not required. Stall should be painted with Wheelchair symbol. Each van stall should be signed with "Van Accessible".
4	Is there at least one accessible route provided within the boundary of the site from public transportation stops, accessible parking spaces, passenger loading zones, if provided, and public streets and sidewalks?	<b>✓</b>				NA if accessible route not required. Accessible route must have no significant changes in elevation or excessive running slopes (5% or less)/cross slopes (2% or less).
5	Do curbs on the accessible route have depressed, ramped curb cuts at drives, paths, and drop-offs?	<b>✓</b>				NA if no curbs. Built-up ramps are non- compliant if they encroach on parking stall or access aisle.
6	If required does signage exist directing you to accessible parking and an accessible building entrance?	<b>✓</b>				Signage typically only required if the main entrance is not accessible, or the parking spaces are not located near the main entrance. For 2010, 60% of building public entrances are required to be accessible.
	Ramps	Yes	No	NA	Comments	Field Instructions
1*	Do all ramps along accessible path of travel appear to meet slope requirements? (1:12 or less)	<b>*</b>				NA if no ramps. Do not measure or calculate slope. NO if unsure.
2	Are ramps that appear longer than 6 ft complete with railings on both sides?	<b>√</b>				Under ADA, a "ramp" must have handrails and is between 5% and 8.33% with a horizontal projection of six feet or longer. Slopes cannot exceed 8.33%(1:12) for any distance.
3	Does the width between railings appear at least 36 inches?	<b>&gt;</b>				NA if no ramps. Do not measure height or size of railings.
4	Is there a level landing for approximately every 30 ft horizontal length of ramp, at the top and at the bottom of ramps and switchbacks?			✓		NA if no ramps. Each landing must be level for five feet and provide 60" turn radius if a turn is required.

			A	bbrevi	ated Accessibility Checklist	
	Entrances/Exits	Yes	No	NA	Comments	Field Instructions
1	Do all required accessible entrance doorways appear at least 32 inches wide and not a revolving door?	✓				For 2010, 60% of building public entrances are required to be accessible. If a building has two public entrances both should be compliant. Service entrances or employee entrances should not be considered.
2	If the main entrance is inaccessible, are there alternate accessible entrances?			✓		NA if main entrance is accessible. If not accessible, check for directional signs to accessible entrance(s).
3	Is the door hardware easy to operate (lever/push type hardware, no twisting required and not higher than approximately 48 inches above the floor)?	<b>*</b>				Latches that require thumb-press or grasping are not compliant.
	Paths of Travel	Yes	No	NA	Comments	Field Instructions
1	Are all paths of travel free of obstruction and wide enough for a wheelchair (appear at least 36 inches wide)?	<b>*</b>				NOTE: For accessing areas of public accommodation. Includes access to all facilities/amenities at hotels/resorts/public golf clubs. Generally excludes mezzanine or employee only areas.  Path of travel is for the "accessible routes". It includes interior common areas and EXTERIOR areas, such as route from parking to entrance and to any public amenities such as pools, fitness centers, etc.
2	Are wheelchair-accessible facilities (toilet rooms, exits, etc.) identified with signage?	<b>√</b>				Signage required only if some are accessible and some are not. Includes designation and directional signage. Must contain raised letters, Braille and international symbol of accessibility
3	Is there a path of travel that does not require the use of stairs?	<b>~</b>				Confirm at least one accessible route to all facilities/amenities at hotels/resorts/public golf clubs.


			A	bbrevi	ated Accessibility Checklist	
	Elevators	Yes	No	NA	Comments	Field Instructions
1	Do the call buttons have visual and audible signals to indicate when a call is registered and answered when car arrives?		✓			Lamp should turn on/off when call button is pressed/car arrives
2	Are there visual and audible signals inside cars indicating floor change?		<b>√</b>			Listen for audibles at each floor change when inside car. The visually impaired must be able to count floor changes. An audible that 'speaks' the floor # is also acceptable.
3	Are there standard raised and Braille marking on both jambs of each hoist way entrance as well as all cab/call buttons?		<b>✓</b>			All markings at lobby and the hoist way should be raised with Braille also.
4	Do elevator doors have a reopening device that will stop and reopen a car door if an object or a person obstructs the door?	<b>√</b>				Electronic or mechanical acceptable.
5	Are elevator controls low enough to be reached from a wheelchair (appears to be between 15 and 48 inches)?	✓				
6	If a two-way emergency communication system is provided within the elevator cab, is it usable without voice communication?	<b>*</b>				Must be push button operation with lamp indicating message sent/received in addition to voice communication. Handheld devices and cabinets that require twisting or pinching of hand to open are non-compliant.
	Toilet Rooms	Yes	No	NA	Comments	Field Instructions
1	Are common area public restrooms located on an accessible route?	<				NOTE: This section covers Common Area Public Restrooms ONLY. It does not cover Apartment Units, Hotel Guestrooms, Nursing Home Resident Rooms, Retail tenant restrooms, or employee restrooms. Enter NA for all questions if there are no applicable restrooms. If representative sampling of the restrooms was necessary indicate which restrooms were visited under Comments.

			A	bbrevi	ated Accessibility Checklist	
	Toilet Rooms	Yes	No	NA	Comments	Field Instructions
2	Are pull handles push/pull or lever type?	<b>√</b>				
3	Are there audible and visual fire alarm devices in the toilet rooms?	<b>√</b>				NA if the building does not have a central fire alarm system. NA if no alarm devices are provided within the toilet room.
4	Are toilet room access doors wheelchair-accessible (appear to be at least 32 inches wide)?	<b>✓</b>				
5	Are public restrooms large enough to accommodate a wheelchair turnaround (appear to have 60" turning diameter)?	<b>~</b>				
6	In unisex toilet rooms, are there safety alarms with pull cords?			<b>✓</b>		NA if the building does not have pull cord alarm system. Typically only applies to healthcare properties.
7	Are toilet stall doors wheelchair accessible (appear to be at least 32" wide)?	<				NA if the bathroom is not divided into stalls.
8	Are grab bars provided in toilet stalls?	✓				Requires two, one at side wall and one at rear.  Do not comment on height or length.
9	Are sinks provided with clearance for a wheelchair to roll under (appear to have 29" clearance)?	<b>√</b>				If multiple sinks, only one is required to have adequate clearance, but it must be located outside of a toilet compartment.
10	Are sink handles operable with one hand without grasping, pinching or twisting?	<b>✓</b>				Knob or atypical handles that cannot be operated with a closed hand are non-compliant
11	Are exposed pipes under sink sufficiently insulated against contact?	✓				NA if the pipes are not exposed.

			A	bbrevi	ated Accessibility Checklist	
	Guest Rooms	Yes	No	NA	Comments	Field Instructions
	How many total accessible sleeping rooms does the property management report to have? Provide specific number in comment field.					NOTE: This section is NA if the property is not Hotel/Healthcare.  If applicable, respond to each item under
1	Are there sufficient reported accessible sleeping rooms with respect to the total number of reported guestrooms? See attached hot sheet.			✓	All residential rooms are considered accessible	Comments  The answer to each question is based on response from the POC and the room requirements listed in the Hot Sheet. You do not need to confirm the POC's statements.
						Indicate if grab bars, lever hardware, etc, are observed in the ADA units you visit.
2	How many of the accessible sleeping rooms per property management have roll-in showers? Provide specific number in comment field.  Are there sufficient reported accessible rooms with roll-in showers with respect to the total number of reported accessible guestrooms? See attached hot sheet.				Most, except for special disability tubs	
3	How many assistive listening kits and/or rooms with communication features are available per property management?  Provide specific number in comment field.  Are there sufficient reported assistive listening devices with respect to the total number of rooms? See attached hot sheet.			<b>*</b>	All residential rooms have nurse call stations	For hotel, compare number of rooms for hearing impaired + hearing impaired kits reported by POC against the Hot Sheet to answer this question
	Pools	Yes	No	NA	Comments	Field Instructions
1	Are public access pools provided? If the answer is no, please disregard this section.			<b>√</b>		NOTE: This section is NA unless recreation facilities are provided for public use(hotel/resort/golf club)

			A	bbrevi	ated Accessibility Checklist	
	Pools (cont.)	Yes	No	NA	Comments	Field Instructions
2	How many accessible access points are provided to each pool/spa? Provide number in comment field.  Is at least one fixed lift or sloped entry to the pool provided?			<b>*</b>		At least one fixed lift or sloped entry required. A portable lift is compliant only if in use prior to 3/15/2012. Pools with 300' or more of pool wall need two means of entry (second means may be transfer wall, transfer system or pool stairs). Spa and wading pools must meet this requirement as well. If spa pools are clustered, at least one should have an accessible means of entry.
	Play Area	Yes	No	NA		Field Instructions
1	Has the play area been reviewed for accessibility? All public playgrounds are subject to ADAAG standards.			<b>√</b>		NOTE: This section is NA unless recreation facilities are provided for public use(hotel/resort/golf club/retail)
	Exercise Equipment	Yes	No	NA	Comments	Field Instructions
1	Does there appear to be adequate clear floor space around the machines/equipment (30" by 48" minimum)?	<b>✓</b>				<b>NOTE:</b> This section is NA unless recreation facilities are provided for public use(hotel/resort/golf club)

<sup>\*</sup>Based on visual observation only. The slope was not confirmed through measurements.



## Vermont Veterans Home Utility Bills By Month FY 2012 & 2013

	Electric		OII IIC	Prop	ane
2)	FY 2012 % FY 2013	FY 2012	FY 2013	FY 2012	FY 2013
July	23,961.99 30+32,124.03	25,502.65	24,178.64	3,634.14	3,613.49
August	25,671.51 26+32,504.42	}		3,482.53	4,221.51
September	26,407.322/ 34,230.11	25,291.12	26,105.40	4,593.10	3,231.71
October	26,012.76 th 30,162.77	22,515.57	26,067.87	3,593.23	2,076.39
November	28,105.89 4- 27,058.61	24,939.43	47,762.47	5,815.62	3,869.50
December	32,658.666 - 30,792.15	47,452.75	23,575.64	6,254.29	4,646.69
January	38,652.3214-33,150.11	24,725.09	47,990.61	3,577.56	4,836.58
February	32,717.91 3+ 33,619.80	51,208.27	25,504.15	5,378.23	2,640.03
March	30,312.69 🕯 29,926.78	25,969.68	46,234.19	6,481.52	3,288.41
April	32,674.48 4+ 33,906.16	26,350.50	22,391.23	255.36	5,363.00
May	29,514.74 12 - 25,918.21	24,016.50	21,606.35	7,464.93	2,907.61
June	33,091.58 - 33,070.69	21,403.35	22,342.64	2,012.56	3,438.52
Total	359,781.85 376,463.84	319,374.91	333,759.19	52,543.07	44,133.44

	/eterans H		1	Propane			Electricity		100	Gasoline			Diesel		
FY Year	gallons	Total Cost		units	Total Cost		KWH	Total Cost		gallons	Total Cost	4.0	gallons	Total Cost	
2002	202017	\$ 170.134.46	\$0.84	19651.6	\$ 13.871.44	\$0.71	1469363	\$128,514.02	\$0.09		2 2		-	58 8	255
2003	212721	\$ 180,268.60	\$0.85	1 10 44 4	\$ 17,225.83	*********		\$134,160.79	\$0.09						
2004	180804		\$0.89	101.0	\$ 20,709.33	\$1.06		\$132,332.40	\$0.09						1
2005	156383	\$ 206,688.45	\$1.32	21876.2	\$ 28,807.47	\$1.32	1480464	\$125,892.05	\$0.09						
2006	154229		\$1.89	22671.2	\$ 37,612.87	\$1.66		\$142,743.69	\$0.09	2511.83	\$ 5,848.70	\$2.33	179.7	\$ 371.91	
2007	178929	\$ 334,612.95	\$1.87	19590.7	\$ 39,975.08	\$2.04	276	(4)	\$0.09	2633.6	\$ 6,461.91	\$2.45	502.1	\$1,082.15	
2008	154056	\$ 428,029.31	\$2.78	17812.8	\$ 57,390.13	\$3.22	1583552	\$139,986.24	\$0.09	3152.97	\$ 9,286.15	\$2.95	299.09	\$1,104.07	15 6
2009	163001	\$ 325,633.34	\$2.00	24824.4	\$ 70,407.23	\$2.84	Separate	Report		3556.7	\$ 9,865.14	\$2.77	N/A	N/A	
2010	113766	\$ 264,975.64	\$2.33	21222.3	\$ 56,181.34	\$2.65	2474129	\$241,339.90	\$0.10	3214.703	\$ 8,254.64	\$2.57	34	V10-14-7	
2011	110433	\$ 314,252.73	\$2.85	25009.7	\$ 63,199.43	\$2.53	2905392	\$307,356.27	\$0.11	3361.37	\$10,348.74	\$3.08			
2012	95237	\$ 319,374.91	\$3.35	20140.8	\$ 52,071.09	\$2.59	2990527	\$335,977.65	\$0.11	3345.958	\$11,865.79	\$3.55	1234.8	\$5,053.98	\$4.09
2013	104119	\$ 334,759.19	\$3.22	26313.5	\$ 44,133,45	\$1.68	3208977	\$376,111.42	\$0.12	3999.384	\$14,061.46	\$3.52	710.7	\$2,857.80	\$4.02
Totals	1825695	\$3,330,720.89		256769	\$501,584.69	tet d	13229219	\$942,335.90		25776.515	\$75,992.53		980.89	\$2,558.13	

336-2013 154729

95% 1362269



## Vermont Department of Public Safety DIVISION OF FIRE SAFETY



Office of the State Fire Marshal, State Fire Academy and State Haz-Mat Team firesafety.vermont.gov

☐ Barre Regional Office

1311 U.S. Route 302 - Berlin, Suite 500

Barre, VT 05641

[phone] 802-479-4434

[fax] 802-479-4446

☑ Rutland Regional Office 56 Howe Street, Building A, Suite 200 Rutland, VT 05701-3449 [phone] 802-786-5867 [fax] 802-786-5872 ☐ Williston Regional Office 372 Hurricane Lane, Suite 102 Williston, VT 05495-2080 [phone] 802-879-2300 [fax] 802-879-2312

Hazard Index:

Level 3

☐ Springfield Regional Office 100 Mineral Street, Suite 307 Springfield, VT 05156-3168 [phone] 802-885-8883 [fax] 802-885-8885

t and an		[ Carry	002 100 0012	Į	MI COL OI O LOIL		Irani con co	0 0000
			FIRE INSPE	CTION RES	ULTS			Site Id: 3862
Structure Inform	nation							
Name:	VERMONT VET CAP 185/6)	ERANS' HOME	44-50-42 (LIC	Address:	325 NORTH	AVE (NH/RCH)		
Structure Id:	3862		92		BENNINGTO	N, VT 05201		*
Owner Informat	ion							
Owner:	VERMONT VET	<b>ERANS' HOME</b>	(N 36219)	Address:	325 NORTH	AVENUE		
Phone:	802-442-6353				BENNINGTO	N, VT 05201		
Building Descri	ption							9
Risk Index:	M1	Smoke Det:	Yes	Occupants:	185	Units:		
Const Type:	2B	CO Detect:	Yes	Stand Pipe:	7.83	Floors:		
Occ Type:	12	Fire Alarm:	Automatic	Sprinkler:	Complete	Sq Feet:	120000	
Heating:	Ground Water H	eat Pump			25. 25.			
Project Descript	tion			7	**			- 1
Name:	ANNUAL INSPE	CTION						
Type:	<b>Building Project</b>	Received:	01/13/1999	Workitem Id	: 156186			
'¬spection Deta	il							
Insp Date:	04/01/2013	Insp Type:	Annual Inspect	ion And Test	Violations:			

### Violations and Notes

Comply By:

Inspector:

05/15/2013

The annual inspection was conducted on 04-01-2013 the following violations noted.

1. A GFCI outlet in the B wing East bath area did not work.

FRANCIS CIOFFI (S 48438)

2. O2 cylinders (2) in the A wing O2 storage area were not properly secured.

Occ Granted:



AGENCY OF HUMAN SERVICES

DEPARTMENT OF DISABILITIES, AGING AND INDEPENDENT LIVING

Division of Licensing and Protection

103 South Main Street, Ladd Hall

Waterbury VT 05671-2306

http://www.dail.vermont.gov

Voice/TTY (802) 871-3317

To Report Adult Abuse: (800) 564-1612

Fax (802) 871-3318

April 29, 2013

Ms. Melissa Jackson, Administrator Vermont Veterans' Home 325 North Street Bennington, VT 05201-5014

Provider #: 475032

Dear Ms. Jackson:

Enclosed is a copy of your acceptable plans of correction for the Life Safety Code survey conducted on April 1, 2013. Please post this document in a prominent place in your facility.

We will follow-up to verify that substantial compliance has been achieved and maintained. If we find that your facility has failed to achieve or maintain substantial compliance, remedies may be imposed.

Sincerely,

Pamela M. Cota, RN

ulaMCotaRN

Licensing Chief

PC:j1

Enclosure



ND PLAN D	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	N 25 (27)	LE CONSTRUCTION		PLETED .
		475032	R. WING_		04/	01/2013.
	ROVIDER ON SUPPLIER IT VETERANS HOME		1 3	REET ADDRESS, ONY, STATE MIP CODE 138 NORTH STREET RENNINGTOH, VT 05201		100
(XA) ID PRETIX YAG	. (EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION	PRIEFIX	PROVIDER'S PLAN OF CORRE (EACH CORRECTIVE ACTION SI CHOSS-REFERENCED TO THE AP DEFICIENCY)	LOULD BE	COMPLETION
K 000	inspection was con	TS  bin-site Life Safety Code  spleted by the Division of Fire The following is a regulatory	K 000	The filing of this plan of correction do nonstitute an admission of guilt, Van Home ("the Provider") submits this P correction ("POC") in accordance with regulatory requirements.	anerelevine	
K 130 69≕D	NFFA 101 MISCEI	LANEOUS CIENCY NOT ON 2786	K 130	K130  The exygen tanks on the A wing were when noted not to be.	e secured	4/26/1
	Based on observa	is not met as evidenced by: tlon, the facility falled to assure setaty Code requirements are ten storage and/or electrical	  - 	The GFC outlet on the B wing was in In good working order.  All GFC outlets were audited to ensure all in good working order.  Supervisors or designee will conduct audits of oxygen tanks on all units to	ire that they	
	wiring in 2 total are include.  1. Per observation the Maintenance S tanks were found in	as of the building. Findings on 4/1/13, accompanied by uppervisor, unsecured oxygen the 'A' wing oxygen storage tenks were not secured per		hey are secured.  Nursing staff will have aducation on oxygen tanks beginning on 4/16/13.  The Maintenance Director or design random weekly audits of oxygen tank that they are secured. And will condition of the conditions with routine maintenance.	securing see will conduct this to chause fuct audits of	ļ.,
	2. Per observation the Maintenance S Fault Circuit Intern	on 4/1/13, accompanied by upprvisor, a GFCI (Ground upprvisor, a GFCI (Ground upport) outlet was not properly ving in the East Bath area.	·   · ·	Data from the audits will be brought Assurance meeting every other more months or until the committee deter resolution.  The administrator is ultimately resp ensure oxygen tanks are secure an are in good working order.	onsible to	
, .				Ki30 POCaccepted 4/29/13 FCIOFFI/ PMC	3	
. [			į .			

Any deficiently statement ording with an extensi () depotes a deficiency which the institution may be excused from connecting providing it is determined that other safeguards provide authority protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclossible to days following the date of sources whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclossible 14 days following the date these documents are made available to the facility. If deficiencies are used, an approved plan of correction is requisite to continued program participation.

FORM DMS-2587(02-98) Provious Vanions Obsolete .

Event ID: VG4P21

Fee Foy JO: 470012

If continuation wheet Page 7 of 7

## FACILITY CONDITION ASSESSMENT

AND ENERGY AUDIT

106686.13R-001.305

# APPENDIX E: PRE-SURVEY QUESTIONNAIRE





Person completing questionnaire:

Have investments been made in energy

or water conservation?

10

## FACILITY CONDITION ASSESSMENT: PRE-SURVEY QUESTIONNAIRE

This questionnaire must be completed by the property owner, the owner's designated representative, or someone knowledgeable about the subject property. The completed form must be presented to EMG's Project Manager on the day of the site visit. If not completed, EMG's Project Manager will require additional time during the on-site to complete the form with the representative. This questionnaire will be included as an exhibit in EMG's final Facility Condition Report.

	Associat	ion with property:	DIR ENVIRONMENTAL DERNICES
	Length of associat	ion with property:	7 12+
		Date Completed:	
		Phone Number:	802 447 6528
		Property Name:	VERMINT VETERANS FORME
	EMC	G Project Number:	
			he best of your knowledge and in good faith. Please provide additional details in the on for any Yes responses.
	Inspections	DATE LAST INSPECTED	LIST ANY OUTSTANDING REPAIRS REQUIRED
1	Elevators	ANNIAC 8-13	10
2	HVAC, Mechanical, Electric, Plumbing	1/4 PREN MAN	AT FILES
3	Life-Safety/Fire	2/26/13	STARE FIRE MARGHAR
4	Roofs	8/-/13	PART OF ARCH ENVELOPE ASSETS.
	QUESTI	ON	RESPONSE
5	List any major capi within the last three		SEE ATTREHES AS PREMUGATED IN YELLES
6	List any major capi planned for the nex		BONGE GENERATOR 8,000 PANING 38,000 ON MAINTEN 1.2M PLOCE MACHINE 8,000 NOWS REMED 1.2M PLOCE MACHINE 20,589
7	What is the age of	the roof(s)?	B/e-2012 A/-2008 FEW-/DIET NEX-2011 D-2010
8	Are there leased are facility?	eas from or to this	1 Americ Fiers
9	Have any ADA studimprovements been		THRESHOLDS SEVERAL PRICES REDUCES

COUPLES WHITE EFF VI FOR PUMPS AS FAR.

TRIALING PLUSH VALVES TOTO

Mark the column corresponding to the appropriate response. Please provide additional details in the Comments column, or backup documentation for any Yes responses. (NA indicates "Not Applicable", Unk indicates "Unknown") RESPONSE QUESTION COMMENTS Y N Unk NA EAST - OLDEST SECTION, INEFFICIENTES HEAT COCKING PLUMBING SIFFICULTIES CONFINED SPIKE, MOLD BASE CRAW ST Are there any unresolved building, K 11 fire, or zoning code issues? Are there any "down" or unusable CRAWL STREE UNDER EAST = 12 areas? Why? Are there any problems with 13 erosion, stormwater drainage or K areas of paving that do not drain? Is the property served by a private K 14 water well? Is the property served by a private 15 septic system or other waste X, treatment systems? Are there any problems with WARE INFILTRATION. BREEMENT 火 foundations or structures? Is there any water infiltration in 17 K basements or crawl spaces? Are there any wall, or window 18 leaks? Are there any roof leaks? 19 20 yes on Koors LINTER HEMENT Is the roofing covered by a warranty 20 X or bond? If so, how long? Are there any poorly insulated 2 21 areas? Is Fire Retardant Treated (FRT) X 22 plywood used? Is exterior insulation and finish 23 X system (EIFS) or a synthetic stucco finish used? NEW SERVICE + TRANSFERMER 2010 ADMIN DISTRIBUTION IN GUESTION Are there any problems with the 24 3 utilities, such as inadequate capacities? Are there any problems with the 25 landscape or irrigation systems? Has a termite/wood boring insect 26 inspection been performed within the last year? Do any of the HVAC systems use R-27 X 11, 12, or 22 refrigerants? REMEDITION ONGOING Has any part of the property ever 28 Q contained visible suspect mold growth?

Mark the column corresponding to the appropriate response. Please provide additional details in the Comments column, or backup documentation for any Yes responses. (NA indicates "Not Applicable", Unk indicates "Unknown") QUESTION RESPONSE **COMMENTS** Y Unk NA PRESIMINARY FORM AS PREV MAINT, BEING EVAL BY ARCH. MOIS CLUING BASEMENT Is there a mold Operations and X 29 Maintenance Plan? Have there been indoor air quality 30 k or mold related complaints from users or tenants? Is polybutylene piping used? 31 3 MINUR LEAKS, NO PRESS PROPES Are there any plumbing leaks or 32 K water pressure problems? NEW LINES UNDERGREENS + Are there any leaks or pressure X 33 2010 INTERIOR problems with natural gas service? 2010 New Are any site electrical service 34 transformers out of date or inadequate for demand? Does any part of the electrical 35 X system use aluminum wiring? 2010 NEW Is the electrical main service switch 35 gear and distribution Does any electrical distribution or 36 branch wiring inside the electrical X service use aluminum wiring? Are there any recalled fire sprinkler 37 X heads (Star, GEM, Central or Omega)? Is there any pending litigation X 38 concerning the property? Has the management previously X 39 completed an ADA review? PREEXISTING Have any ADA improvements been & 38 made to the property? Does a Barrier Removal Plan exist 40 K for the property? Has the Barrier Removal Plan been 41 approved by an arms-length third x party? Has building ownership or 42 × management received any ADA related complaints? Does elevator equipment require X 43 upgrades to meet ADA standards? LUDKINGETO OPGRADE FM MERCO Are there any problems with X 44 SOB/LES exterior lighting?

de	QUESTION		RESI	PONSE	6	COMMENTS
		Υ	N	Unk	NA	
45	Are there any other significant issues/hazards with the property?		×			**
46	Are there any unresolved construction defects at the property?			K		PENSING ENNELLIE EVAL

R.Stante	12/8/13	
Signature of person interviewed or completing form	Date /	

**©** 

28

AND ENERGY AUDIT

106686.13R-001.305

## APPENDIX F: ENERGY CONSERVATION MEASURES



	UIC			Replace Extern	nal Windows		
	EAE2	Details: Single Glazed Win	dows Along Cor	ridors along Chapel and	Social Hall		
				ENTER EXISTING CON			
Existing and Pro	posed Wind	ow Properties			Existing & Proposed Air Leakage Through Windows		
Total Sq.Ft window a	rea:		720	sq.ft	Insert Existing Estimated Air Change Rate/Hr (ACH 1):	1.00	
Approximate numbe	r of windows:		18		(Existing Air Changes Per Hour, 3 is very leaky and 0.35 ideal) Insert Proposed Estimated Air Change Rate/Hr (ACH 2):	0.85	
Total existing window	w area:		720	Sq.Ft	Estimated Space Volume Under Consideration	82,320 Cu. Ft	
Select The Existing W	/indow Type			Metal Frame & Single Glazing	(Select)		
Existing U-value of w	rindow: (1/R)		1.31	Btu/ ft².°F·h	<del></del>		
Select Property Loca New U-value with Do AHRAE 90.1 Recommended V	ouble pane Low	E window: (1/R)	Zone-6 0.31	(Select) Btu/ft²-°F-h	Is the Property Cooled ?	Yes (Select)	
		WINTER			SUMMER		
Select Type of Heatir	ng Fuel		No. 2 Oil	(Select)	Select Type of Cooling Fuel:	Electric (Default)	
Net heating plant & o	distribution syste	em efficiency:	0.60	%	Cooling Plant Efficiency (EER):	10.00 EER	
Annual Heating Hou	rs:		2,800	Hrs	Annual Cooling Hours:	400 Hrs	
Estimated Total Anni Windows	ual Input Heatin	g Energy Savings By Replacing	17.52	Gallons	Annual Total Input Cooling Fuel Savings During Summer Season By Replacing Windows	29 kWh	
Estimated Total Anni Controlling Air Leaka		g Energy Savings Achieved By dows	254	Gallons	Estimated Total Annual Input Cooling Energy Savings Achieved By Controlling Air Leakage Through Windows	435 kWh	
Estimated Total Inpu Windows	t Heating Fuel Sa	avings From Replacing	271	Gallons	Estimated Total Input Cooling Fuel Savings From Replacing Windows	464 kWh	
				ENERGY & COST AN	NALYSIS		
Insert Cost of Heatin Insert Cost of Coolin	•		\$3.43 \$0.12	\$/Gal \$/kWh	Annual Heating Cost Savings: Annual Cooling Cost Savings:	\$929.27 \$\$ \$54.18 \$\$	
Total Annual Cost Sa	ivings		\$993		Total Annual Cost Savings From Heating & Cooling:	\$983 \$\$	
Cost of window upg	rade:		\$9,900		Estimated Annual O&M Savings	\$10	
Simple payback:			9.97	Yrs	Type of Recommendation Capital Cost ECM Recom	mendation	

Disclaimer: PREPARED BY EMG. JANUARY 2012, INFORMATION CONTAINED IN THIS DOCUMENT IS PRIVILEGED AND CONFIDENTIAL "TRADE SECRET" AND IS THE SOLE PROPERTY OF EMG CORP. THIS MATERIAL MUST BE CONSIDERED PRIVELEDGED AND CONFIDENTIAL BY ALL PARTIES PRIVY.

#### ECM DESCRIPTION:

Windows play a major role in the energy use and comfort of an interior space. In the winter, heat in a room is lost when cold outside air infiltrates around the edges of windows. Heat also can be lost by conduction directly through the pane, even if the window fits tightly. Windows with insulated panes, such as those filled with Argon address this issue, while proper caulking and sealant address the infiltration issue. The cold drafts and the chilly windowpane make the room uncomfortable. Windows also can help to heat a room by letting the sun's rays enter. While this solar radiation is beneficial in the winter, it can be a major source of discomfort in hot, summer climates. Energy Star rated windows with Low-E glazing are designed to keep the solar heat gain minimized during the summer months. Choosing a replacement window that fits properly has the desired U-value, and proper glazing characteristics is critical to energy conservation through window upgrades.

#### Summary:

Initial Investment: \$9,900 Simple Payback 9.97 Yrs

Annual Energy Cost Savings: \$993.29

Property of FMG Corp. All Rights Reserved

UIC		Replace Ineffic	cient HVAC Package System	perty of Ewig Corp. All Rights Reserved
EAH12	Details: Replace Roof Top Unit at Administration	1	<u> </u>	
Estimated	Annual Cooling Hours:	400 Hrs	Estimated Annual Heating Hours:	2,800 Hrs
Are The Co	ondensing Units Being Replaced	Yes	Existing Type of Heating Fuel:	Propane
	Existing Cooling System		Existing Heating System	
No. of Coo	ling Plants To Be Replaced:	1	No. of Furnaces To Be Replaced:	1
Input the E	Btu/Hr of the air conditioner:	60,000	Input the MBH Rating of the Furnace:	300 MBH
Input Exist	ing EER of the Air Conditioner:	7.50	Input Existing AFUE for the Furnace:	<del>70%</del> %
Estimated (For All Units)	Current Annual Energy Consumption For Cooling:	3,200 kWh	Estimated Annual Current Energy Consumption For Heating: (For All Units)	13,115 Gallons
	Proposed Cooling System		Proposed Heating System	
Input the E	Btu/Hr of the Proposed Air Conditioner:	<b>60,000</b> Btuh	Proposed Furnace: Propane Fired -300MBH	
Input EER o	of the Proposed Air Conditioner:	13.00	Input AFUE for the Proposed Furnace:	90% %
Estimated (For One Unit)	Annual Energy Consumption With New AC's	1,846 kWh	Estimated Annual Energy Consumption With New Furnace (For One Unit)	10,200 Gallons
	Energy & Cost Savings From New Cooling Syste	m	Energy & Cost Savings From New Heating System	
Estimated (Total)	Annual Energy Savings From New Cooling System:	1,354 kWh	Estimated Annual Energy Consumptions From New Heating System:	10,200 Gallons
Average El	ectric Rate:	\$0.12 \$/kWh	Average Heating Fuel Cost For New Furnace:	\$2.12 \$/Gal
Estimated	Annual Cost Savings From Cooling:	\$158	Estimated Annual Cost Savings From Heating:	\$6,165 \$\$
	Cost of New Condensing Unit:	\$4,450	Estimated Cost of New Furnace Unit: (Material + Installation+Labor)	\$3,305 \$\$
	Cost of New Evaporator Coils In Furnace: tallation+Labor)	\$1,145	Estimated Total Cost of New Furnace Unit: (Material + Installation+Labor)	\$3,305 \$\$
Total Estim	nated Installed Cost For A New Air Conditioning System	n Setup + New High Efficiency F	\$8,900 \$\$	
Estimated	Total Energy Cost Savings From New HVAC System:	\$6,323 \$\$ Est	imated O&M Savings: \$316 Total Annual Savings:	\$6,639 \$\$
Estimated	Simple Pay Back Period:		1.34 Years	
		Type of Recommendation	Capital Cost ECM Recommendation	

Disclaimer: PREPARED BY EMG. JANUARY 2012, INFORMATION CONTAINED IN THIS DOCUMENT IS PRIVILEGED AND CONFIDENTIAL "TRADE SECRET" AND IS THE SOLE PROPERTY OF EMG CORP. THIS MATERIAL MUST BE CONSIDERED PRIVELEDGED AND CONFIDENTIAL BY ALL PARTIES PRIVY.

	T	5 1		of EMG Corp, All Rights Reserved
UIC		•	t Linear Fluorescent Lamps	
EAL2-S	Details: Replace Remain	ing T-12s Adding Motion Se		
		LAISTING LIGHTING SYS	stem .	
Current Type of Lamp:	(Select)	F42T12	F22T12M F44T12	F22T12M
Current Annual Avg Hr	rs of Operation:	<b>8,760</b> hrs	2,000 hrs 1,500	hrs <b>8,760</b> hrs
Existing Number of Fix	tures:	800	250 125	175
		Proposed Lighting S	ystem	
Proposed Lamp Replac	cement: (Select)	F42T8N	F22T8 F44T8N	F22T8
Proposed Annual Avg.	Hours of Operation	6,000 hrs	2,000 hrs 1,500	hrs <b>1,000</b> hrs
Proposed Number of F	ixtures:	800	250 125	175
Proposed Lighting Con	itrol: (Select)	Ceiling Mounted Occupancy Sensor	Light Switch Light Switch	Wall Mounted Occupancy Sensor
No. of Lighting Control	ls:	50 Qty	0 Qty 0	Qty 175 Qty
		Energy Saving Calcu	lation	
Estimated Annual Ene	ergy Savings	254976.00 kW	n 9000.00 kWh 8625.00	kWh 72408.00 kWh
Are The Ballast's Bei	ng Replaced: (Select)	Yes	Yes Yes	Yes
Estimated Material Co	st:	\$42,750 \$\$	\$11,250 \$\$ \$6,875	\$\$ \$17,500 \$\$
Estimated Labor Cost:		\$35,983 \$\$	\$10,000 \$\$ \$5,000	\$\$ \$20,939 \$\$
Estimated Total Mater	ial Cost:	\$78,375 \$\$	Estimated Total Labor Cost:	\$71,921
Electric Rate:		\$0.12 \$\$	Total kWh Saving	345,009 kWh
Total Initial Investmen	nt For Retrofit	\$150,296 \$\$	Estimated Annual Cost Savings	\$40,281 \$\$
Simple Pay back Period	d	3.73 Yrs		
	Type of Recomm	nendation	Capital Cost ECM Recommendation	1

Disclaimer: PREPARED BY EMG, JANUARY 2012, INFORMATION CONTAINED IN THIS DOCUMENT IS PRIVILEGED AND CONFIDENTIAL "TRADE SECRET" AND IS THE SOLE PROPERTY OF EMG CORP. THIS MATERIAL MUST BE CONSIDERED PRIVELEDGED AND CONFIDENTIAL BY ALL PARTIES PRIVY.

#### ECM DESCRIPTION:

Fluorescent lighting is recommended for areas where color sensitivity is an important criterion (e.g., offices or small parts assembly rooms). Fluorescent tubes are currently available that produce a higher light output (more lumens per watt) than standard fluorescent tubes. There are efficient 40-watt lamps that produce 8% to 10% more light than standard lamps. The 34-watt fluorescent tubes use 15% less power than standard lamps, while producing about 8% less light. Since the human eye responds to light exponen-tially, rather than linearly, the difference is often unnoticeable. "T8" fluorescent lamps use only 32 watts, but existing fixtures must be replaced.

It is important to replace all lamps when re-lamping a fluorescent fixture, never mix energy-efficient and standard lamps with the same ballast. Ensure that the fluorescent ballast is compatible with the energy-efficient lamps. It must be noted that when switching from T-12 magnetic ballast to T8 lamps, the ballasts should be replaced with instant start electrical ballast. Also it should be noted that when installing an occupancy sensor/motion sensor, rapid start electronic ballast should be used.

#### SUMMARY:

Initial Investment: \$78,375 Simple Payback: 3.73 Years

Annual Cost Savings: \$40,281

Property of EMG Corp, All Rights Reserved

UIC	Replace Exit Signs With LED Exit Signs	Corp, All Rights Reserve
EAL7-S	Details: Update remaining incandescant exit signs	
Total Existin	g Fixtures:	75
Current Wa	tts/ Fixture:	40 Watt
Annual Hou	rs of Operation (24hrsx365 days):	8,760 Hrs
Total Annua	l Energy Consumption:	26,280 kWh
Electric Rate	e:	\$0.12 \$\$
EMG Recomi	nends: Replace Entire EXIT Fixture	
Number of	Fixtures To Be Replaced:	75 (Qty)
Total Mater	ial Cost of Replacing Entire Fixture \$35/Fix.:  1000bulbs.com	\$2,625 \$\$
Estimated A	nnual Energy Consumption By Replacing Entire EXIT Fixture:	<b>1,314</b> kWh
Total Cost Sa	vings:	\$153 \$\$
Total Labor	Costs For Retrofit:	\$2,987 \$\$
Estimated T	otal Investment:	\$5,611.88 \$\$
Estimated Ar	nual Energy Savings From EXIT Sign Retrofits :	24,966 kWh
	kM Savings From The Proposed Retrofit: Incandescent Lamps in Exit Fixtures is 2000 hrs)	\$5,237 \$\$
Estimated To	tal Cost Savings:	\$8,152 \$\$
Simple Pay B	ack Period:	0.69
Type of Rec	ommendation Capital Cost ECM Recomme	ndation

Disclaimer: PREPARED BY EMG. JANUARY 2012, INFORMATION CONTAINED IN THIS DOCUMENT IS PRIVILEGED AND CONFIDENTIAL "TRADE SECRET" AND IS THE SOLE PROPERTY OF EMG CORP. THIS MATERIAL MUST BE CONSIDERED PRIVELEDGED AND CONFIDENTIAL BY ALL PARTIES PRIVY.

## **ECM DESCRIPTION:**

Life safety of the occupants holds the primary importance for any facility; hence the EXIT signs need to be illuminated all the times irrespective of the occupancy in the building. This means that these signs remain ON 24/7. In most cases the EXIT sign fixtures are powered by either a 40W incandescent lamp or an 11/13 Watt CFL lamp. EMG strongly recommends replacing the existing fixtures with LED fixtures powered by 2 or 4 watt LED lamps. At the same time the existing EXIT light fixture can be retrofitted with an LED lamp in place of an incandescent lamp. The later turns out to be a more cost effective procedure but might not apply to all the existing EXIT fixtures.

## SUMMARY:

Initial Investment: \$5,611.88 Simple Payback Period: 0.69

Annual Cost Savings: \$8,152.25

UIC	UIC Replace Halogen Flood Lamps With LED  EAL9-S Details: Along Entry Drive for Flag Poles		
EAL9-S			
Existing Lamp & Fixture Type		Flood Lights:- 150W Wall Packs- 175W -	-
Proposed Replacement Type:		LED LED LED	LED
Number of Lamps to Be Replaced :		100 25 0	0
Current Annual Avg Hrs of Operation:		4,380 hrs 4,380 hrs 0	hrs 0 hrs
Proposed Annual Avg. Hours of Operation		4,380 hrs 4,380 hrs 0	hrs 0 hrs
Proposed Replacem	ent:	54Watt -	-
Proposed Lighting C	ontrol: (Select)	Photosensor Light Switch	Light Switch
No. of Lighting Cont	rols:	2 Qty 25 Qty 0	Qty 0 Qty
Estimated Annual E	nergy Savings	42,048 kWh 13,250 kWh 0	kWh 0 kW
Total labor Cost		\$11,948 \$\$ \$2,987 \$\$ \$0	\$\$ \$0 \$\$
Estimated Material Cost:		\$617 \$\$ \$702 \$\$ \$0	\$\$ \$0 \$\$
Cost For Retrofit		\$73,643 \$\$ \$20,536 \$\$ \$0	\$\$ \$0 \$\$
Cost of Hiring A 60'	Tall Engine Powered Articulati	g Man lift For Fixture Replacement: \$9,613	
Total Initial Investment For Retrofit		\$103,791 \$\$ Total kWh Saving	55,298 kW
Electric Rate:		\$0.12 \$\$ Total Energy Cost Savings:	\$6,456 \$\$
Total O&M Savings:		\$27,500 \$\$ Total Cost Savings:	\$33,956 \$\$
Simple Pay back Per	iod	3.06 Yrs	
Type of Recommendation		endation Capital Cost ECM Recommendati	on
laimer: PREPARED BY EN	IG. IANUARY 2013. INFORMATION O	NTAINED IN THIS DOCUMENT IS PRIVILEGED AND CONFIDENTIAL "TRADE SECRET" AN	D IS THE SOLE PROPERTY OF EMG