



Photo	1	Direction	E	Date	11/7/2016
Subject: ATV damage despite attempt to barricade.					

Photo	2	Direction	E	Date	11/7/2016
Subject: Waterbar destroyed by ATVs above headwall erosion in trail.					



Photo	3	Direction	N	Date	11/7/2016
Subject: Skid trail eroded down to bedrock due to ATV traffic.					

Photo	4	Direction	SE	Date	11/7/2016
Subject: Same trail as in photo 3.					



Photo	5	Direction	W	Date	11/7/2016
Subject: Severe erosion just below a waterbar compromised by ATVs.					

Photo	6	Direction	NW	Date	11/7/2016
Subject: Long stretch of skid trail deeply eroded as a result of ATV use.					

