

# WOODSIDE JUVENILE REHABILITATION FACILITY

An overview of the existing facility, building and program shortcomings, and an introduction to the proposed 30 bed replacement facility.

January 2019

# Overview of Existing Facility

- Existing facility was built in 1984 as a 30 bed juvenile detention center.
- Existing structure is sound but all walls support the concrete deck above, making it difficult to modify or change the layout.
- Mechanical systems are at the end of their lifespan and will need to be replaced.
- Fire protections is adequate and complies with code.
- Wiring is original and appears to be adequate and code compliant.
- Life safety systems (alarms/egress/emergency lighting) will need upgrading and/or replacement. Some items no longer meet code.

# Overview of Existing Program Functions

- The Council of Juvenile Correctional Administrators (CJCA) report that almost everything about the appearance and function of the building runs counter to and works against the treatment model that Woodside has implemented in moving from detention to rehabilitation.

# Building Impact on Program and Functionality

- Lack of natural light.
- Residents cannot easily be isolated from others when necessary.
- The layout prevents segregation by gender, age, or needs.
- There is insufficient space for counseling, treatment, family visits, legal counsel etc.
- There is insufficient space for critical program elements, and some rooms are used for multiple purposes. Many rooms are interconnected and one must pass through to reach another room.
- There is insufficient nursing space and no dedicated intake or infirmary.
- Medicine does not have a dedicated space.
- Staff does not have sleeping, bath or personal space and are utilizing a storage closet for sleeping.
- The kitchen cooler and freezers are outside.
- The existing elevator does not meet current standards and the only access to it is through the kitchen, dishwashing, and dining rooms.

# Building Impact on Program and Functionality

- Resident rooms are too small to meet ADA.
- Doors and locks are not rated to withstand abuse.
- The rear egress stairs do not meet current life safety requirements.
- The parking lot is too small.
- The maintenance dept. does not have adequate storage or work space.
- Windows and doors need to be replaced.
- There is not adequate access or space to service mechanical systems.
- Gym surfaces are not holding up to use.

# Proposed New Facility first floor

## WOODSIDE

WOODSIDE JUVENILE REHABILITATION CENTER  
ESSEX, VERMONT

### TABLE OF CONTENTS

- 01. EXECUTIVE SUMMARY
- 02. PROJECT NARRATIVE
  - TEAM & PROCESS
  - EXISTING SITE REVIEW
  - EXISTING BUILDING REVIEW
  - PROGRAM
  - DESIGN OVERVIEW
  - SITE DESIGN
  - BUILDING DESIGN
  - ENERGY-EXISTING & PROPOSED
  - PROBABLE COST
- 03. DRAWINGS
  - CIVL - EXISTING SITE PLAN
  - CIVL - 25 BED SITE PLAN
  - CIVL - 30 BED SITE PLAN
  - EXISTING - FIRST FLOOR
  - EXISTING - SECOND FLOOR
  - 25 BED - SITE PLAN
  - 25 BED - BUILDING DIAGRAM
  - 25 BED - FIRST FLOOR
  - 25 BED - SECOND FLOOR
  - 30 BED - SITE PLAN
  - 30 BED - BUILDING DIAGRAM
  - 30 BED - FIRST FLOOR
  - 30 BED - SECOND FLOOR
  - BLDG. & SITE PHASING DIAGRAM
- 04. APPENDIX
  - A - PROGRAM
  - B - STRUCTURAL REPORT
  - C - MEP REPORT
  - D - CUA LETTER OF SUPPORT
  - E - WOODSIDE REPORT
  - F - ACA STANDARDS-EXCERPTS
  - G - EXISTING PHOTOS




**Duncan Wisniewski**  
ARCHITECTURE  
**TREANORHL**

30 BED - FIRST FLOOR PLAN  
0 20 40 FT

# Proposed New Facility second floor

WOODSIDE

WOODSIDE JUVENILE  
REHABILITATION CENTER  
ESSEX, VERMONT



- SPACE LEGEND**
- YARD
  - ADMINISTRATION
  - CIRCULATION
  - CIRCULATION - SP
  - DINING
  - EDUCATION / COUNSELING
  - HOUSING
  - STAFF HOUSING
  - INTAKE / NURSE
  - UTILITY
  - EXISTING GYM

**TABLE OF CONTENTS**

- 01. EXECUTIVE SUMMARY
- 02. PROJECT NARRATIVE
  - TEAM & PROCESS
  - EXISTING SITE REVIEW
  - EXISTING BUILDING REVIEW
  - PROGRAM
  - DESIGN OVERVIEW
  - SITE DESIGN
  - BUILDING DESIGN
  - ENERGY-EXISTING & PROPOSED
  - PROBABLE COST
- 03. DRAWINGS
  - CIVL - EXISTING SITE PLAN
  - CIVL - 25 BED SITE PLAN
  - CIVL - 30 BED SITE PLAN
  - EXISTING - FIRST FLOOR
  - EXISTING - SECOND FLOOR
  - 25 BED - SITE PLAN
  - 25 BED - BUILDING DIAGRAM
  - 25 BED - FIRST FLOOR
  - 25 BED - SECOND FLOOR
  - 30 BED - SITE PLAN
  - 30 BED - BUILDING DIAGRAM
  - 30 BED - FIRST FLOOR
  - 30 BED - SECOND FLOOR
  - BLDG. & SITE PHASING DIAGRAM
- 04. APPENDIX
  - A - PROGRAM
  - B - STRUCTURAL REPORT
  - C - MEP REPORT
  - D - C/JCA LETTER OF SUPPORT
  - E - WOODSIDE REPORT
  - F - ICA STANDARDS EXCERPTS
  - G - EXISTING PHOTOS

30 BED - SECOND FLOOR PLAN  
0 20 40 FT

Duncan  
Wisniewski  
ARCHITECTURE  
TREANORHL

# Existing Facility

## WOODSIDE

WOODSIDE JUVENILE  
REHABILITATION CENTER  
ESSEX, VERMONT

### TABLE OF CONTENTS

- 01. EXECUTIVE SUMMARY
- 02. PROJECT NARRATIVE
  - TEAM & PROCESS
  - EXISTING SITE REVIEW
  - EXISTING BUILDING REVIEW
  - PROGRAM
  - DESIGN OVERVIEW
  - SITE DESIGN
  - BUILDING DESIGN
  - ENERGY-EXISTING & PROPOSED
  - PROBABLE COST

- 03. DRAWINGS
  - CIVL - EXISTING SITE PLAN
  - CIVL - 25 BED SITE PLAN
  - CIVL - 30 BED SITE PLAN
  - EXISTING - FIRST FLOOR
  - EXISTING - SECOND FLOOR
  - 25 BED - SITE PLAN
  - 25 BED - BUILDING DIAGRAM
  - 25 BED - FIRST FLOOR
  - 25 BED - SECOND FLOOR
  - 30 BED - SITE PLAN
  - 30 BED - BUILDING DIAGRAM
  - 30 BED - FIRST FLOOR
  - 30 BED - SECOND FLOOR
  - BLDG. & SITE PHASING DIAGRAM

- 04. APPENDIX
  - A - PROGRAM
  - B - STRUCTURAL REPORT
  - C - MEP REPORT
  - D - CIVIL LETTER OF SUPPORT
  - E - WOODWORK REPORT
  - F - ACA STANDARDS-EXCERPTS
  - G - EXISTING PHOTOS

Duncan  
Wisniewski  
ARCHITECTURE

TREANORHL

### APPENDIX G - EXISTING PHOTOS



EXISTING BUILDING



EXISTING BUILDING ENTRY




EXISTING BUILDING WEST WING



EXISTING PARKING



EXISTING YARD



EXISTING STAFF SLEEPING ROOM



EXISTING YARD



# Existing Facility



EXISTING RESIDENT SLEEPING ROOM



EXISTING DAYROOM



EXISTING STORAGE ROOM



EXISTING CLASSROOM



EXISTING STAFF OFFICE



EXISTING FITNESS ROOM



EXISTING CONTROL ROOM



EXISTING STAFF OFFICE



EXISTING STAFF OFFICE



EXISTING MECHANICAL LOFT

## WOODSIDE

WOODSIDE JUVENILE  
REHABILITATION CENTER  
ESSEX, VERMONT

### TABLE OF CONTENTS

#### 01. EXECUTIVE SUMMARY

#### 02. PROJECT NARRATIVE

- TEAM & PROCESS
- EXISTING SITE REVIEW
- EXISTING BUILDING REVIEW
- PROGRAM
- DESIGN OVERVIEW
- SITE DESIGN
- BUILDING DESIGN
- ENERGY-EXISTING & PROPOSED
- PROBABLE COST

#### 03. DRAWINGS

- CIVIL - EXISTING SITE PLAN
- CIVIL - 25 BED SITE PLAN
- CIVIL - 30 BED SITE PLAN
- EXISTING - FIRST FLOOR
- EXISTING - SECOND FLOOR
- 25 BED - SITE PLAN
- 25 BED - BUILDING DIAGRAM
- 25 BED - FIRST FLOOR
- 25 BED - SECOND FLOOR
- 30 BED - SITE PLAN
- 30 BED - BUILDING DIAGRAM
- 30 BED - FIRST FLOOR
- 30 BED - SECOND FLOOR
- BLDG. & SITE PHASING DIAGRAM

#### 04. APPENDIX

- A - PROGRAM
- B - STRUCTURAL REPORT
- C - MEP REPORT
- D - CDDA LETTER OF SUPPORT
- E - WOODSIDE REPORT
- F - ACA STANDARDS-EXCERPTS
- G - EXISTING PHOTOS

Duncan  
Wisniewski  
ARCHITECTURE

TREANORHL

# Where we are now:

- **Permits** — We have consulted with the State, Army Corp of Engineers and the Town, and do not foresee any major issues with permitting a new facility at this site.
- **Design** — We need to Competitively bid for Architectural and Engineering Design Services, evaluate and award the contract and begin full design services. Award of the Contract and Design should take 12 - 16 months.
- **Construction** — We anticipate construction taking approximately 18 months to complete. We plan to keep the existing facility fully operational during construction of the new facility, saving time, money and effort by not having to find homes for the residents during that time.
- **Cost** — The 30 bed option is estimated to cost approximately \$23,300,000, which includes all project costs.