

The Vermont Building at the Eastern States Exposition, West Springfield, MA



Before New Energy Efficient Lighting & Mechanical



Progress on the installation of New Energy Efficient Lighting and Painting of Black Ceilings



Before New Energy Efficient Lighting & Air Handler Work & Black Painted Ceilings.



Before New Energy Efficient Lighting & Air Handler Work & Painting.




Before Energy Efficient Lighting & Air Handler Duct Work Installed.



After New Energy Efficient Lighting & Air Handler Duct Work Installed.



Before New Energy Efficient Lighting & Air Handler Duct Work Installed.



After New Energy Efficient Lighting & Air Handler Duct Work Installed.



Existing Back Entry slated for the following work: window restoration, lawn drainage, restore entry doors, upgrade landscaping and fabricate new Band Pavilion.



RE-Gild Vermonts Dull Dome



Marble Pilaster Separating from Building Facade



Restore Cupola Windows Walk and Deteriorated Trim