

OFFICE OF THE CHANCELLOR PO BOX 7 MONTPELIER, VT 05601 P (802) 224-3000 F (802) 224-3035

January 13, 2017

Rep. Alice Emmons, Chair, and Members, House Committee on Corrections and Institutions Sen. Peg Flory, Chair, and Members, Senate Committee on Institutions State of Vermont General Assembly 115 State Street Montpelier, VT 05633-5301

Re: Long-Term Strategic Plan for the Most Effective Use of Capital Funds

Dear Representative Emmons and Senator Flory,

Thank you for the opportunity for the Vermont State Colleges System to provide a long-term strategic plan for the use of capital funds.

Sec. 30a. of No. 160 of the Acts of 2016 stated in part:

On or before January 15, 2017, the Chancellor of the Vermont State Colleges and the President of the University of Vermont shall each submit a long-term strategic plan to the House Committee on Corrections and Institutions and the Senate Committee on Institutions for the most effective use of capital funds, including outlining priorities for whether to allocate future capital appropriations to general construction, maintenance, and renovation costs or to specific capital projects, and how to maximize the use of matching grant funds.

This memorandum responds to each element of this statutory charge, and proposes a framework for the System's future Capital Bill requests.

#### Overview of the Vermont State Colleges System

Strategic capital planning presents a challenge to the System for a number of reasons. Foremost, as we have consistently reported, is that the magnitude of need dwarfs the available resources. The System comprises five institutions – Castleton University, the Community College of Vermont, Johnson State College, Lyndon State College, and Vermont Technical College – in twenty locations spread across the geographic entirety of the State of Vermont, with 154

buildings and 2.34 million square feet of space, occupying over 1,700 acres, with \$563 million of insured property.

The System's facilities and infrastructure are extensive, and aging. The average age of our buildings is almost 50 years, and major infrastructure such as underground electrical, water and sewer mains, and steam distribution systems range from 25 to 50 years old. A list of the System's building inventory, with ages, is included as Attachment 1, and a narrative description of the System's major infrastructure is included as Attachment 2.

As shown on the following table, our facilities directors estimate combined deferred maintenance of \$58.5 million, and our fiscal year 2016 audited financial report lists an annual depreciation expense of \$10.5 million.

#### **Capital Funding Constraints**

At the same time that aging facilities and infrastructure cause the System's needs to grow, the System has struggled

CCV Newport O + Swanton GRAND ESSEX ISLE 14 EMPLOYEES CCV St. Albans 🖈 107 STUDENTS ORLEANS ✓ N. Hero 66 EMPLOYEES FRANKLIN 11 EMPLOYEES 583 STUDENTS 74 EMPLOYEES 105 STUDENTS 874 STUDENTS Johnson State Lyndon State O College 1 O College + CCV Morrisville 🖪 CCV Winooski CCV VT Tech LAMOILLE Burlington O St. Johnsbury 🐗 Williston + NA CHITTENDEN CALEDONIA 219 EMPLOYEE 2421 STUDENTS CCV 693 STUDENTS O Montpelier 🖈 WASHINGTON ADDISON 221 EMPLOYEES 71 EMPLOYEES 953 STUDENTS ORANGE 548 STUDENTS 151 EMPLOYEES CCV Middlebury **500 STUDENTS** +4 Vermont Technical College + W \* RUTLAND 413 EMPLOYEES CCV 1307 STUDENTS Upper Valley +124 O CCV Rutland 4 WINDSOR Castleton 78 EMPLOYEES University + 855 STUDENTS CCV Springfield C Campuses and BENNINGTON **Academic Centers** 498 STUDENTS VSCS Nursing Programs ✓ External Degree **Program Sites** WINDHAM 67 EMPLOYEES ✓ VT Small Business 608 STUDENTS **Development Center Sites** \* VT Manufacturing **Extension Center Sites** CCV CCV Brattleboro C VSCS EMPLOYEES Bennington +1 VSCS STUDENTS Source: VSCS Institutional Research

**Vermont State Colleges System Locations** 

financially. Since the peak of student enrollments in 2010, demographically driven decreases in the number of high school graduates in both Vermont and the northeastern United States have negatively impacted System revenues. State budget appropriations have remained essentially unchanged, and yet salary and benefit costs, especially employee healthcare, continued to rise, causing severe budget pressures and several years of deficits. As such, the System has been increasingly unable to fund adequately its capital needs from operations, and has increasingly

needed to conserve and use its reserves just to balance budgets, further preventing needed capital investments.

Communally another	Year	Campus	Decilalinas	Square	Deferred
Campus/Location	Founded	Acres	Buildings	Footage	Maintenance
Castleton University	1787	165	31	676,904	\$ 8,824,950
Spartan Arena		1	1	42,256	
Vermont Tech					9,594,350
Randolph Center Campus	1866	75	30	439,256	
VTC Farmstead		525	6	30,403	
Williston Campus		12	7	66,000	
Norwich Farm		350	9	31,000	
Lyndon State College	1866	200	27	496,010	15,726,030
Johnson State College	1866	380	39	440,079	23,717,700
Community College of Vermont	1970				600,000
CCV St. Albans		2.5	1	9,900	
CCV Upper Valley		2	1	15,000	
CCV Montpelier		8.3	1	34,000	
CCV Winooski		1.5	1	65,000	
Totals		1,722.3	154	2,345,808	\$ 58,463,030

Negative operating performance has also precluded the System from accessing the capital markets, owing to covenants related to a series of bank loans entered into in 2005, 2008 and 2009 that require net income to be at least 100% of annual debt service. The System last sold bonds to fund new construction in 2010.

Finally, while the Colleges all have diligent and hardworking staff devoted to fundraising, and while they are grateful to generous alumni, private individuals, foundations, and corporate donors for gifts and grants, this type of funding tends to occur in the tens and hundreds of thousands, and to be applied toward scholarship assistance. The System simply does not have a history of attracting multi-million dollar gifts typically associated with new construction and renovations.

Against this backdrop, for the four fiscal years from 2014 through 2017, the System has received a base annual capital appropriation from the State of \$1.4 million towards major and deferred

maintenance, every dollar of which is spent almost immediately. We also acknowledge and are grateful that the State has provided additional appropriations of \$1.5 million for Vermont Technical College, \$1 million for Castleton University, and \$150,000 for Lyndon State College during this timeframe. However, even with these additional investments, the current level of State funding simply does not lend itself to strategic capital planning in the sense of a Systemwide, multi-year program of new construction, major renovations, upgrades, and service life extensions.

#### Current Capital Planning Process, and FY2018-19 Capital Request

Given the System's financial challenges and the recent history of State capital appropriations, the System has conducted its capital planning year by year, and focused on urgent needs. Each spring, the Colleges' facilities directors and staff review their overall list of projects, and in accordance with the System's policy, select a subset of projects ranked, in order, based upon life and safety, ADA and other compliance issues, major maintenance, and finally new construction. These lists are then reviewed by the System's facilities director, further reviewed by the Finance and Facilities Committee of the System's Board of Trustees, and finally approved by the full Board and submitted to the State.

For the FY2018-19 biennium, the System has requested a total of \$11 million, comprised of \$4 million in each year for major and deferred maintenance, and a supplemental \$3 million in FY2018 for replacement of the System's "Colleague" enterprise resource planning (ERP) software, which dates from 2003. A list of projects and accompanying narrative is included as Attachment 3, and for your information, the System's entire \$58.5 million list of deferred maintenance is included as Attachment 4.

### Near-Term Debt Management to Enable Longer-Term Planning

The System plans to refinance its bank loans via an approximately \$80 million bond sale during FY2017. This refinancing will remove the restrictive loan covenants that currently prevent the System from borrowing additional funds, while also restructuring the System's principal and interest payments to provide for a more level amortization of the System's debt service. This restructuring, along with an increased budget appropriation from the State, and an accompanying improvement in financial operating performance, should enable the System within several years to access the capital markets again for modest new borrowing.

All of the Colleges have either formal strategic plans, or specific priorities for new construction or major upgrades to existing facilities, but these generally have been on hold for lack of financial resources. To cite just a few examples: Castleton University's success has caused it to outgrow its main campus footprint, necessitating expansion into downtown Rutland; CCV continually needs to invest in information technology to support its broad selection of online

course offerings; Johnson State needs to renovate its centerpiece Dibden Center for the Arts in support of its recent recognition as a premier, and Vermont's only, Council of Public Liberal Arts Colleges (COPLAC) member college; Lyndon State needs to enhance its information technology infrastructure to deliver its nationally-recognized professional programs, such as Atmospheric Sciences, to a wider cohort of students; and Vermont Tech needs to expand capacity for its very popular and over-subscribed nursing and aviation programs at its Williston campus.

With this large array of needs, all of which are essential to future success, the System intends to approach new construction and major renovations through a formal capital planning process that prioritizes projects through quantitative measures, such as return on investment, and qualitative measures, such as realization of broad strategic objectives. Over the course of calendar year 2017, senior staff will work with the Finance and Facilities and the Long Range Planning Committees of the System's Board of Trustees to develop a more thorough strategic capital planning process.

#### Proposal for Future Vermont State Colleges System Capital Bill Requests


In specific response to the Legislature's statutory charge, the System believes it can best utilize precious State capital allocations toward reducing its backlog of deferred maintenance, with the goal of targeting its own incremental borrowing capacity toward specific projects, both new construction and major renovations. While we are grateful for all allocations of State capital funds, we believe that an increased and consistent allocation of State capital funds, prioritized within the System's existing capital budgeting framework, will both help to insulate the System from year-to-year variations in operating performance, and best position the System to direct its limited borrowing capacity toward specific, prioritized new investments.

With respect to maximizing the use of matching grant funds, we have experienced mixed results. While we have used "challenge grants" to attempt to motivate additional giving, there is little evidence these grants assist the Colleges with raising additional funds. As a practical matter, Colleges are just as likely to redirect limited existing fundraising resources to avoid losing a capital allocation.

Going forward, we request that the State commit 6% of the Capital Bill allocation to the Vermont State Colleges System. As shown on the following chart, this corresponds the historical average that the System received throughout the 1990s.

It appears that when the State's general obligation bonding capacity steadily decreased through 2004, the dollar amount of the System's allocation shrunk accordingly. However, when general

obligation bonding increased thereafter, the System's dollar amounts remained low, and its percentage of Capital Bill allocation correspondingly decreased.



**History of Vermont State Colleges System Capital Bill Appropriations** 

A 6% allocation, which coincidentally corresponds to the System's \$4 million capital allocation request for deferred maintenance in each of FY2018 and FY2019, makes sense for several reasons. Most importantly, a percentage allocation recognizes that the Capital Debt Affordability Advisory Committee's (CDAAC) recommendation regarding the State's prudent maximum debt issuance will vary from year to year, and that maintaining the State's triple-A credit rating is paramount. The System is a direct and indirect beneficiary of the State's excellent credit ratings and attendant strong financial management, and it therefore would not be appropriate to request an ongoing fixed dollar capital allocation each year at the expense of other critical State-supported programs.

At the same time, a 6% allocation targeted primarily toward the System's deferred maintenance needs has an immediate and widely distributed impact on the State's economy; the map on page 2 shows our locations spread throughout thirteen of Vermont's fourteen counties. In addition,

given the immediacy of our needs, we spend our capital allocations right away. The System's only unspent capital bill dollars relate to challenge grants, and we are working overtime to identify matching gifts accordingly.

The State can demonstrate a meaningful commitment to the System with an ongoing 6% annual capital bill allocation, as this would begin to enable substantial progress toward addressing our critical maintenance backlog. This level of funding would invest in improving the System, while being flexible and responsive to the State's long-term capital budgeting process, and not overly burdening or pressuring myriad other State capital needs.

Should you have any questions regarding this report, please feel free to email me at <a href="mailto:jeb.spaulding@vsc.edu">jeb.spaulding@vsc.edu</a>, or contact me by phone at 224-3001. I look forward to discussing the System's capital allocation request, and to working constructively with you in the coming Legislative session.

Sincerely,

Jeb Spaulding Chancellor

cc: Stephen Klein and Catherine Benham, Vermont Legislative Joint Fiscal Office

#### Attachments:

- 1. List of System buildings and ages
- 2. System major infrastructure narrative
- 3. FY2018 Capital Bill request and narrative

Brang (m)

4. List of deferred maintenance

CASTLETON UNIVERSITY
COMMUNITY COLLEGE OF VERMONT
JOHNSON STATE COLLEGE
LYNDON STATE COLLEGE
VERMONT TECHNICAL COLLEGE



OFFICE OF THE CHANCELLOR PO BOX 7 MONTPELIER, VT 05601 P (802) 224-3000 F (802) 224-3035

## Attachment 1: List of System Buildings and Ages

College, Location (Building Name)	Description	Year Built	Building Age	Construction
Community College of VT / 41 Harmony Place, Brattleboro, VT 05301	Classroom (Leased Space)	1860 / 2014	155	Brick / Wood Frame
Community College of VT, 1997 Main St, St. Johnsbury VT	Classroom	1869	146	Brick
Community College of VT, 10 Merchants Row, Middlebury, VT	Classroom	1900	115	Brick
Community College of VT, 324 Main St, Bennington VT	Classroom	1920	95	Brick
Community College of VT, 197 Harrel St, Morrisville, VT	Classroom	1984	31	Wood Frame
Community College of VT, 660 Elm Street , Montpelier, VT	Classroom Building	1987/ 2000/ 2012	28	Wood / Steel framed
Community College of VT, 142 So. Main St, St. Albans VT	Classroom	1992	23	Wood Frame
Community College of VT, 100 Main St, Newport VT 05855	Classroom	1998	17	Brick
Community College of VT, Billings Farm Industrial Park, Wilder VT	Classroom	2004	11	Brick/Steel
Community College of VT, 1 Abenaki Way, Winooski, VT	Classroom/Admin	2009	6	Masonry/NC
Community College of VT, 60 West Street, Rutland, VT 05701	Classroom	2011	4	Masonry/NC
Castleton University, Rutland, VT 05701 (leased Space)	Offices			Brick/Wood
Castleton University, Castleton, VT (30 Seminary Lane)	Offices	Pre 1900	115+	Wood Frame
Castleton University, Castleton, VT (36 Seminary Lane)	residence	Early 1900's	100+	Wood Frame
Castleton University, Castleton, VT (Old Chapel)	Seminar	1821/1987	194	Wood Frame
Castleton University, Castleton, VT (HopeHouse/Wellness Center)	Wellness Center	1850	165	Wood Frame
Castleton University, Castleton, VT (Wooldridge House)	Art Studio	1890	125	Wood Frame
Castleton University, Castleton, VT (Moriarty House)	Classroom/Office	1900	115	Wood Frame
Castleton University, Castleton, VT (Chris White House)	House	1900's	115	Wood Framed
Castleton University, Castleton, VT (Wright House)	Offices	1900	115	Wood Frame
Castleton University, Castleton, VT (Observatory)	Observatory	1919	96	Brick/Metal
Castleton University, Castleton, VT (Woodruff Hall)	Classroom/Administration	1927	88	Brick/Wood
Castleton University, Castleton, VT (Ellis Hall)	Dormitory	1950	65	Brick/Block
Castleton University, Castleton, VT (Glenbrook Gym)	Gymnasium	1959/2009	56	Brick/Block
Castleton University, Castleton, VT (Huden Hall)	Dining Hall	1965/1997	50	Brick/Wood
Castleton University, Castleton, VT (Adams Hall)	Dormitory	1965	50	Brick/Steel
Castleton University, Castleton, VT (Haskell Hall)	Dormitory	1965	50	Brick/Block
Castleton University, Castleton, VT (Morrill Hall)	Dormitory	1968	47	Brick/Block
Castleton University, Castleton, VT (Wheeler Hall)	Dormitory	1968	47	Brick/Block
Castleton University, Castleton, VT (Fine Arts Center)	Auditorium	1969	46	Brick/Steel
Castleton University, Castleton, VT (Superior Boiler Room)	Boiler Plant	1969	46	Brick/Block
Castleton University, Castleton, VT (Jeffords Science Center)	Classroom	1969/1993/2007	46	Brick/Block
Castleton University, Castleton, VT (President's House)	Residence	1972	43	Wood Frame
Castleton University, Castleton, VT (Leavenworth Hall)	Classroom	1974/2009	41	Brick/Block
Castleton University, Castleton, VT (Campus Center)	Student Union	1975/2009	40	Block/Steel
Castleton University, Castleton, VT (Babcock Hall)	Dormitory	1989	26	Brick/Steel
Castleton University, Castleton, VT (SHAPE (gym) Addition)	Gymnasium	1990	25	Brick/Block
Castleton University, Castleton, VT (Stafford Academic Ctr)	Classroom/Office	1999	16	Brick/Steel
Castleton University, Castleton, VT (Calvin Coolidge Library)	Library	1999	16	Brick/Steel
Castleton University, Rutland, Vt (Spartan Arena)	Ice Arena	2004	11	Prengineered Metal
Castleton University, Castleton, VT (Residence Hall and Fitness Center)	Residence/Fitness	2004	11	Brick/Steel
Castleton University, Castleton, VT (North, Center & South Halls) 3 buildings	Dormitory	2004	9	Wood Frame
Castleton University, castleton, Vt. (Green House)	Green House	2008	7	Steel / Glass
Castleton University, Behind 360 Street (Stadium/Bleachers)	Athletic Facility	2009	6	Steel / Wood
Casheton University, Definite 500 Street (Stadium/Dieachers)	Intiliette i acility	2009	U	Steel / WOOd

College, Location (Building Name)	Description	Year Built	<b>Building Age</b>	Construction
Castleton University, Castleton, VT (Maintenance Building)	Maintenance Building	2011	4	Wood/Prengineered Metal
Castleton University (Residence Hall)	Dormitory	2012	3	Brick / Steel
Castleton University, Castleton, VT ( Pavilion Building)	Pavilion	2012	3	Wood Frame
Johnson State College, Johnson, VT (Farm House Duranleau)	Farm House	1919	96	Wood Frame
Johnson State College, Johnson, VT (McClellend Hall)	Classrooms/Offices	1941	74	Brick/Steel
Johnson State College, Johnson, VT (Martinetti Hall)	Dormitory/Offices	1958	57	Brick/Block
Johnson State College, Johnson, VT (Arthur Hall)	Dormitory	1964/2012	51	Brick/Conc
Johnson State College, Johnson, VT (Dewey Campus Ctr)	Classrooms/Offices	1964	51	Brick/Steel
Johnson State College, Johnson, VT (Carter Gymnasium)	Gymnasium	1965/2009	50	Brick/Block
Johnson State College, Johnson, VT (President's House)	Residence	1967	48	Wood Frame
Johnson State College, Johnson, VT (Governors Hall)	Dormitory	1968	47	Brick/Block
Johnson State College, Johnson, VT (Stearns Dining Hall)	Dining Hall	1968/ 2008	47	Brick/Block
Johnson State College, Johnson, VT (Bentley Hall)	Classroom/Labs	1970/2010/2011	45	Brick/Block
Johnson State College, Johnson, VT (Dibden Auditorium)	Auditorium	1970	45	Brick/Block
Johnson State College, Johnson, VT (Duranleau Barn)	Barn	1970	45	Wood Frame
Johnson State College, Johnson, VT (Senators Hall)	Dormitory	1970	45	Brick/Block
Johnson State College, Johnson, VT (Water Tower)	Water Tower	1970	45	Steel
Johnson State College, Johnson, VT (Campus Apartments)	Apartments	1973	42	Wood Frame
Johnson State College, Johnson, VT (Visual Arts Ctr)	Classrooms	1976/2012	39	Brick/Block
Johnson State College, Johnson, VT (Maintenance Bldg)	Maintenance Shop	1978	37	Block/Wood
Johnson State College, Johnson, VT (House 1096 College Hill)	House	1980	35	Wood Framed
Johnson State College, Johnson, VT (Shop Storage)	Storage Building	1982	33	Wood Frame
Johnson State College, Johnson, VT (Garage)	Bus Shed	1983	32	Wood Frame
Johnson State College, Johnson, VT (Hazardous Material Storage Shed)	Haz Storage at Maint	1993	22	Wood Frame
Johnson State College, Johnson, VT (Library Learning Ctr)	Library	1995	20	Brick/Steel
	·			
Lyndon State College, Lyndonville, VT (McGoff Hill House (325k) & Barn (100k))	Residence	1860	155	Wood
Lyndon State College, Lyndonville, VT (Alumni House)	Offices	1910	105	Wood Frame
Lyndon State College, 173 York Street, Lyndon, VT 05849	Grange Building (Vacant)	1915	100	Masonry
Lyndon State College, Lyndonville, VT (Day Care Ctr)	Day Care Facility	1960	55	Wood Frame
Lyndon State College, Lyndonville, VT (Gray House)	Residence	1963	52	Wood Frame
Lyndon State College, Lyndonville, VT (Ball Field Service Bldg)	Residence	1963	52	Wood Frame
Lyndon State College, Lyndonville, VT (President's House)	Residence	1964	51	Wood Frame
Lyndon State College, Lyndonville, VT (Stevens Dining Hall)	Dining Hall	1965	50	Brick/Wood
Lyndon State College, Lyndonville, VT (Harvey Academic Ctr)	Classrooms/Offices	1965/2010	50	Brick/Steel
Lyndon State College, Lyndonville, VT (Wheelock Dormitory)	Dormitory	1965	50	Brick/Concrete
Lyndon State College, Lyndonville, VT (Arnold/Bayley Dorm Complex)	Dormitory	1967	48	Brick/Concrete
Lyndon State College, Lyndonville, VT (Rogers/Poland Dorm Complex)	Dormitory	1967	48	Brick/Concrete
Lyndon State College, Lyndonville, VT (Activities Building)	Thearter/Gym/Labs	1969/2011	46	Brick/Steel
Lyndon State College, Lyndonville, VT (Maintenance Shop)	Maintenance Shop	1970	45	Steel
Lyndon State College, Lyndonville, VT (Crevecoeur/Whitelaw Dorm Complex)	Dormitory	1970	45	Brick/Concrete
Lyndon State College, Lyndonville, VT (Samuel Reed Hall Library)	Library	1971	44	Block/Concrete
Lyndon State College, Lyndonville, VT (Theodore Vail Ctr)	Classrooms/Offices	1976	39	Brick/Concrete

College, Location (Building Name)	Description	Year Built	Building Age	Construction
Lyndon State College, Lyndonville, VT (Brown house)	Health Services	1978	37	Wood Frame
Lyndon State College, Lyndonville, VT (Bus Garage)	Storage Building	1983	32	Wood Frame
Lyndon State College, Lyndonville, VT (Storage Bldg)	Storage Building	1983	32	Wood Frame
Lyndon State College, Lyndonville, VT (Transmitter House)	Radio Equipment	1986	29	Block
Lyndon State College, Lyndonville, VT (Rita Bole Ctr Shape)	Gym/Pool	1990	25	Brick/Steel
Lyndon State College, Lyndonville, VT (New Student Housing Complex)	Dormitory	2005	10	Brick/Steel
Lyndon State College, Lyndonville, VT (Academic and Student Center)	Offices	2009	6	Brick / steel
Vermont Technical College, Randolph Center, VT (Langevin Hall)	Conference Ctr.	1803	212	Wood Frame
VTC Nursing Program, Thompson School, 41 Harmony Place, Brattleboro VT	Classrooms	1860 / 2014	155	Brick / Wood Frame
Vermont Technical College, Randolph Center, VT (Allen House)	Offices	1869/2012	146	Brick/Wood
Vermont Technical College, Randolph Center, VT (Red School House)	Classrooms/Offices	1901	114	Wood Frame
Vermont Technical College, Randolph Center, VT (Old Dorm)	Dormitory	1918	97	Wood F/Vinyl Side
Vermont Technical College, Randolph Center, VT (Nutting House)	Residence	1919	96	Wood Frame
VTC Nursing Program, Putnam Memorial, Bennington VT	Classrooms	1946	69	Brick
Vermont Technical College, Randolph Center, VT (Admin Ctr)	Offices	1950	65	Brick/Wood
Vermont Technical College, Randolph Center, VT (Judd Hall)	Gymnasium	1957	58	Brick/Steel
Vermont Technical College, Randolph Center, VT (Morrill Hall)	Classrooms/Labs	1963	52	Brick/Steel
Vermont Technical College, Randolph Center, VT (Conant Hall)	Classrooms/Offices	1964	51	Brick/Steel
VTC, 5689 Route 2, Williston, VT 05495	VT Sandwich Company	1964	51	Wood Frame
Vermont Technical College, Randolph Center, VT (Water Tower)	Water Tower	1965	50	Metal
Vermont Technical College, Randolph Center, VT (Morey Hall)	Dormitory/Cafeteria	1966	49	Brick/Block
Vermont Technical College, Randolph Center, VT (Hartness Library)	Library	1967 / 2011	48	Brick/Steel
Vermont Technical College, Randolph Center, VT (Keenan Hall)	Dormitory	1967	48	Brick/Block
Vermont Technical College, Randolph Center, VT (Main Barn)	Barn/Classroom/offices	1967	48	Wood Frame
Vermont Technical College, Randolph Center, VT (Heifer Barn)	Barn	1967	48	Wood Frame
Vermont Technical College, Randolph Center, VT (Machinery Shed)	Equipment Barn	1967	48	Wood Frame
Vermont Technical College, Randolph Center, VT (Sugar House)	Sugarhouse	1967	48	Wood Frame
Vermont Technical College, Randolph Center, VT (Silo-Cement)	Silo	1967	48	Concrete
Vermont Technical College, Randolph Center, VT (Silo-Fiberglass)	Silo	1967	48	Fiberglass
Vermont Technical College, Randolph Center, VT (Silo Shed)	Silo Unloading	1967	48	Wood Frame
Vermont Technical College, Randolph Center, VT (Barn - Pole)	Scale Building	1967	47	Wood Frame
VTC, 5667 Route 2, Williston, VT 05495	Vacant	1968	47	Wood Frame
Vermont Technical College, Randolph Center, VT (Green Hall)	Classrooms/Offices	1969	46	Brick/Steel
Vermont Technical College, Randolph Center, VT (Nutting Hall)	Dormitory	1969	46	Brick/Block
Vermont Technical College, Randolph Center, VT (Boiler Plant/ Maintenance)	Boiler Plant	1972	43	Brick/Block
Vermont Technical College, Randolph Center, VT (President's House)	Residence	1972	43	Wood Frame
Vermont Technical College, Randolph Center, VT (Generator Building)	Garage	1976	39	Brick/Block
Vermont Technical College, Randolph Center, VT (Silo H1 Harvester)	Silo	1982	33	Steel
Vermont Technical College, Randolph Center, VT (Silo H2 Harvester)	Silo	1982	33	Steel
Blair Park, VTC Site Williston VT Williston (Campus) North	Classrooms	1986	29	Prengineered Metal
Blair Park, VTC Site Williston VT Williston (Campus) South	Classrooms	1987	28	Prengineered Metal
Blair Park, VTC Site Williston VT Williston (Campus) Easth	Classrooms	1987	28	Prengineered Metal
Blair Park, VTC Site Williston VT Williston (Campus) West	Classrooms	1988	27	Prengineered Metal

College, Location (Building Name)	Description	Year Built	Building Age	Construction
Vermont Technical College, Randolph Center, VT (Livestock Barn)	Barn	1988	27	Wood Frame
Vermont Technical College, Randolph Center, VT (Auto Tech)	Classrooms/Labs	1989	26	Metal
Vermont Technical College, Randolph Center, Vt. (44 Water Street)	Student Housing	?	25+	Wood Frame
VTC, Route 66, Randolph Center, VT (VT Tech Enterprise Ctr, Storage Shed#1)	Storage	?	25+	Wood Frame
VTC, Route 66, Randolph Center, VT (VT Tech Enterprise Ctr, Storage Shed#2)	Storage	?	25+	Wood Frame
VTC, Route 66, Randolph Center, VT (VT Tech Enterprise Ctr, Storage Shed#3)	Storage	?	25+	Wood Frame
Vermont Technical College, Norwich Farm, Norwich, Vt. (Mobile Home)	Residence	?	25+	Wood Framed
Vermont Technical College, Norwich Farm, Norwich, Vt. (Ranch Style House)	Residence	?	25+	Wood Framed
VTC, Route 66, Randolph Center, VT (VT Tech Enterprise Center, bldg #2)	Offices	1990	25	Wood Frame
Vermont Technical College, Randolph Center, VT (SHAPE/Campus Center)	Gymnasium/Pool/Campus Center	1990/2007	25	Brick/Steel
Vermont Technical College, Randolph Center, VT (Building Trades)	Garage/Lab	1993	22	Wood/Frame
Vermont Technical College, Randolph Center, VT (Maintenance Storage)	Storage Building	1993	22	Wood Frame
Vermont Technical College, Randolph Center, VT (Redstone Lease)	Diesel Program	1993	22	Prengineered Metal
Vermont Technical College, Randolph Center, VT (Hay Barn)	Barn	1994	21	Wood Frame
VTC, 72 Helena Drive, Williston, VT	Classroom/ Dorm	1997/2009/2011	18	Steel/Brick
Vermont Technical College, Norwich Farm, Norwich, Vt. (Colonial House)	Residence	1998	17	Wood Framed
VTC Nusing School at VTC Campus Randolph Center VT	Classrooms	1999	16	Brick
Vermont Technical College, Randolph Center, VT (Morrill Addition)	Classrooms	2000	15	Brick/Steel
Vermont Technical College, Randolph Center, VT (Solar Barn)	Barn	2000	15	Metal/Plastic
Vermont Technical College, Norwich Farm, Norwich, Vt. (Old Barn)	Barn	2000	15	Wood Framed
Vermont Technical College, Norwich Farm, Norwich, Vt. (Heifer Barn)	Barn	2000	15	Wood Framed
Vermont Technical College, Norwich Farm, Norwich, Vt. (Sand Shed)	Shed	2000	15	Wood Framed
Vermont Technical College, Norwich Farm, Norwich, Vt. (Dry Cow Barn)	Barn	2000	15	Wood Framed
Vermont Technical College, Norwich Farm, Norwich, Vt. (Dairy Barn)	Barn	2000	15	Wood Framed
Vermont Technical College, Norwich Farm, Norwich, Vt. (Shop)	Shop	2000	15	Wood Framed
Vermont Technical College, Randolph Center, VT (Windmill)	Wind Mill	2003	12	Metal
Vermont Technical College, Randolph Center, Vt (Burn Simulator Building)	Training Facility	2009	6	Prengineered Metal
VTECH Building - 1540 Route 66, Randolph, VT	Office Space	2010	5	Wood Frame
Vermont Technical College, Randolph Center, Vt (Digester Building)	Digester Building	2014	1	Wood Frame
Vermont Technical College, Randolph Center, Vt (Digester Tank)	Digester Tank	2014	1	Steel
Vermont Technical College, Randolph Center, Vt (Hydrolyzer Tank)	Hydrolyzer Tank	2014	1	Steel
Vermont Technical College, Randolph Center, Vt (Effluent Tank)	Effluent Tank	2014	1	Steel
VSC Chancellors Office, 575 Stonecutters Way, Montpelier, Vt	Offices (Leased Space)	2012	3	Wood Framed
VSC Baker Road 1502-1735-1750 Eden, VT	Cabin	?	25+	Wood Framed
VSC Baker Road 1502-1735-1750 Eden, VT	Cabin	?	25+	Wood Framed

CASTLETON UNIVERSITY
COMMUNITY COLLEGE OF VERMONT
JOHNSON STATE COLLEGE
LYNDON STATE COLLEGE
VERMONT TECHNICAL COLLEGE



OFFICE OF THE CHANCELLOR PO BOX 7 MONTPELIER, VT 05601 P (802) 224-3000 F (802) 224-3035

# Attachment 2: System Major Infrastructure Narrative

### **VSC Infrastructure Information**

Each of the college campuses is made up of a number of systems that perform their functions very quietly and mostly without issues. These systems provide the electricity, water, heat, waste disposal for the buildings. Most of these systems are underground, unseen and unthought-of by most students, employees and visitors to the campuses but have a real impact on all these individuals when one of the systems fail. With the exception of infrastructure installed to support new construction a majority of the systems are 25 to 50 years old and have been operating with only minor issues. These systems do not operate forever and in the event of a major failure the campuses could possibly be faced with an extended interruption of services that would affect the daily operations. We are fortunate that most system failures can be repaired without extend interruptions but this is not always the case. For example, if we experience a failure of the underground high voltage electrical system in the vicinity of the interconnection point of the local utility there would not be any feasible work around to the failure short of repairing the failure. Equipment and contractor availability will determine the length of the outage.

- 1) Campus **underground electrical systems**: (2,400 to 12,500 volts depending upon the campus) many sections of underground and equipment are 25 to as much as 40 years old. A campus electrical system is made up of underground conduit and cables, high voltage switches and transformers. The cables and cable connections are most prone to failure. Cables degrade over time and eventually short to ground causing damage to conduits and equipment in the vicinity of the failure. These electrical systems should be evaluated, sections of underground critical to the campus operations should be scheduled for replacement as needed.
- 2) The **steam distribution systems** found on our campuses are constructed of insulated steel piping and valves, all installed in concrete vaults and tunnels. A majority of these systems were installed during the early to mid-80's because of premature failures of the original systems. These networks of piping move steam from the heating plants to the building where in most cases it is used to make hot water that is circulated around the building for heat purposes. The environmental conditions in which these streamlines exist is less than ideal for promoting longevity. A portion of the year the tunnels are excessively hot and possibly moist and during the times when the system has been shut down they subject to the moist air from ground water infiltration into the tunnels, thus causing corrosion both in and outside of the piping. The planned replacement of these systems should be part of the VSC long range plans.
- 3) Campus water and sewer mains were installed during the late 60's and 70'sand 45-50 years old. With the exception of new lines installed as part of new construction the majority of the water mains were installed using ductile iron pipe and transite piping. Much of the older drainage lines are transite piping. A typical waterline system consists of piping and underground shutoff valves and a sewer system consist of piping and manholes. The interior of ductile piping in both systems, will over time either corrode or wear through from the movement of liquids and solids moving along the bottom of the pipe. The underground shutoff valves and the exterior of the piping will also corrode from being in contact with the corrosive elements found in ground water. The transite piping will typically fail due to ground movement which causes the pipe to break or collapse. Both systems should be evaluated, a replacement scheduled developed with priority given to the sections critical to the operation of the campuses.
- 4) Our college campuses have a number of **other systems** such as communications, site lighting, stormwater, all very important but not as critical to the operations as the ones listed above. We all understand that funds are limited and investments in updating buildings is very important to attract students but planned replacement of our campus infrastructure needs to be part of the VSC long range planning.

CASTLETON UNIVERSITY
COMMUNITY COLLEGE OF VERMONT
JOHNSON STATE COLLEGE
LYNDON STATE COLLEGE
VERMONT TECHNICAL COLLEGE



OFFICE OF THE CHANCELLOR PO BOX 7 MONTPELIER, VT 05601 P (802) 224-3000 F (802) 224-3035

# Attachment 3: FY2018 Capital Bill Request, with Narrative

# VERMONT STATE COLLEGES FY 2018 CAPITAL APPROPRIATION REQUEST SUMMARY OF ALL PROJECTS

10/19/2016

	Deferred Maintenance Projects Proposed		VSC Request
VSC VSC	Emergency Maintenance (Recurrent Need) Roof Repair and Replacement (Recurrent Need)	\$ \$	200,000 300,000
CCV	Academic Facility Improvements	\$	250,000
CU CU CU CU CU CU	ADA Compliance Improvements Sidewalk/Roadway Replacement Coolidge Library Lighting Upgrade Science Window Replacement Campus Flooring Replacement Stafford A/C Phase I Campus Walkway Reconstruction	\$ \$ \$ \$ \$ \$ \$ \$ \$	75,000 350,000 40,000 75,000 150,000 122,500
TSC	Campus Safety Projects Campus Security Surveillance System Building Backflow Preventers Dewey Window Replacement Dibden Dressing Room Renovation LLC Window Replacement McClelland Fasica Repair Campus Energy Conservation	\$ \$ \$ \$ \$ \$ \$ \$	25,000 75,000 30,000 200,000 100,000 85,000 25,000 37,500
LSC LSC LSC LSC LSC LSC LSC LSC LSC LSC	Shape Pool Dehumidification Equipment Phase II Alumni House Roof & Paint Campus Acoustical Ceiling Upgrades Activities Window Replacement Phase II Boiler Burner Retrofits Phase I Campus Ductwork Cleaning Phase I Campus Exterior Door Replacements Library Roof Replacement McGoff House Window Replacement Vail Window Replacement Campus Stormwater Improvements	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	70,000 37,000 50,000 50,000 30,000 44,000 20,000 100,000 36,500 190,000 185,000
VTC VTC VTC VTC VTC VTC VTC VTC VTC	Randolph Site Light Upgrade Phase IV Norwich Farm - Ext Paint & Repair SHAPE Pool Flooring Repair Phase II Judd Hall Roof Replacement Conant Classroom Upgrades Williston Bld 200 Roof Window Replacement Project Hartness Roof Replacement Road & Walkway Repairs  Total Deferred Maintenance Projects	\$	75,000 31,000 71,000 92,000 35,000 130,000 178,000 86,000 114,500
VSC	System-Wide Business Process Standardization and new Enterprise Resource Planning (ERP) System	\$	3,000,000
	Total Projects	\$	7,000,000

# VERMONT STATE COLLEGES FY 2018 CAPITAL APPROPRATION REQUEST - STATE FUNDED PROJECTS -

#### **Community College of Vermont**

Academic Facility Site Improvements: \$250,000 CCV owns or leases twelve academic facilities. Therefore the burden for interior maintenance and improvement falls within CCV's responsibilities, either through lease agreements or ownership. Significant increases for contract work necessitate an increase in requested funds. Examples of candidate projects for FY17 site improvement funds are:

- Adaptation of facilities for new and revised programmatic offerings.
- Adaptation and expansion of facilities, and equipment for changes in enrollment.
- Addressing workplace safety and accessibility issues.
- Continued fit-out of site-based science and art rooms, computer labs, libraries, and other nonstandard classroom facilities.
- Replacement/upgrade of building support systems (HVAC, EMS, etc)

#### **Castleton University**

<u>ADA Compliance Improvements Project \$75,000</u> The Castleton Disability and Access committee has evaluated the campus and has created a list of projects and improvements to help us comply with ADA requirements and to better serve students and the campus community. This project would fund campus wide improvements such as door openers, signage and cross walk identification.

Sidewalk / Roadway Replacement Project: \$350,000 Replacement of failing sidewalks and roadways around campus has been an ongoing project. The main loop through campus has substantial potholes and cracking which allow moisture to penetrate the base material, causing frost heaving. Repairs have been made, however there needs to be a more long-term solution. There are also several sidewalks on campus that need to be replaced and brought up to current standards. Funding of this project would allow Castleton to continue with replacing failing sidewalks, resurfacing parking lots and roadways around campus.

Coolidge Library Lighting Upgrade Project: \$40,000 The Library lighting system utilizes over 900 fluorescent bulbs. A number of years ago the lighting fixtures were upgraded to T-8 tubes and ballast. Since the last upgrade, lighting systems have evolved and we now have LED lighting technology. In the never ending quest for energy savings, it makes sense to convert to a LED lighting system which will yield significant energy savings.

Science Window Replacement Project: \$75,000 The Science Building was constructed in 1969 and still has the original windows. These window units are aluminum frames with single pane glass that are not thermally broken and are difficult to operate. These single pane non- thermally broken units allow the cold and heat to infiltrate the building during the winter and summer months. New energy efficient replacement windows would reduce heating and cooling costs by eliminating air infiltration.

<u>Campus Flooring Replacement Project: \$150,000</u> There are numerous areas on campus where the carpet or tile needs to be replaced due to wear and tear. Funding of this project would allow Castleton to replace the carpet in the Stafford Academic Center hallways and offices, Herrick Auditorium, Fine Arts Center and Woodruff Hall.

Stafford A/C Project Phase I: \$122,500 When Stafford was remodeled in 1998, air conditioning was removed from the project, with exception of the computer labs and Herrick Auditorium. Stafford Academic Center houses the Nursing program and the Center for Schools and is extensively used during the summer months. It is proposed that cooling coils be added to the HVAC roof top unit to provide the necessary cooling for the classrooms and offices.

#### **Johnson State College**

<u>Campus Walkway Reconstruction Project: \$235,000</u> The campus walkways throughout the campus are in a deteriorated condition and are in need of replacement. The A&E for this project has been completed and the construction documents are ready to be released for bidding. The reconstruction will involve the complete removal of the existing walkway and the complete reconstructed the walkway base and walking surface. This approach will remove all conditions that could lead to premature failure of the walkways and insure a long useful life.

<u>Campus Safety Projects: \$25,000</u> This project would fund a number of small safety related projects across the campus. A few examples of these types of projects would be the repairs of small sections of walkways, building entry repairs, mold or asbestos issues, and emergency repair to site lighting.

<u>Campus Security Surveillance System project: \$75,000</u> Over the years JSC has installed 3 completely different video surveillance systems that do not communicate with each other. As a result of the non-communication issue, it is very cumbersome for Campus Security to review and follow up on incidences. It is proposed that a new centralized system be installed, one that will integrate as much of the existing hardware as possible including expanded coverage. This will allow Public Safety to retrieve data and monitor the campus more efficiently.

**Building Backflow Protection Project: \$30,000** There are 5 buildings on campus that do not have back flow protection and pressure regulators. Building backflow protection insures that contaminants cannot be siphoned from a contaminated source back into the public water supply. This project would fund the required water line reconfigurations and the installation of the backflow preventers.

<u>Dewey Window Replacement Project: \$200,000</u> Dewey Hall was constructed in 1964 and still have the original windows. These window units are single pane glass with aluminum frames that are not thermally broken, thus allowing the cold and heat to infiltrate the building during the winter and summer months. Funding of this project would allow us to release the construction documents create in the A&E project to install energy efficient windows units that would eliminate air infiltration thus reduce draft and conserve energy and reduce heating and cooling costs.

<u>Dibden Dressing Room Renovation Project: \$100,000</u> The Dibden Theater was constructed in 1970. The dressing rooms and the associated restrooms have never been updated, the finishes and fixtures are worn and showing their age. This project would allow us to upgrade the finishes, replace the fixtures and improve the lighting. These improvements will greatly improve the appearance of the space.

<u>LLC Window Replacement project: \$85,000</u> The LLC building was built in 1996 and we now have a situation where the windows have been losing their thermal seals thus decreasing their energy efficiency.

A number of units have been replaced over the years but at this time we have approximately 70 windows that require replacing. Replacement of these failed windows will help JSC's efforts to reduce campus energy costs.

McClelland Fasica Repair project: \$25,000 The McClelland Fascia is in need of repairs due to its exposure to the elements. This Fascia is not protected by the roof, it is attached directly to the building exterior and is totally exposed to the elements. This project would fund the repair or replacement of the fascia as needed.

<u>Campus Electrical Energy Upgrades Project: \$37,500</u> Many of the campus building systems are original and by today's standards do not operate efficiently. This project would enable us to start updating these systems by installing energy efficient equipment that work reduce energy consumption, improve reliability and reduce maintenance repair costs.

#### **Lyndon State College**

Shape Pool Dehumidification Equipment Project Phase II: \$70,000 The SHAPE pool dehumidification and water heating systems are original equipment installed in 1990. These units have reached the end of their useful lives. Project funding for Phase I was received last year and now we are requesting funding for the second phase, which will allow us to complete the project. This funding will allow us to replace these units with energy efficient equipment, thus reducing operating and maintenance costs.

Alumni House Roof & Paint Project: \$37,000 The roofing and exterior of the Alumni House are in need of repairs. The asphalt roofing shingles are 19 years old, very close to the end of their design life. In a number of areas the shingles are starting to show signs of disintegration. The building exterior is also in need of repainting and minor trim repair. In a number of locations, paint is peeling and exposing the wood which will lead to further deterioration of the trim.

<u>Campus Acoustical Ceiling Upgrades Phase I Project: \$65,000</u> There are numerous areas on campus where the ceilings are very poor condition and have become unsightly. Many of the ceiling tiles are water stained, dingy in appearance and have sagged. This project would fund the replacement of the tiles starting with the worst areas.

Activities Window Replacement Project Phase II: \$50,000 The windows located in the Activities Building are the original wood framed thermopane units. Over the years the seals in these thermopane units have failed and thus causing them to collect moisture, and become unsightly. The scope of work for this project is to replace the existing windows and frames with energy efficient units thus improving the appearance and conserving energy. Funding was received for Phase I, funding for this phase would complete the project.

<u>Boiler Burner Retrofit Project Phase I: \$30,000</u> a number of the campus boilers have a tendency to over fuel the boilers thus making it difficult to maintain these units at their peak efficiency. This project would retrofit the existing burners with the latest technology in fuel metering and combustion controllers.

<u>Campus Ductwork Cleaning Project Phase I: \$44,000</u> Ductwork in all the HVAC systems are in need of cleaning. These ducts have collected over the years a significant amount of dust and dirt and when disturbed, these contaminants are distributed throughout buildings. These dirty ducts are also known to cause air quality issues if not cleaned periodically. This project will be the first of a number of future projects for HVAC systems duct cleaning.

<u>Campus Exterior Door Replacement Project: \$20,000</u> A number of the exterior doors on building across campus are in need of replacement. The existing doors and hardware are worn, and do not function properly thus requiring a significant amount of maintenance. Replacement of these units with energy efficient models and having them operating correctly will also yield some energy saving for the college.

<u>Library Roof Replacement Project: \$100,000</u> This building was constructed in 1997 and is now 19 years old. This EDPM membrane ballasted roofing has recently started having roof leaks on a regular bases. It is recommended that we replace the roofing on this building within the next 1-2 years.

McGoff House Window Replacement Project; \$32,000 The McGoff Hill House is approximately 150 years old and is believed to still have the original windows. These units are drafty, do not have storm sashes and do not operate very well. There are also units that have a considerable amount rot. It is proposed that the existing units be replaced with new energy efficient models that reasonably replicate the originals.

<u>Vail Window Replacement Project Phase II: \$190,000</u> The Vail Center was constructed in the mid 70's and still has the original windows. These window units are single pane glass with aluminum frames and are not thermally broken. These single pane non- thermally broken units allow the cold and heat to infiltrate the building during the winter and summer months. New energy efficient replacement window would reduce heating and cooling costs by eliminating air infiltration.

<u>Campus Stormwater Improvements Project: \$185,000</u> Recently LSC contracted with Krebs and Lansing Consulting Engineers to create a Campus Stormwater Management Plan. This plan identified a number of areas on campus which would benefit from improvements in Stormwater management. This project would fund improvements in the following areas:

- Add retention pond to lower discharge area below Skateboard Park.
- Tie store water drains from Harvey and Wheelock into the storm system emptying into the Rita Bole retention pond.
- Upgrade rain gardens at Stonehenge by increasing holding capacity in all areas.
- Address all swales and upper rain garden and swales along Lower Campus Drive to retention area.

#### **Vermont Technical College**

Site Lighting Improvements, Phase IV: \$75,000 The site lighting system on the Randolph Center campus is approximately 20+ years old. The funding received from prior Capital requests has enabled us to replace the existing lighting system in phases. At this time we are requesting funding for Phase IV which will bring us very close to completing the replacement project. Only 75 of the original high pressure sodium fixtures remain. In addition to replacing the lighting fixture and poles the underground electrical is also being replaced.

Norwich Farm Exterior Painting & Repair Project: \$31,000 A number of the structures at the Norwich Farm are in need of painting and minor repairs. The southern exposure of some of these structures are in need of a fresh coat of paint. A couple structures will need to have some exterior trim replaced due to equipment incidences prior to repainting. Also, the Green House which now serves as a residence for students is in dire need of repainting.

Shape Pool Tile flooring Repair Phase II Project: \$71,000 The SHAPE pool has been in operation for over 25 years. Pool environments are harsh on surrounding surfaces and mechanical systems. As a result of these harsh conditions a number of small projects are need to be funded to maintain the overall appearance and functionality of the pool. As part of the FY 17 request we completed Phase I of this project, we repaired the ceramic tile in a section of the pool deck. This year we are requesting funding for Phase II which will allow us to correct the situation where the HVAC air supply ducts located under the concrete pool deck slab is allowing sand to infiltrate into the supply ducts and being deposited on the pool deck. These ducts will be repaired and sealed to prevent this condition.

<u>Judd Hall Roof Replacement Project:</u> \$92,000 The current EDPM membrane roof on this building is 30+ years old. It was not replaced when the building underwent an interior renovation that was completed in 2009, and is close to the end of its useful life. Over the years a number of repairs have been made to this roof to extend its life, but in recent years leaks have become more commonplace. It is recommended that the roof be replaced within the next 1-2 years with a .060 EDPM membrane system.

<u>Conant Classroom Upgrade Project: \$35,000</u> The finishes in the Conant classrooms are dated and are in need of being upgraded. This project would fund the replacement of the ceiling tile, the installation of new flooring, new energy efficient lighting and the repainting of these spaces.

Williston Building 200 Roof Replacement Project: \$130,000 The EDPM membrane roof on this building is 28 years old. It was not replaced when the building underwent an interior renovation approximately 7 years ago, and has reached the end of its useful life. Leaks have become more commonplace and, as this building houses a newly renovated interior, it is recommended that the roof be replaced within the next 1-2 years with a .060 EDPM membrane system.

<u>Window Replacement Project: \$178,000</u> Administration Building: We would like to replace the two storefront windows located on the north and south entries of this building. These windows were installed as part of the general building renovation in 1986. However, the metal support frame is deteriorating because of the use of salt, which in turn is then oxidizing (deteriorating) the aluminum window frames.

Conant: We would like to replace the existing original (1964) single pane hopper windows in this building. The storefront windows and entry doors have been replaced, are in good shape, hence they are not included in this project. There are 36 total windows in this building, and we to replace these windows with a more energy efficient Dual Pane/Low E model. We would also like to include new window treatment as well.

Morrill/Morrill Annex: We would like to replace the existing original (1964) single pane hopper windows in these buildings, as well as several original wood doors. There are 26 windows in Morrill, 18 doors in Morrill Annex, as well as two storefront and 6 exterior doors that we would like to replace. All windows will be replaced with a double pane Low E model. Doors will be replaced with energy efficient models as well.

Hartness Roof Replacement Project: \$86,000 The current EDPM Membrane roof on this building is 20+ years old and is reaching the end of its expected life. This roof has been repaired numerous times. The lack of funding prevented us from replacing this roof when the building underwent a complete interior renovation in 2012. It is proposed that the roof be replaced with a new .060 EDPM fully adhered roofing system.

**Road & Walkway Repair Project: \$114,500** Sections of the Campus roadways are developing pot holes and cracks which allow moisture to penetrate the base material thus causing frost heaving. These areas will be shimmed and repaved to prevent further deterioration. We also have sections of walkways that have

deteriorated due to salt damage and harsh winter conditions, these areas will be evaluated and be replaced or repaired as needed.

#### **System-Wide**

#### **Emergency Maintenance:** \$200,000

As in previous years, this is annual funding to provide the college system with a contingency that will be used to fund unplanned needs that inevitably arise across VSC's more than 100 buildings (approximately 1,7000,000 sq ft) and over 1,400 acres of property, which combined have a replacement value approaching \$250,000,000.

**Roof Repair and Replacement: \$300,000** To address the most serious roofing concerns as assessed from annual review of all structures throughout the college system.

<u>Enterprise Resource Planning (ERP) Software Replacement: \$3,000,000</u> To standardize systemwide business processes and replace existing Enterprise Resource Planning (ERP) system, whether as a single instance of Colleague or a new software program.

The System is looking to move toward a cloud-centric approach to application hosting and delivery. The overall goal is a total solution that is seamless and operates as a secure, single solution with the ability to configure the software appropriately to meet each of the college's needs. The current system is impeding the system's ability to meet future educational initiatives in a cost effective manner. The new system will increase security, be stable and scalable, with robust features and functionality. It will provide an intuitive and efficient user experience for all constituent groups. It will be accessible via any device and responsively designed. It will include flexible, web-accessible reporting, executive leadership dashboards and decision support capabilities. It will be user-friendly, easy to administer. It will allow the VSCS to improve support and meet the needs of online learning. In short, this investment by the State will be transformative in the VSCS' efforts to deliver a quality educational experience to Vermonters continuing on to college.

CASTLETON UNIVERSITY
COMMUNITY COLLEGE OF VERMONT
JOHNSON STATE COLLEGE
LYNDON STATE COLLEGE
VERMONT TECHNICAL COLLEGE



OFFICE OF THE CHANCELLOR PO BOX 7 MONTPELIER, VT 05601 P (802) 224-3000 F (802) 224-3035

# Attachment 4: Full List of System Deferred Maintenance

			Į.	COUSE	eu 6/10/2010
Community College of Vermont					
	St Albans HVAC Equipment Replacement	\$	150,000		
	Leashold Invrovements	\$	450,000 600,000	¢	600,000
		Φ	600,000	Ą	600,000
Castleton University					
ADAMS HALL	REPLACE STAIR TREADS	\$	5,000		
	RETUBE #3 BOILER	\$	15,000		
	REPLACE PNEUMATIC AIR COMPRESSOR	\$	4,000		
	REINSULATE BOILER ROOM CEILING	\$	20,000		
	REPLACE DOMESTIC SUPPLY AND WASTE LINES Replace Entry Steps	\$ \$	300,000 15,000		
AUDET HOUSE	REPLACE CEMENT BOARD TRIM AT COLUMNS AND FRO	ONTT\$	2,000		
BABCOCK HALL	FIX EXHAUST FANS NOT WORKING (4)	\$	3,000		
	CLEAN DUCTS	\$	5,000		
	REPAIR ROTTEN EYEBROW ROOFS	\$	28,000		
	CLEAN COILS FOR MAKEUP AIR	\$	2,000		
	REPLACE STAIR TREADS	\$	5,000		
	REPLACE CARPET HALLWAYS	\$	12,000		
	EPOXY BATHROOM FLOORS	\$	85,000		
CALVIN COOLIDGE LIBRARY	REPLACE BATHROOM DIVIDERS	\$	4,000		
	REPLACE T-12 LIGHTING	\$	20,000		
	REZONE HEAT MEDIA ROOM	\$	5,000		
	REZONE HEAT SECOND FLOOR	\$	8,000		
CAMPUS CENTER	FILTER CHANGE	\$	1,500		
	TEST AND ADJUST LOOP ANTI FREEZE	\$	3,000		
CASTLETON HALL	INTERIOR FILTER CHANGES	\$	1,500		
	EPOXY BATHROOM FLOORS	\$	75,000		
	DUCT CLEANING	\$	4,000		
	REPLACE 3RD FLOOR DOORS	\$	2,000		
ELLIS HALL	DOMESTIC WASTE LINES NEED TO BE REPLACED (ROT	TEN) \$	285,000		
	EPOXY BATHROOM FLOORS	\$	50,000		
Facilities Barn	Reset Perimiter Fences Posts	\$	3,000		
	REPAIR GUTTER NORTH SIDE	\$	500		
FINE ARTS CENTER	FINISH ROOF REPLACEMENT	\$	310,000		
	SMOKE HATCH REPLACEMENT (ROTTEN)	\$	8,000		
	REPAIR FOUNDATION @ S. ELEVATOR	\$	15,000		
	REPLACE FAILED PNEUMATIC VALVES	\$	5,000		
	REPLACE THEATER HOUSE LIGHTS	\$	15,000		
GRAY HOUSE	ROOF REPLACEMENT	\$	9,750		
HASKELL HALL	CLEAN DUCT WORK	\$	4,000		
	REPLACE STAIR TREADS	\$	5,000		
	ELEVATOR POWER HEAD REPLACEMENT	\$	15,000		
	REPLACE DOMESTIC SUPPLY AND WASTE LINES Replace Entry Steps	\$ \$	300,000 15,000		
HOPE HOUSE/PUBLIC SAFETY	REPAIR FRONT PORCH	\$	10,000		
	REPAIR PATIO	\$	4,000		
	REPLACE ROOFING (Addition)	\$	6,500		
HOFF HALL	EPOXY BATHROOM FLOORS	\$	74,000		
	INTERIOR FILTER CHANGE	\$	1,500		
	REPLACE FREEZ STAT ON RTU 1&2	\$	500		

HUDEN DINING HALL	COOLER AND FREEZER SERVICE COILS FIND AIR LEAK FOR BUILDING SYSTEM REPLACE MISSING PIPE INSULATION FIX BAD UNDERGROUND WIRE FOR WALKWAY LIGHTS	\$ \$ \$	2,000 1,000 5,000 2,000
JEFFORDS CENTER	REPLACE MISSING CEILING TILES (INTERLOCKING GRID SYS	\$	7,000
	INSTALL OCCUPANCY SENSORS	\$	2,000
	FIX HEATING IMBALANCE	\$	10,000
LEAVENWORTH HALL	REPLACE BROKEN ROOM DIVIDER	\$	10,000
	REPLACE WORN CARPET	\$	50,000
COFFEE COTTAGE	REPLACE FRONT RAMP	\$	3,000
MORRILL HALL	CLEAN DUCT WORK EPOXY BATHROOM FLOORS REPLACE DAMAGED OR MISSING CEILING TILES IMPROVE BATHROOM VENTILATION	\$ \$ \$	5,000 102,000 1,500 8,000
NORTH HOUSE	SERVICE INSIDE UNIT VENTILATORS	\$	1,500
	REPLACE ROTTEN CEMENT BOARD TRIM AT ENTRANCE	\$	2,000
OLD CHAPEL	EXTERIOR PAINT	\$	20,000
	REPLACE RAMP	\$	15,000
PRESIDENT'S HOUSE	REPLACE CARPET	\$	5,000
	ROOF REPLACEMENT	\$	19,500
REINFURT HOUSE	NEW ROOF	\$	12,000
	REPAIR ROTTEN COLUMNS AT MAIN DOOR	\$	5,000
	PATCH AND PAINT WATER DAMAGE ON CEILINGS	\$	5,000
REINFURT COTTAGE	REPAIR ROTTEN DOOR FRAME ENTRANCE	\$	2,000
	REPLACE FAILED WINDOWS	\$	7,000
SOUTH HOUSE	SERVICE ROOM FAN COIL UNITS	\$	2,000
	REPLACE ROTTEN CEMENT BOARD TRIM ENTRANCE	\$	2,000
SPARTAN ATHLETIC COMPLEX	COMPLETE AIR HANDLER SERVICE STEAM TRAP MAINTENANCE OLD SECTIONS REPLACE SHAPE GYM DOORS FIX OCCUPANCY SENSOR FOR GYM LIGHTS	\$ \$ \$	2,500 2,000 3,000 1,000
SPARTAN STADIUM	GRIND HEAVING CONCRETE	\$	2,000
	RECAULK EXPANSION JOINTS IN SLAB	\$	2,000
STAFFORD ACADEMIC CENTER	REPLACE CARPET THROUGHOUT	\$	15,000
	REPLACE DOORS HERRICK AUDITORIUM	\$	3,000
	REPLACE BAD ACTIVATOR ON REHEAT COILS	\$	2,000
WHEELER HALL	CLEAN DUCT WORK EPOXY BATHROOM FLOORS REPLACE MISSING DAMAGED CEILING TILES IMPROVE BATHROOM VENTILATION	\$ \$ \$	2,000 102,000 1,000 2,000
WOODRUFF HALL	REPLACE CARPET FIX SIDE ENTRANCES' STEPS, PAINT, ROTTEN WOOD FIX HEAT IN SEVERAL CLASSROOMS RESTROOM UPGRADES REPLACE HEAT AND DOMESTIC SUPPLY AND WASTE LINES REPLACE MEMBRANE ROOFING	\$ \$ \$ \$ \$ \$ \$	10,000 4,000 2,000 8,000 350,000 89,100
WOOLDRIDGE HOUSE	PUT IN ADDITIONAL SUB PANEL ROOF REPAIRS REPAIR MISSING OR BAD WINDOWS AND STORMS REPAIR BACK STAIRS	\$ \$ \$	1,500 10,000 10,000 2,500

Revised 8/16/2016

WRIGHT HOUSE (ADMISSIONS) PAINT HOUSE 10,000 REZONE HEAT \$ 3,000 4,000 6,000 \$ **INSULATE WALLS** REPLACE WINDOWS REPLACE ADDITION ROOF \$ 8,100 **CAMPUS GENERAL** REPAIR OR REPLACE BAD SIDEWALK 50,000 \$ START REPLACING UNDERGROUND STEAM LINES 1,000,000 START REPLACING 50 YEAR OLD BOILERS 5,000,000 \$ CAMPUS STEAM TRAP MAPPING AND MAINTENANCE 35,000 **GROUNDS** FERTILIZATION AND WEED CONTROL SPORTS FIELDS \$ 10,000 OVERSEED NORTH AND SOUTH FIELD \$ 4,000 **Castleton University Subtotal** \$ 8,824,950 \$ 8,824,950

Lyndon State College				
<u> </u>				
Wheelock Bathrooms	4 suites \$196,000 x 3	\$	600,000	
Bleachers Gymnasium	Failed safety insp.	\$	120,000	
Generator Arnold	Repairs almost equal to new	\$	36,000	
Dinning Hall Tile	Quarry tiles in cooking and dish room	\$	12,500	
Pool Dectrons	Operating life at Lifes end	\$	270,000	
Repair Dectron (alternate to above)	New compressor and wiring - units are 35 yrs old	\$	35,000	
Roofs Roofs				
Library Roof	Over 20 years old	\$	157,500	
Stonehenge Roof (6) Building	Stonehenge 15 + years old	\$	110,000	
Activities Roof	16 years old	\$	250,000	
Wheelock Roof	25 years old	\$	61,880	
Alumni House Roof	Near lifes end	\$	32,000	
Stonehenge Entrance roofs	32 years old	\$	18,600	
•	•			
A/C in DATA Closets	Needs to be equipment specific	\$	12,000	
Control Upgrades	Gym air handler run wild - occupancy controls	\$	30,000	
Ceiling Upgrades	Campus wide acoustical ceilings outdated :			
Ceiling Upgrades	Theater Lobby w/ new lighting	\$	25,000	
Ceiling Upgrades	Vail 4th floor w/ lighting	\$	22,000	
Ceiling Upgrades	Science wing corridor	\$	23,000	
Ceiling Upgrades	Shape corridor	\$	7,000	
Ceiling Upgrades	Activities EJA corridor	\$ \$ \$	13,150	
Ceiling Upgrades	Dinning Room East room	\$	29,000	
Theater Lobby	New ceilings and Lighting	Š	25,000	
Gas Pumps Maintenance	Controls and Pumps	\$	20,000	
·	·			
Residence Hall Painting		_		
Interor Painting	Wheelock 60,000 sq '	\$	87,300	
Interor Painting	Stonehenge 6 buildings \$56000 ea.	\$	336,000	
Alumni House Paint	Exterior of hose needs paint	\$	4,500	
McGoff Hill house	Window replacement	\$	32,000	
Brown House Sprinklers	Water line required	\$	79,000	
Brown House structure	Foundation cracks and deck footers	Š	8,000	
Windows Activities Building	Need replacement due to deteriation	\$	322,000	
Vail stair tread / risers	Worn out	\$	20,000	
Vail window replacement	Old and not efficient	\$	190,000	
SHAPE foam and EFIS @ Foundation	Destroyed	\$	15,500	
Rita Bole Window sills	All need refinishing	\$	9,500	
Heat enclosures Stonehenge	rough Shape throughout	\$	180,000	
Stonehenge Rubber Stair threads	Needed throughout	\$	93,000	
S .		э \$	685,000	
Stonehenge Doors	Rough throughout	φ	000,000	
Pond Dredging Dragon Pond	Silted in and over vegetated drain & dredge	\$	35,000	
Veterens small fountain	new liner due to leak	\$	30,000	
Added landscapping pond area	With fountain work	\$	10,000	
Wheelock:				

Revised 8/16/2016

Electrical	Replace switch gear and panels	\$	130,000
Fire Alarm	New fire alarms needed - Life Safety	\$	84,000
Storm Water Issues:	On the second state of the Conference of the Con	•	45.000
Rebuild catch basins Clean and flush catch Basins	Campus wide see list in facilities assessment 28 campus wide	\$ \$ \$ \$ \$ \$ \$ \$	15,000 10,500
Storm water tie ins to pond	Harvey roofs in storm system pipe to pond	Φ \$	35,000
Add more retention below Skate	Continued wash outs below park- add pond	\$	50,000
Swale below Wheelock	Clean & reshape add stone check dams	\$	8,000
Repair Granite curbs Rita Bole	Need to keep water headed to Storm drain	\$	2,500
Storm Water Issues:	Repairs and Upgrades per Engineer's report Master Plan	\$	85,000
Fire Sefets			
Fire Safety Vail	Install Sprinklers	\$	260,000
Maintenance	Install Sprinklers	\$	60,000
Stonehenge (6) Buildings	New Fire alarm system	\$	180,000
3 ( )	,		,
Paving parking lots & walkways:	Wheelock w/ infrastructure	\$	222,000
Paving parking lots & walkways:	Vail faculty	\$ \$ \$	50,000
Paving parking lots & walkways:	Walks & rear drive Shape to Rotundra		25,000
Paving parking lots & walkways:	Maintenance & Brown House	\$	201,000
Campus wide due to age & inefficiences			
Retrofit Burners & Combustion Fans	Boiler efficiency increased greatly 3.5 yr. pay back	\$	180,000
Circulating pumps to varible speed	Varible speed controls payback 5 yrs	\$ \$ \$	176,100
Alexander Twilight Theater	Install a HVAC system w/ energy recovery	\$	420,000
Vail lower level	Install a HVAC system w/ energy recovery	\$	78,000
Dining Hall	Add more make up Air	\$	10,000
<u>Architectual</u>			
Windows Activities	Single glazed and deterioriating	\$	300,000
Hand rails non compliant	Redo area at Activities Mezzanine	\$	23,000
ADA Bathroom in EJA area	Make Compliant	\$	40,000
Carpet Campus wide Egress Door 2nd floor library	On going Budget Exterior grading included	Φ Φ	200,000 90,000
Redo ceiling Dinning hall	bad condition as well as stained	φ \$	30,000
Wheelock Railings	Railing need to be added existing not to code	\$	270,000
Doors in Stonehenge	In poor Shape interior	\$	500,000
ADA compliance Stonehenge	Per Architects assessment / 220,000/ building	\$	1,320,000
Alumni House paint	w/ lead abatement	\$	12,000
Alumni House	ADA compliance issues	***	42,000
McGoff Hill house ADA	ADA compliance issues	\$	150,000
Day Care	Rear access has 7' drop need guard rails	\$	24,000
Deiler plants			
Boiler plants: Activities			
Replace feed tank	Condensate Tank corroding (Replacement)	\$	50,000
Replace fuel pumps	Old #6 pumps to #2(requires new lines to tank)	\$	20,000
New Domestic hot water tank	Exterior corrosion and blistering on inside	\$	15,000
Boiler Control Panels	Old and some pose a Arc fault threat too full	\$ \$	15,000
Perimeter drains	Water infiltration issues	\$ \$	5,000
Piping Throuhghout	Most over 45 yeats old leaks showing		25,000
Boiler replacement (???)	Inefficient and 47 years old - Strategizng	\$	150,000
Deilara continued			
Boilers continued  Vail Boilers	Panlaga two hailars and airs numps	œ	250,000
Wheelock Boilers	Replace two boilers and circ pumps Replace heat exchanger	Φ Φ	250,000 15,000
Isolation Valves & circ pumps	Isolation Valves associated piping and circ pumps	\$	25,000
Boiler replacement	Nearly 50 years old	\$ \$ \$ \$ \$ \$ \$	320,000
Arnold Boilers	Newfuel & circulator pumps	\$	6,000
Hot water boiler	Domestic hot water boiler swing season use	\$	30,000
Boilers replaced	Nearly 50 years old		300,000
Rita Bole	New circulator Pumps (ASAP)	\$	3,500
Company and an extended to the extended	I and an antifolian about the control of	•	450 000
System automated controls  Graphics & Management	Legacy controllers obsolete very expensive to replace	\$	150,000
Graphics & Management	Energy management added & graphics added to system	\$	35,000

Plumbing code compliance

Backflow preventers campus wide Isolation Valves campus wide Underground piping upgrades Steam Piping Storm & Sewer piping replacemnet	Need to bring into compliance Large % of valves need to be replaced Piping and insulation replacement Stonehenge Piping leaks and upgrades Dinning Hall Underground piping in bad shape (Need to start phasing In)	\$ \$ \$ \$ \$ \$	30,000 500,000 40,000 100,000 300,000	
HVAC Upgrades  Make Up air Wheelock Energy recovery ventilation System Energy recovery ventilation System Library Ventilation system Vail 1st & 2nd floor Clean ductwork Campus wide	Building in a extreme negative - No Make up Air Wheelock Building has humidity problems during summer Stonehenge Building humidity problems during summer Library humidity problems - have been using dehumidifiers Lacks ventilation and a/c (15) builds at an average of \$22,000 / bldng	\$ \$ \$ \$ \$ \$	25,000 300,000 1,320,000 210,000 80,000 330,000	
Electrical Stonehenge replace power system Stonehenge fire alarm Dining Hall fire alarm system Library fire alarm Vail fire alarm Generator for Stonehenge Activities Electric distribution Preisdent's House Electric McGoff Hill Electric distribution Lighting in Stonehenge & Wheelock	Distribution system 50 years old past life needs replacing Replace w/ new addressable system Generator is in need of replacing - tie in battery emergency Distribution system 50 years old past life needs replacing Old and beyond safe life Old and beyond safe life Energy use & quality of light	***	300,000 97,000 50,000 97,000 50,000 97,000 180,000 30,000 36,000 690,000	
Building Structures Brick Repair Campus wide Exterior Painting all exterior buildings Exterior Doors	On going care of exterior bricks Grey House, Alumni House, Brown House Old and rusting Activities, Wheelock, Maint.  Lyndon State College Subtotal	\$ \$	50,000 35,000 35,000 15,726,030	\$ 15,726,030

Johnson	State	Col	leae

Site	Bentley parking lot improvements Campus Sidewalk Replacement Campus Undergrond Power Replacement Card Access and Hardware Upgrades Cross Country Trail improvement General site improvements Improve Clay Hill Entrance Install Building Back Flow Preventers & Pressure Regulators Landscape master plan/management plan Pave Parking Lot East of Gov's, Senators, Stearns, Arthurs Paver removal at Gov's Entrance and sidewalk from Parking ( Pa Site lighting improvements Replacement of AC Water piping and valves on Campus Road Siding / Swale work Roadway & parking lot repaving Safety improvements to "Y" intersection Safety To Life Projects Sidewalks along loop road Signage and way finding	***	750,000 400,000 500,000 125,000 29,000 75,000 35,000 75,000 1,000,000 50,000 1,600,000 50,000 300,000 150,000 150,000
Barn	Electrical Service / Water and limited lighting Road Grading	\$	17,500 12,000
Library & Learning Center	ADA-compliant audio-visual booth Key and Card Access System Replacement Install back flow and pressure regulator at water service entrance Carpet Replacement Landscaping Lighing systems Maintenance	\$ \$ \$ \$ \$ \$	9,500 50,000 8,500 100,000 15,000 75,000

	Modify/replace handrails for ADA	\$	6,000
	Repaint decorative sunscreen metal work	\$	25,000
	Replace drinking fountains with ADA "hi-low" fountains	\$	25,000
	Replace failed entrance sidewalk	\$	50,000
	Roof Replacement Replace windows with broken seals	\$	275,000 70,000
	Seal and waterproof the building envelope	\$ \$ \$ \$ \$	65,000
	Sump pumps/exhaust for steam pit	\$	13,500
	Upgrade interior Finishes	\$	75,000
Dibden Center for the Arts			
	Backflow preventer/water meter	\$	7,000
	Bring Stairs into Safety compliance	\$	100,000
	Emergency Lighting System Improvements Enclose lobby stairs on second floor	***	35,000 12,000
	Exterior Painting / Sealing	φ \$	45,000
	Fire-rated ADA-compliant doors	\$	118,000
	Handrails at first floor and basement	\$	25,000
	Loading dock handrail/guardrail	\$	13,000
	Paint and interior upgrades in theatre proper Perimeter heating w/DDC controls	Ф \$	75,000 202,500
	Proscenium Curtain Replacement	\$	225,000
	Renovate Dressing rooms and adjacent bathrooms	\$	75,000
	Renovate dressing/toilet rooms	\$ \$ \$	181,500
	Renovate dressing/toilet rooms for ADA Renovate gallery for 3 teaching spaces	\$	32,000 55,000
	Renovate Hall ceiling and lighting system	φ \$	112,000
	Replace AHUs and exhaust fans and controls	\$ \$ \$	150,000
	Replace air handling units/exhaust fans	\$	267,500
	Replace chiller	\$	135,000
	Replace drinking fountains for ADA Replace entry doors/sidelights for ADA	\$ \$	5,500 55,000
	Replace FA system with point ID / voice notification/ Em Exit Signal	\$	30,000
	Replace Failed Sidewalk	\$	15,000
	Replace fire alarm system	\$	101,500
	Replace incandescent lighting	\$ \$	81,000
	Replace Lower Roof Replace membrane roof		100,000 222,000
	Replace stage floor	\$ \$	785,000
	Sprinkler Entire Building	\$	115,000
	Stage floor electrical receptacles	\$	2,500
	Upgrade fluorescent lighting Upgrade House lighting	\$ \$	75,000 125,000
	opgicado Hodoo lightinig	Ψ	120,000
Carter/SHAPE	ADA-compliant signs	\$	3,500
	Exterior Landscaping	\$	15,000
	HW Distribution system upgrades	\$	75,000
	Improve Racquet Ball Ventilation	\$	45,000
	Install water softener	\$	13,500
	Lighting replacement Maintenance Locker Room Upgrades	\$ \$	10,000 200,000
	Paint Multi-Gym / Ceilings / FRP Sheetrock Walls	\$	30,000
	Repair Paver entrance	\$	50,000
	Replace AHU's	\$	75,000
	Replace corridor floor Replace drinking fountains for ADA	\$ \$	18,000 9,000
	Replace electrical panels	\$	3,000
	Replace lighting in pool	\$	13,500
	Replace membrane roof (high roof)	\$	301,500
	Upgrade heating controls to DDC Waterproof and Seal the building envelope	\$ \$	34,000 84,000
	Tato, proof and oods the building envelope	Ψ	57,000
McClelland Hall	Fire alarm System Replacement	¢	15,000
	Flooring Upgrades	\$ \$	75,000
	Renovation Bathrooms	\$	150,000
			•

Martinetti Hall

**Maintenance Building** 

Install fire-rated doors Install handrails and guards Install occupancy sensors/controls Install sump alarms linked to DDC Interior Painting Lighting upgrade Modify boiler piping Parking upgrades Remove and relocate 2nd set of stairs Renovate HC entrance Repair / replace and paint rotten Fascia Repair boiler room wall Replace entrance vestibule doors Replace water service entrance Replacement of carpeting Restore fire escape Solar Hot Water Sprinkler Installation Upgrade elevator alarm interface	***	7,000 20,500 8,000 50,000 45,000 125,000 20,000 20,000 4,000 28,500 25,000 14,000 75,000 75,000 7,000
Asbestos abatement Construct new entry to Admissions / Parking and Addition Electrical Transformer Upgrade Improve safety & appearance of west stair Install sprinkler system Install unit ventilators - 2nd/3rd classrooms Install water meter at service entrance Lighting replacement Maintenance Lighting upgrade in dorm rooms Modify generator to prevent freeze-up Ramp/accessible entrance to Admissions Renovate 2nd/3rd toilet rooms for ADA Repaint and Repair Window Brick and Sills Repair exterior brick and entrances Repair planter and Academic Deans Entrance Replace 2nd & 3rd floor lighting Replace entire heating system Replace entrance doors for ADA Replace entrance doors for ADA Replace first floor drinking fountain for ADA Replace flooring on second floor north wing Replace four single-glazed windows on first Replace hot water heating equipment Replace south elevation storefront Replace two egress doors for safety Replacement of dormitory doors Rewire 2nd & 3rd floors/devices Upgrade HVAC system ( 2nd and 3rd FL)	*****	70,000 150,000 75,000 33,000 216,000 65,000 60,000 27,000 57,500 284,000 125,000 199,800 45,000 54,000 54,000 34,000 34,000 34,000 355,000 17,000 34,000 34,000 450,000
Fire alarm system Upgrade Install accessible sidewalk to entrance Install backflow preventer Install emergency lighting Install exit signs Insulate exterior walls with EIFS Interior repainting Lighting replacement Maintenance New Doors and Windows New Salt/ Sand shed Pave the parking lot, drive, drain line Renovate hallway and toilet rooms for ADA Replace existing stair with steel Replace heating system in office and shop	***	10,000 18,500 10,000 4,000 3,000 120,500 50,000 12,000 40,000 85,000 52,000 12,000 15,000 67,500

	Rework Leech Field	\$	15,000	
	Roof over Compactors / safety	\$	35,000	
	Sprinkler Building	\$	28,000	
	Sprinkler Building	Ф	20,000	
<b>D O O I</b>		•	00.000	
Dewey Campus Center	Key System Replacement	\$	20,000	
	Exterior Painting / Sealing	\$	20,000	
	Flooring upgrades	\$	20,000	
	Lighing replacement	\$ \$	40,000	
	Interior Painting	\$	40,000	
	Re-carpet Building	\$	65,000	
	Relocate hot water pumps/piping	\$ \$ \$	4,000	
	Renovate toilet rooms for ADA	\$	110,000	
		φ		
	Replace drinking fountains for ADA	Þ	4,000	
	Replace sump pumps	\$	7,000	
	Stair and Sidewalk constuction	\$	25,000	
	Window Replacement	\$	320,000	
	Trindow Replacement	Ψ	020,000	
Dentley Hell	Dentley Cound Entenuation (207)	<b>c</b>	20.000	
Bentley Hall	Bentley Sound Entenuation (207)	\$	38,000	
	Duct System Cleaning	\$	25,000	
	New Electrical transfer switch and panel	\$	67,500	
	Perimeter heating w/DDC controls	\$	405,000	
		Φ		
	Repair Exterior brick and concrete walls	\$	375,000	
	Replace Dimmer system and lighting in 207	\$	75,000	
	Replace AHU's	\$	110,000	
	Roof Replacement	\$	165,000	
	Troof Tropiacomont	Ψ	100,000	
B 11 4 11				
Presidents House				
	Drive Repair	\$	48,000	
	Exterior Painting	\$	13,000	
	Install Fire Alarm / Security System	\$	10,000	
		Φ		
	Interior Painting	\$ \$	12,000	
	Landscaping	\$	15,000	
	Repair Foundation at Garage	\$	20,000	
	Sprinkler System	\$	10,000	
	Sphilikler System	Ψ	10,000	
_				
Governors				
	Bathroom Upgrades	\$	270,000	
	Bathroom Upgrades  Complete Sprinklering of the building	\$ \$	270,000 125,000	
	Complete Sprinklering of the building	\$	125,000	
	Complete Sprinklering of the building Electrical upgrades	\$ \$	125,000 200,000	
	Complete Sprinklering of the building	\$ \$ \$	125,000	
	Complete Sprinklering of the building Electrical upgrades	\$ \$ \$	125,000 200,000	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting	\$ \$ \$	125,000 200,000 45,000 100,000	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting	\$ \$ \$ \$ \$	125,000 200,000 45,000 100,000 150,000	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads	\$ \$ \$ \$ \$ \$	125,000 200,000 45,000 100,000 150,000 20,000	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair	\$ \$ \$ \$ \$ \$ \$	125,000 200,000 45,000 100,000 150,000	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads	\$ \$ \$ \$ \$ \$ \$ \$ \$	125,000 200,000 45,000 100,000 150,000 20,000	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks	\$ \$ \$ \$ \$ \$ \$ \$ \$	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls	***	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 75,000	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade	***	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 75,000 50,000	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade Window replacement	***	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 75,000 50,000 15,000	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade	***	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 75,000 50,000	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade Window replacement	***	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 75,000 50,000 15,000	
Stearns	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade Window replacement Membrane Roofing Replacement	***	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 75,000 50,000 15,000 172,800	
Stearns	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade Window replacement Membrane Roofing Replacement Exterior brick repair & Seal	<i><b>««»</b></i>	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 75,000 50,000 15,000 172,800	
Stearns	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade Window replacement Membrane Roofing Replacement  Exterior brick repair & Seal Domestic Hot Water System Upgrade	<i><b>«</b>»</i>	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 75,000 172,800 450,000 75,000	
Stearns	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade Window replacement Membrane Roofing Replacement  Exterior brick repair & Seal Domestic Hot Water System Upgrade Front Entrance Lighting	*****	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 75,000 50,000 15,000 172,800	
Stearns	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade Window replacement Membrane Roofing Replacement  Exterior brick repair & Seal Domestic Hot Water System Upgrade	<i><b>«</b>»</i>	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 75,000 172,800 450,000 75,000	
Stearns	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade Window replacement Membrane Roofing Replacement  Exterior brick repair & Seal Domestic Hot Water System Upgrade Front Entrance Lighting	*****	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 75,000 172,800 450,000 75,000 15,000 15,000	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade Window replacement Membrane Roofing Replacement  Exterior brick repair & Seal Domestic Hot Water System Upgrade Front Entrance Lighting	*****	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 75,000 172,800 450,000 75,000 15,000 15,000	
Stearns	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade Window replacement Membrane Roofing Replacement  Exterior brick repair & Seal Domestic Hot Water System Upgrade Front Entrance Lighting Walk In Coolers Compressor Upgrade With Back Up	****	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 75,000 15,000 172,800 450,000 75,000 15,000 50,000	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade Window replacement Membrane Roofing Replacement  Exterior brick repair & Seal Domestic Hot Water System Upgrade Front Entrance Lighting Walk In Coolers Compressor Upgrade With Back Up	*****	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 75,000 15,000 172,800 450,000 75,000 15,000 60,000	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade Window replacement Membrane Roofing Replacement  Exterior brick repair & Seal Domestic Hot Water System Upgrade Front Entrance Lighting Walk In Coolers Compressor Upgrade With Back Up	**************************************	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 75,000 15,000 172,800 450,000 75,000 15,000 50,000	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade Window replacement Membrane Roofing Replacement  Exterior brick repair & Seal Domestic Hot Water System Upgrade Front Entrance Lighting Walk In Coolers Compressor Upgrade With Back Up  Asbestos removal Card Access upgrade	**************************************	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 75,000 15,000 172,800 450,000 75,000 15,000 60,000	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade Window replacement Membrane Roofing Replacement  Exterior brick repair & Seal Domestic Hot Water System Upgrade Front Entrance Lighting Walk In Coolers Compressor Upgrade With Back Up  Asbestos removal Card Access upgrade Building Sprinkler System	**************************************	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 75,000 172,800 450,000 75,000 15,000 60,000 50,000 150,000	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade Window replacement Membrane Roofing Replacement  Exterior brick repair & Seal Domestic Hot Water System Upgrade Front Entrance Lighting Walk In Coolers Compressor Upgrade With Back Up  Asbestos removal Card Access upgrade Building Sprinkler System Domestic Hot Water System Upgrades	<i><b>««»</b> «»»</i> «»» «»» «»» «»» «» «» «» «» «» «» «» «»	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 75,000 172,800 450,000 75,000 15,000 60,000 60,000 60,000 60,000	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade Window replacement Membrane Roofing Replacement  Exterior brick repair & Seal Domestic Hot Water System Upgrade Front Entrance Lighting Walk In Coolers Compressor Upgrade With Back Up  Asbestos removal Card Access upgrade Building Sprinkler System Domestic Hot Water System Upgrades Interior Painting	<i><b>«</b></i>	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 75,000 172,800 450,000 75,000 15,000 60,000 50,000 150,000 60,000 75,000 75,000	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade Window replacement Membrane Roofing Replacement  Exterior brick repair & Seal Domestic Hot Water System Upgrade Front Entrance Lighting Walk In Coolers Compressor Upgrade With Back Up  Asbestos removal Card Access upgrade Building Sprinkler System Domestic Hot Water System Upgrades Interior Painting Interior Finishes Upgrades	<i><b>« « « « « « « « « « « « « « « « « « « </b></i>	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 75,000 15,000 172,800 450,000 75,000 15,000 60,000 50,000 150,000 150,000 150,000 100,000 100,000	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade Window replacement Membrane Roofing Replacement  Exterior brick repair & Seal Domestic Hot Water System Upgrade Front Entrance Lighting Walk In Coolers Compressor Upgrade With Back Up  Asbestos removal Card Access upgrade Building Sprinkler System Domestic Hot Water System Upgrades Interior Painting	<i><b>«</b></i>	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 75,000 172,800 450,000 75,000 15,000 60,000 50,000 150,000 60,000 75,000 75,000	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade Window replacement Membrane Roofing Replacement  Exterior brick repair & Seal Domestic Hot Water System Upgrade Front Entrance Lighting Walk In Coolers Compressor Upgrade With Back Up  Asbestos removal Card Access upgrade Building Sprinkler System Domestic Hot Water System Upgrades Interior Painting Interior Finishes Upgrades Lighting Upgrades	<i>。</i>	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 75,000 172,800 450,000 75,000 15,000 50,000 60,000 50,000 150,000	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade Window replacement Membrane Roofing Replacement  Exterior brick repair & Seal Domestic Hot Water System Upgrade Front Entrance Lighting Walk In Coolers Compressor Upgrade With Back Up  Asbestos removal Card Access upgrade Building Sprinkler System Domestic Hot Water System Upgrades Interior Painting Interior Finishes Upgrades Lighting Upgrades Stair Tread Replacement	<i><b>« « « « « « « « « « « « « « « « « « « </b></i>	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 50,000 172,800 450,000 75,000 15,000 50,000 60,000 50,000 150,000 150,000 150,000 150,000 150,000 150,000 150,000 20,000 135,000 20,000	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade Window replacement Membrane Roofing Replacement  Exterior brick repair & Seal Domestic Hot Water System Upgrade Front Entrance Lighting Walk In Coolers Compressor Upgrade With Back Up  Asbestos removal Card Access upgrade Building Sprinkler System Domestic Hot Water System Upgrades Interior Painting Interior Finishes Upgrades Lighting Upgrades Stair Tread Replacement Repair decks	<i><b>««»</b> «»»</i> «» «» «» «» «» «» «» «» «» «» «» «» «»	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 50,000 172,800 450,000 75,000 15,000 50,000 60,000 50,000 150	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade Window replacement Membrane Roofing Replacement  Exterior brick repair & Seal Domestic Hot Water System Upgrade Front Entrance Lighting Walk In Coolers Compressor Upgrade With Back Up  Asbestos removal Card Access upgrade Building Sprinkler System Domestic Hot Water System Upgrades Interior Painting Interior Finishes Upgrades Lighting Upgrades Stair Tread Replacement Repair decks Renovate Counseling Ctr and Health Center Bathrooms	<i><b>««»</b> «»»</i> «» «» «» «» «» «» «» «» «» «» «» «» «»	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 50,000 172,800 450,000 75,000 15,000 15,000 150,000 60,000 50,000 150,000	
	Complete Sprinklering of the building Electrical upgrades Fire Alarm upgrade Interior Painting Lighting New Stair Treads Remove Broken Pavers and Road Repair Repair decks Repair foundation and retaining walls Card Access upgrade Window replacement Membrane Roofing Replacement  Exterior brick repair & Seal Domestic Hot Water System Upgrade Front Entrance Lighting Walk In Coolers Compressor Upgrade With Back Up  Asbestos removal Card Access upgrade Building Sprinkler System Domestic Hot Water System Upgrades Interior Painting Interior Finishes Upgrades Lighting Upgrades Stair Tread Replacement Repair decks	<i><b>««»</b> «»»</i> «» «» «» «» «» «» «» «» «» «» «» «» «»	125,000 200,000 45,000 100,000 150,000 20,000 100,000 40,000 50,000 172,800 450,000 75,000 15,000 50,000 60,000 50,000 150	

	Fire alarm system Upgrade	\$	35,000	
VAC	Exterior Wood Finish / replacement Grounds Work / Drainage / Landscaping	\$	20,000 35,000	
College Apartments	Construct Parking Lots / Drive / Sidewalk Electrical system upgrade Entrance Lock Replacement (Electronic) Flooring upgrades Heating System conversions Kitchen Upgrades Lighing replacement Maintenance Sprinkle all apartments Roofing Replacement (2 Units)	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$	200,000 175,000 40,000 143,000 172,000 150,000 30,000 150,000 23,400	
Arthur Hall	ADA Compliance Hardware Door replacement Elevator/Replacement Flooring upgrade Front Door Replacement Heating Control upgrades 2nd 3rd, Heating system replacement Improve boiler room safety Interior painting Interior Upgrades Laundry room upgrades Loading Dock Repair / Stair Railing replacement Replace #1 & #2 boilers Replace chemical room ventilation system Replace Window walls windows Membrane Roof Replacement	****	25,000 22,000 300,000 13,000 15,000 500,000 25,000 30,000 45,000 45,000 25,000 472,000 20,500 75,000 54,900	
	Lyndon State Subtotal	\$	23,717,700	\$ 23,717,700
Vermont Technical College  Campus Infrastructure	Campus South Water Installation	\$	250,000	
	Center Campus Waterline Replacement Parking Lot Repairs and Repaving Power House Steamline Replacement Sewer Pump Station Replacement Underground Power Repairs and Replacement Walkway Repairs and Replacement Campus Steamline Repairs	\$ \$ \$ \$ \$ \$	400,000 450,000 75,000 175,000 600,000 82,000 425,000	
Maintenance Building / Central Heating	Plant Ramp and Stair Repairs Heating Plant Repairs and Equipment Replacement	\$	12,000 850,000	
Trades Building (Old Auto Tech)	Roof Replacement Exterior STO Repairs Entry Porch Roof	\$ \$ \$	150,000 50,000 2,700	
Conant	Conant 102 (PIT) Renovation Conant Window Replacement Conant Roof Replacement	\$ \$ \$	27,500 165,000 81,000	

	System-Wide Deferred Maintenance Total	Ψ	0,004,000	\$ 58,463,030
-	Vermont Tech Subtotal	\$	9,594,350	\$ 9,594,350
Williston Building 5667 Williston Building 5689	Roof Replacement Roof Replacement	\$ \$	9,750 9,750	
Williston Building 200	Roof Replacement	\$	148,500	
VTEC (Lower Building)	Roof Replacement	\$	45,500	
	Barn infrastructure Repairs	\$	150,000	
	Farmstead Storage Barn Roof Replacement Building Repairs and Paint	\$ \$	50,000 85,000	
Farmstead				
Οπα <b>ρ</b> σ	Pool Gutter Replacement	\$	35,000	
Shape				
Old Dorm	Porch Roof Replacement East Wing Roof Replacement	\$ \$	2,700 22,500	
	Elecrical System Upgrades	\$	250,000	
Keenan	Plumbing infrastructure Replacement	\$	300,000	
	Nutting Electrical Upgrade	\$	350,000	
	Nutting Windows Replacement	\$	225,000	
	Nutting Plumbing Upgrade Nutting Restroom Renovations	\$ \$	500,000 350,000	
Nutting	Nutting Mechanical Upgrade	\$	450,000	
Norwich Farm (Green House)	Roof Replacement	\$	16,250	
	Morrill Window Replacement	\$	225,000	
Morrill	Morey Electrical System Upgrade			
	Morey Flectrical System Ungrade	\$ \$	180,000 350,000	
	Morey Kitchen Renovation	\$ \$	600,000	
	Morey Entry Door Replacement Morey Kitchen HVAC Replacement	\$ \$	25,500 400,000	
Morey				
<del>-</del>	Judd Hall Roof Replacement	\$	144,000	
Judd		Ť	,	
Hartness	Roof Replacement	\$	136,500	
	Green Hall Retaining Wall Replacement Green Hall Lower Roof Replacement	\$ \$	110,000 18,200	
	Green Hall Window Replacement	\$ \$ \$	145,000	
	Green Hall Recaulking Green Hall Roof Replacement	\$	30,000 160,000	
	Green Hall Floor & Ceiling Replacement	\$ \$	100,000	
Green Hall	Green Hall a/c unit replacement	\$	175,000	
G. 55.1. 1 tall	Green Hall a/c unit replacement	¢	175 000	