




**Waterbury Dam Spillway Replacement, Risk Assessment, \$215k from previous years. The approach channel in need of a new boat barrier can be seen.**



**Waterbury Dam Gatehouse. The UST to be removed can be seen. A security and surveillance system for the dam and gatehouse are needed.**



**Waterbury Dam Spillway, the access ladders requiring a fall protection system can be seen.**



**Waterbury Dam Seepage Collection System**



**Wrightsville Dam, principal spillway intake structure and leak in spillway tunnel**



**Wrightsville Dam, aux. spillway, note overgrown and aging rock cut at left side of image**



**Miles Pond Dam, various minor repairs needed.**



**Little Hosmer Dam, assessment, design, rehabilitation construction**



**Lake Bomoseen Dam, minor repairs**